

ASS. REC. BY:

REF: CS/MSG18003008/

K903⁷²

Special Instruction:

Surveyor: Kenneth
Menimen

ASSIGNMENT (Office)

From (Person): Christina Wong

of MSIG

Date/Time: 13/2/18 @ 4:11 pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 95732

Insured: SLM 5067P

at Workshop m/s Alans United

Tel:

of BLK 7 Sin Ming Ind. Est # 01-76

Policy No: 28931732 AVW

Claim No: 519298

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A 09/02/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 9:40am @

Person Contacted: Kenny

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 95732 - X
	SLM 5067P - X
22/7/18 @	5:06pm revised to Christina Wong via Menimen.

MSIG

ASSIGNMENT

From _____ Date 23/2/18

Estimated Cost: _____

03 WS TR RES CD RES EVA INV M

To inspect vehicle No: SKS 95732

at address: Alans' United

at Blk 7, sin Ming Ind. Est #01-76

insured: _____

Policy No: _____

DATE: _____

Sum Insured: _____ Excess: _____

Claims Record: _____

Make of Van: _____

Vehicle No: SKS 95732 Reg: 03 11

Type: M Cycle Bus/ Van Light Truck Other Motor

Track: Trailer

Make: Bmw ^{A1} 523i cc: 2497

Colour: N. Black No. Insured: 1 No. Insured: 1

Sp. Resing: 177584 TP. Insured: 1 No. Insured: 1

Engine: _____

C.No: WBA1-P-320800804312

Gen. Cond: Paint Rust Burnt

Steering: Inop Jammed Leaked Burnt

Brake: Inop Jammed Leaked Burnt

Mod: NR S Rim ST ABS on

Tyre Size: F _____

R 225/55R17

BS/ DUN/ EXNOVA/ BY/ FS/ LZA/ MIO/ OHTSL/ R/R/ SUM

YOYO/ YOKO: _____

Front	Feet
R.Ba. <u>6</u> --	R.Ba. <u>7</u> --
L.Ba. <u>6</u> --	L.Ba. <u>7</u> --
D.O. <u>9/2/18</u>	D.O. <u>23/2/18</u>

Surveyed at: _____ ✓

Dist of Damages: FR REAR OS NS US ROOF COL

NS FR

The UIC / Chassis frame / Body Structure affected due to the

<input checked="" type="checkbox"/>	<input type="checkbox"/>
NS	OS
<input type="checkbox"/>	<input type="checkbox"/>

Policy Condition: _____

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value: _____

DAD Accident Report: _____ Consistent? : Yes or No

G/A - FR Seen: _____ Consistent? : Yes or No

Est. Repair: 01 days. Pass: Yes or No

Wm Sum: 1.31 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1wp}

Date _____ Person Contacted: _____

Vehicle IN / OUT

Date Time Action/ Instruction

16/2 FR parts to Cashmere

8 400 8 confirmed with Kenny. Used 6


5/3/2018

RECEIVED 05 MAR 2018

Date Time File Report: Prel. Report

Final Report

Days Of Repair: 1

Resurvey No. of Trip: 1

Surf Fee: 200

Transportation: 10

Other Fee: _____

Record Former: MER-PP

Surf Fee: 400

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003008/Kqd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 14-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 5067P	Veh. Inspected	SKS 9573Z
Policy No.	28931732AWW	Coverage (\$)	0.00
Claim No.	549298	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	14/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/02/2018	Inspection Date	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. : Cy/MSK/18003008/KQ/3
 Policy Type: OD / TP / TP RES / TL / EVA

SKS 95732

Case Handler

Typist

Admin (Nirupam): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (Kenneth): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded	✓			

Check By: [Signature] 07/3/14
Case Handler Date

*C: Critical *N: Non-Critical

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2018		13 Feb 2018 16:11 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LIM BENG KWEE , ID: S7677505B, Tel: +6597985714, Email: NOEMAIL		
Main Claimant:	TAN KEOK BUAY FELICIA , ID: S0126004I		
Vehicle Reg. No.:	SKS9573Z	Date of Loss:	09/02/2018 14:00 - :59
Claim Type:	TP / 549298	Policy/Cover Note No.:	28931732AVW (Comprehensive) Coverage: 31/03/2017 - 30/03/2018
Vehicle Reg. No. (Insured):	SLM5067P	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76, 575642 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/02/2018]		
Driver/Custodian (Insured):	LIM BENG KWEE (41 / Male), NRIC: S7677505B, Tel: +6597985714		
Adj Asg. Remarks:	W/s wld like Mr Kenneth Kong to survey the vehicle.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 27 Feb 2018

Preliminary Advice

Insured Vehicle No	: SLM5067P	Accident Date	: 09/02/2018
TP Vehicle No	: SKS9573Z	Assignment Date	: 13/02/2018
Make	: BMW 523I	Est. Duration of Repair	: 1.00
Date of Inspection	: 23/02/2018		
Inspection At	: ALANS UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	550.00
Revised Amount	:SS	400.00
Check Items (Estimated)	:SS	0.00
Total	:SS	400.00
Lump Sum Repair	:SS	

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

QBE Insurance (Singapore) Pte Ltd

A member of the worldwide QBE Insurance Group - Unique Entity No. 198401363C

1 Raffles Quay, #29-10 South Tower, Singapore 048583
Tel: 65-6224 6633 Fax: 65-6533 3270
GST Registration No.: M200644018
www.qbe.com.sg



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULE, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No. **8-V0013814-MVA-R001** Account Name **TAN KOEK EN JANET** MCI Type **MX1**

1 Index Mark and Registration Number of Vehicle or Chassis No: **SKS9573Z**

2 Name of Policyholder **TAN KEOK BUAY FELICIA**

3 Effective date of Commencement of Insurance for the purpose of the Regulations **02/09/2017**

4 Date of Expiry **01/09/2018**

5 Person or Classes of Person entitled to drive*

(a) The Policyholder

The Policyholder may also drive a motor car not belonging to him/her and not hired to him/her under a hire purchase agreement.

(b) Any person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from the driving the Motor Vehicle

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage

6 Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

7 Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risk and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia) are not to be included under these headings

I/WE HEREBY CERTIFY that the Policy to which this certificate relates is issued in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act. 1987 (Malaysia)

QBE Insurance (Singapore) Pte Ltd

Authorized Signature

Date of Issue: 24/08/2017

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLM5067P (MSIG)

Accident Date : 09-02-2018

Our Ref : SKS9573Z / CHAN

TAN KEOK BUAY FELICIA
C/O ALAN'S UNITED AUTO PTE LTD
BLK 7 SIN MING IND. EST.SECTOR C
#01-76
SINGAPORE

Date : 12-02-2018

*Not authorized
Returning After Paint
1 day*

ESTIMATE COST OF REPAIR FOR BMW 523I SKS9573Z

TO REMOVE FRONT BUMPER FOR ADJUST ,ALIGN AND REFIX

\$250.00 *150*

TO PUTTY AND SPRAY FRONT BUMPER

\$300.00 *250*
\$550.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Singapore Dollars Five Hundred Fifty Only

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003008/KQD3N2

Date: 06/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28931732AVW
Claimant Vehicle No :	SKS9573Z	Insured Vehicle No :	SLM5067P
Date of Loss:	09/02/2018	Nature of Claim:	TP
		Claim No:	549298

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS9573Z	Engine No:	03187691N52B25AF
Make & Model:	BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)	Chassis No:	WBAFP32080C864312
Reg. Date:	02/03/2011 (Man. Year: 2011)	Odometer:	177584 km
Colour:	Metallic Black		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	550.00	400.00	150.00	27.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	550.00	400.00	150.00	27.27
+ GST 7.00/7.00% (\$\$)	38.50	28.00	10.50	27.27
Nett Amount (\$\$)	588.50	428.00	160.50	27.27

INSPECTION

Date of Assignment:	13/02/2018	
Date Inspected:	23/02/2018 Inspected At:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 Singapore 575642
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2018)
Parts: 143	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS9573Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE FRONT BUMPER FOR ADJUST ,ALIGN AND REFIX	New	250.00	150.00
2	TO PUTTY AND SPRAY FRONT BUMPER	New	300.00	250.00
Gross Labour Cost (\$\$)			550.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >