

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4082X

DATE 13/2/2018 9:47

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber X			\$ 110.90
	Boot Lid Lock Upper X			\$ 132.10
	Boot Lid Lock Lower X			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (RH)			\$ 38.00
	Rear Panel X <i>repair</i>			\$ 391.80
	Rear Panel Garnish X			\$ 95.80
	SUB TOTAL			\$ 3,671.90
	LESS 20%			\$ 734.38
	DISCOUNTED TOTAL			\$ 2,937.52
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Boot Lid Advertisement Logo			\$ 100.00
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)			\$ 200.00
				\$ 430.00
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,550.00
	ESTIMATE TOTAL			\$ 4,917.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ka hwa (Kwa)
13/2/18
3 P.m.
4.5
After repair photo

400
540
X
20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.