

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD293E -

AAD1802-124

Not Authorized
Resurvey B4 paint @ 5687.51
93

Vehicle No.:	SHD239E - JHOW
Chassis No.:	VF1ABL15AUC282283
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	10.02.2018
Third Party Insurer :	AIG

PART		LIST
1	1 BUMPER COVER FRT	\$ <i>Bu</i> 1,259.42 ✓
2	1 BUMPER SPOILER FRT	\$ <i>Sn</i> 181.75 X
3	1 BUMPER FOG LAMP GRILLE LH	\$ <i>Sn</i> 207.22 X
4	1 BUMPER RETAINER FRT LH	\$ <i>Dir</i> 151.41 ✓
5	1 BUMPER SUPPORT FRT LH	\$ <i>Sn</i> 123.88
6	1 BUMPER BEAM FRT	\$ <i>R</i> 914.08
7	1 RADAITOR GRILLE	\$ <i>Sn</i> 1,707.78 X
8	1 RADAITOR GRILLE BADGE 'RENAULT'	\$ <i>Sn</i> 225.36 X
9	1 RADAITOR GRILLE FRAME ✓	\$ <i>CRS Sn</i> 1,353.75 ✓
10	1 FRAME FULL SUPPORT PANEL	\$ <i>Sn CR</i> <i>Sn</i> 615.90
11	1 FRAME FULL SUPPORT BRACKET	\$ <i>R</i> 89.79
12	1 AIR CLEANER LOWER	\$ <i>Sn</i> 352.64
13	1 AIR CLEANER HOSE	\$ <i>Sn</i> 76.14
14	1 AUTO COMPUTER	\$ <i>Sn</i> 5,032.17 X
15	1 STEERING PUMP ELECTRIC	\$ <i>Sn</i> 2,306.90
16	1 LOWER ARM LH	\$ <i>Sn</i> 685.76
17	1 KUNCKLE ARM LH	\$ <i>Sn</i> 846.98
18	1 ABSORBER FRT LH	\$ <i>Sn</i> 360.54
19	1 BONNET	\$ <i>R</i> 1,941.63
20	1 HEADLALMP LH	\$ <i>my CRS</i> 1,184.43 ✓
21	1 HEADLAMP PANEL FRT LH	\$ <i>R</i> 152.15 X
22	1 WHEEL HOUSING PANEL FRT LH	\$ <i>R</i> 5,173.47 X
23	1 FENDER PANEL FRT LH	\$ <i>R</i> 783.83 ✓
24	1 WHEELARCH FRT LH	\$ <i>CRS</i> 278.84 ✓
25	1 DOOR MIRROR LH	\$ <i>Sn</i> 1,483.40 X
26	1 DOOR MIRROR GLASS LH	\$ <i>Sn</i> 148.20 X
27	1 DOOR MIRROR BACK COVER LH	\$ <i>Sn</i> 218.46 X
28	1 DOOR PANEL FRT LH	\$ <i>R</i> 2,844.66 X
29	1 DOOR HINGE UPPER LH	\$ <i>R</i> 274.50 X
30	1 DOOR HINGE LOWER LH	\$ <i>R</i> 300.55 X

TOTAL	\$	31,275.60
10%	\$	3,127.56
	\$	28,148.04

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD293E -

AAD1802-124

Special Nett

1	1SET	FRONT BUMPER CLIP	\$	na	66.00	✓
2	1SET	WHEELARCH CLIP LH	\$	na	66.00	✓
3	1	TOW COVER FRT	\$	sn	14.50	X
4	1	CAP HUB LH FRT	\$	sn	35.00	X
5	1	RIM LH FRT	\$	n	385.00	X
6	1	TYRE LH FRT	\$	sn	330.00	X
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	na	9.80	X
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	na	12.50	X
9	1	DOOR STICKER "Trans-cab"	\$	na	80.00	60sn
10	1	DOOR STICKER "Classic"	\$	na	30.00	15sn

TOTAL	\$	1,028.80
TOTAL PARTS	\$	29,176.84

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	400l
To Check Electrical Lighting Concerned.	\$	170.00	20l
Putty and spray painting of the affected portion.	\$	3,000.00	440l
To check steering geometry and computer wheel alignment	\$	220.00	60l
Towing Fees	\$	na	120.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	20l
To rust-proofing of the affected areas.	\$	170.00	30l
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test \$ na 170.00 X

LKK Auto Consultants hence notify the Repairer of the following:
 To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

TOTAL \$ 7,200.00
Over All Total \$ 36,376.84

Repair Days 10 Days
 3 days

Acknowledged by Repairer
 Signature:
 Date:

(PARTS BY PARTS)