



陳林澤嗎私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SGK8M
Date of Accident : 14 February 2018

Messrs Gotbus Travel Pte Ltd

Date : 14 February 2018

Estimate To Repair PC1234E - Toyota Hiace Highroof Auto 14 Seater
Chassis No : JTFST22P500014280

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper <i>DO/DE</i>	\$ 496.00
02	1 pc	o/s front bumper side retainer <i>n/c</i>	\$ 145.00
03	1 pc	front bumper lower centre air grille <i>n/c</i>	\$ 218.10
04	1 pc	front bumper spot lamp garnish <i>n.s</i>	\$ 50.00
05	1 pc	o/s headlamp <i>n/c</i>	\$ 800.00
			\$ 1,709.10
		Less 25 %	\$ 427.28
			\$ 1,281.82
		<u>LABOUR & MISC. CHARGES</u>	
01		To check electrical lighting concerned.	\$ 60.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
03		Putty and spray painting of the affected portion.	\$ 11 250.00
			\$ 710.00
		Total	\$ 1,991.83

Not Authorized
HL
Tel: 62563561
take photo After repair
2 day
14/2/18
P/C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: