

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

13-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1064 T

| | | |
|-------|---|-------------|
| 1 pc | o/s tail lamp @ \$421.00 | \$ 421.00 |
| 1 pc | o/s bootlid reflector @ \$350.00 | \$ 350.00 |
| 1 pc | Bootlid cRdi | \$ 29.00 |
| 1 pc | Bootlid emblem | \$ 27.00 |
| 1 pc | Rear bumper | \$ 696.00 |
| 1 pc | Rear bumper lower cover | \$ 206.00 |
| 1 pc | Rear bumper o/s side bracket @ \$29.00 | \$ 29.00 |
| 1 pc | Rear bumper inner sponge | \$ 114.00 |
| 1 pc | Rear bumper reinforcement | \$ 607.00 |
| 1 pc | Rear bumper o/s stay @ \$53.00 | \$ 53.00 |
| 2 pcs | Rear bumper reinforcement lower bracket @ \$18.00 | \$ 36.00 |
| 2 pcs | Rear bumper reinforcement upper bracket @ \$18.00 | \$ 36.00 |
| 1 pc | Rear bumper o/s reflector | \$ 46.00 |
| 1 pc | Rear muffler assy | \$ 1,009.00 |
| 1 pc | Rear exhaust pipe hanger | \$ 49.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting \$ 3,708.00
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation *Less 10%* \$ 370.80
- Third party survey is on a "Without Prejudice" basis \$ 337.20
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by Repairer
Signature: *13/2/8 1600hs* \$ 280.00
Date: *13/2/8* \$ 100.00

S/NETT

| | | |
|-------|---|------------------------|
| 1 set | Rear bumper clips | \$ 48.00 |
| 1 set | Reverse sensor | \$ 280.00 <i>200</i> |
| 1 set | Bootlid stickers | \$ 100.00 |
| | Sundry | |
| | To dismantle / replace / test reverse sensor to new bumper and reset to the same | \$ 50.00 <i>20</i> |
| | To dismantle / replace exhaust pipe | \$ 120.00 <i>20</i> |
| | To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. | \$ 120.00 <i>50</i> |
| | To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel | \$ 180.00 <i>X</i> |
| | To putty and spray painting on rear bumper, bootlid, bootlid lower garnish, end panel | \$ 1,000.00 <i>400</i> |
| | To apply rustproofing on the repaired and replaced panels. | \$ 800.00 <i>540</i> |
| | | \$ 200.00 <i>X</i> |
| | | \$ 6,235.20 |

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.