

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6008Z
Ref. No : TAX/02/18/2082
Reg. Date : 13/05/2016
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : LOW SHIRLEY PUAY LI
Type of Accident : SIDE SWIPE
Date / Time of Accident : 10/02/2018 11:20:00 AM
Accident Reported Date / Time : 12/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 10/02/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094585
Special Instruction to ARC, if any :
TOWED \$60 / SFL9896M / *rich / Resurvey by part*
Prepared Date : 12/02/2018 02:11:21 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905768035

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 2,499.03	2,499.03
Other Charges	: 344.00	0.00
TOTAL	: 4,286.03	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00	0.00 3 days - p/p
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 12/02/2018 02:58:49 PM	01/01/1900 12:00:00 AM



13/02/18 @ 1420

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/02/2018 02:58:49 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	507.00	0.00 300
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER LH	378.00	0.00 75 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 X
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00	0.00 60 receipt
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	344.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>PT</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>na</i>	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>DE</i>	No
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace <i>Repair</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>na</i>	No
87940-47310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace <i>X</i>	No
81740-52040		6505465	MIRROR LAMP LH	1	65.30	10.00	58.77	Replace	Replace <i>X</i>	No
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace <i>X</i>	No
TOTAL MATERIALS								2,499.05	2,499.03	
TOTAL MATERIALS(Discounted)							2,499.03	2,499.03		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									