



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

| Invoice Name & Address                                                                                                      | Owner Name & Vehicle Info                                                                                                                                                                                         |
|-----------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| MS ADAMDAM<br><br>471B FERNVALE STREET<br>03-103 FERNVALE RIVERGROVE<br>SINGAPORE 792471<br><br>Contact No Mobile: 81898208 | Cust No/Name /MS ADAMDAM<br>Reg No/Reg Date SLC9724C / 31/05/201<br>Date In/Mileage / 0<br>Chassis No KNAFZ411MG5580435<br>Engine No G4FGFH609750<br>Make/Model KIA/FORTE K3 1.6 A SX ADQ<br>Colour/Trim D7U / WK |

| Account No                       | Terms                                                                          | Date/Time Printed | CSE        | Operator          | WIP No           |
|----------------------------------|--------------------------------------------------------------------------------|-------------------|------------|-------------------|------------------|
| CSM00081                         | Cash                                                                           | 13/02/2018/ 21:28 |            | 465 / Tay Jian Ye | 23458            |
| Description of Goods / Services  |                                                                                | Qty               | Unit Price | Disc%             | Amount           |
| E PNT88000                       | TO RENEW REAR BUMPER LWR , REPAIR REAR BUMPER                                  |                   |            |                   | 550 1375 1650.00 |
| E PNT98000                       | PAINT WORK SPRAY REAR BUMPER                                                   |                   |            |                   | 420 840.00       |
| E PNT88000                       | TO RENEW FRT BUMPER , HOOD, FRT SUPPORT PANEL                                  |                   |            |                   | 1100 2200.00     |
| E PNT88000                       | TO REMOVE AND REFIT RADIATOR AND CONDSENSOR                                    |                   |            |                   | 120 200.00       |
| A 97000001                       | TO TOP AIR CON GAS AND CHECK SYSTEM                                            |                   |            |                   | 80 200.00        |
| E PNT98000                       | PAINT WORK SPRAY FRT BUMPER , HOOD,                                            |                   |            |                   | 840 1260.00      |
| A 54900099                       | CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM                                     |                   |            |                   | 20 50.00         |
| A 10028901                       | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST<br>USING HI-SCAN PRO TEST |                   |            |                   | 200.00           |
| M SUNDRY                         | TO APPLY ANTI COROSSION ON AFFECTED PORTION                                    |                   |            |                   | 60 80.00         |
| M SUNDRY                         | SUNDRIES                                                                       |                   |            |                   | 20 50.00         |
| M STAY-RR BUMPER LH              |                                                                                | 1.00              | 75.00      | 00.00             | ? 75.00          |
| M STAY-RR BUMPER RH              |                                                                                | 1.00              | 75.00      | 00.00             | ? 75.00          |
| M BEAM-RR BUMPER                 |                                                                                | 1.00              | 365.00     | 00.00             | ? 365.00         |
| M BRACKET-RR BEAM LWR,CTR        |                                                                                | 1.00              | 5.00       | 00.00             | ? 5.00           |
| M BRACKET-RR BEAM LWR MTG        |                                                                                | 2.00              | 5.00       | 00.00             | ? 10.00          |
| M COVER-RR BUMPER,UPR            |                                                                                | 1.00              | 245.00     | 00.00             | ? 245.00         |
| M ULTRASONIC SENSOR ASSY-FBWS RR |                                                                                | 1.00              | 172.00     | 00.00             | ? 172.00         |
| M ULTRASONIC SENSOR ASSY-FBWS RR |                                                                                | 1.00              | 172.00     | 00.00             | ? 172.00         |
| M CARRIER ASSY-FRONT END MODULE  |                                                                                | 1.00              | 776.00     | 00.00             | ? 776.00         |
| M BRACKET-FR BUMPER SIDE MTG,LH  |                                                                                | 1.00              | 12.00      | 00.00             | 12 12.00         |
| M BRACKET-FR BUMPER SIDE MTG,RH  |                                                                                | 1.00              | 12.00      | 00.00             | 12 12.00         |
| M RAIL ASSY-FR BUMPER            |                                                                                | 1.00              | 410.00     | 00.00             | ? 410.00         |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address                                                                                                      | Owner Name & Vehicle Info                                                                                                                                                                                         |
|-----------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| MS ADAMDAM<br><br>471B FERNVALE STREET<br>03-103 FERNVALE RIVERGROVE<br>SINGAPORE 792471<br><br>Contact No Mobile: 81898208 | Cust No/Name /MS ADAMDAM<br>Reg No/Reg Date SLC9724C / 31/05/201<br>Date In/Mileage / 0<br>Chassis No KNAFZ411MG5580435<br>Engine No G4FGFH609750<br>Make/Model KIA/FORTE K3 1.6 A SX ADQ<br>Colour/Trim D7U / WK |

| Account No                       | Terms | Date/Time Printed | CSE        | Operator          | WIP No      |
|----------------------------------|-------|-------------------|------------|-------------------|-------------|
| CSM00081                         | Cash  | 13/02/2018/ 21:28 |            | 465 / Tay Jian Ye | 23458       |
| Description of Goods / Services  |       | Qty               | Unit Price | Disc%             | Amount      |
| M ABSORBER-FRONT BUMPER ENERGY   |       | 1.00              | 97.00      | 00.00             | CRA 97.00   |
| M GARNISH-RADIATOR GRILLE,UPR    |       | 1.00              | 44.00      | 00.00             | CRA 44.00?  |
| M COVER-FR BUMPER                |       | 1.00              | 728.00     | 00.00             | CRA 728.00  |
| M GRILLE ASSY-RADIATOR           |       | 1.00              | 322.00     | 00.00             | CRA 322.00  |
| M MOULDING-FRT BPR LICENSE PLATE |       | 1.00              | 21.00      | 00.00             | ? 21.00     |
| M LAMP ASSY-HEAD,LH              |       | 1.00              | 1870.00    | 00.00             | CRA 1870.00 |
| M LAMP ASSY-HEAD,RH              |       | 1.00              | 1870.00    | 00.00             | CRA 1870.00 |
| M CONDENSER ASSY-COOLER          |       | 1.00              | 697.00     | 00.00             | ? 697.00    |
| M PANEL ASSY-HOOD                |       | 1.00              | 1408.00    | 00.00             | PA 1408.00  |
| M HINGE ASSY-HOOD,RH             |       | 1.00              | 34.00      | 00.00             | X 34.00     |
| M HINGE ASSY-HOOD,LH             |       | 1.00              | 34.00      | 00.00             | X 34.00     |

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASH - Hp 90010068  
22/02/18 @ 1440  
6 days

Resy by paint

Confirm &amp; accepted by

|                      |                  |
|----------------------|------------------|
| Nett                 | 16,184.00        |
| 7% GST on            | 1132.88          |
| <b>Total Payable</b> | <b>17,316.88</b> |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.