



Neo Wee Cheong
Blk 320 Ang Mo Kio Ave 1
#12-1521
Singapore 560320

File No : SH/2018
Date : 14-February-2018

Estimated cost of repair for vehicle no : **SLB3786T** Nissan Sylphy
Accident involving vehicle no: **SLB3786T** & **SLK1273Y** on **14.02.2018**

Description	Quantity	Cost Price
RH front fender	1	\$ <i>Bn</i> 386.50 ✓
RH head lamp	1	\$ <i>Cr</i> 482.40 ✓
Front bumper	1	\$ <i>Bn</i> 382.70 ✓
Front bumper clips (1 set)	1	\$ <i>nn</i> 32.00 ✓
RH front bumper retainer	1	\$ <i>bn</i> 38.20 ✓
RH front bumper headlamp bottom beam (to check)	1	\$ <i>n</i> 165.00 X
Front bumper reinforcement (to check)	1	\$ <i>n</i> 561.90 X
To spray paint affected front and inner damaged portion inclusive of preparatory works and material		\$ 750.00 <i>Good</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp		\$ 30.00 <i>20</i>
To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment		\$ 520.00 <i>400</i>
To perform computerised wheel alignment		\$ 65.00 <i>60</i>
To perform computer diagnostic on drivetrain, ABS systems and clear fault codes		\$ <i>nn</i> 120.00 X
		\$ 3,533.70

T/Party: AXA Insurance Pte Ltd

Not Notified
1-B.1
Resurvey B4p.9m
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: **Page 1 of 1**