

AXA INSURANCE (S'PORE) PTE LTD

8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Attention: Motor Claim Department

ESTIMATE

DATE : 12/08/2018
ACC DATE : 09/02/2018
REF NO. : VFIX-TP20180424
POLICY NO :

RE : VEHICLE NO XD 2058 R MITSUBISHI FV 51

PARTICULAR

AMOUNT S\$

1	1	FRONT CHASSIS MEMBER		4,250.00	X
2	1	BONNET GRILLE		650.00	?
3	1	FRONT BUMPER	10/seat	3,530.00	
4	2	FRONT BUMPER END GARNISH R+L	152.00 17	304.00	X
5	1	STEP BOARD CENTER GARNISH	De	532.00	
6	2	FRONT BUMPER CENTER PANEL R+L	258.30 0.5/mis	516.60	12C
7	1	HEADLAMP RH		2,200.80	?
8	2	HEADLAMP RIM RH	138.00 0.5/cu	276.00	12C
9	1	FOG LAMP RH	17	1,008.00	X
10	2	FOG LAMP RIM RH	119.00 17	238.00	X
11	1	REAR MUDGUARD RH	mis	755.00	
12	1	REAR MUDGUARD MUDFLAG RH	mis	65.00	
13	3	MUDGUARD REAR BRACKET	50.00 100	150.00	12C
14	1	STEP BOARD GARNISH RH	17	280.00	X
15	1	STEP BOARD BASE RH	17	255.00	X
16	1	STEP BOARD BASE LOWER GARNISH RH	17	322.00	X
17	1	SIDE CANVAS FRAME RH	DD	750.00	
18	1	SIDE CANVAS RH	17	450.00	X
19	1	SIDE CANVAS MOTOR RH	17	1,228.00	X
20	1	TAIL LAMP RH	mis	325.00	
21	1	TAIL LAMP BRACKET RH	mis	65.00	
22	1	NUMBER PLATE BASE	50/	186.00	145.00
23	1	NUMBER PLATE LAMP	50.00	50.00	
			\$	18,386.40	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	DESCRIPTIONS	SPECIAL NETT	UNIT PRICE	AMOUNT S\$
1	1	60KM/H STICKER		<i>25</i> 25.00 SN 10
2	1	NUMBER PLATE FRONT/REAR		<i>75</i> 75.00 SN 14
3	1	TAIL GATE		<i>5,230</i> 5,230.00 SN ?
4	1	TAIL SIDE PANEL LEFT		<i>8,000</i> 8,000.00 SN X
5	1	TAIL SIDE PANEL RIGHT		<i>8,000</i> 8,000.00 SN X
6	1	REAR CHASSIS MEMBER		<i>1,800</i> 1,800.00 SN X
				<u>\$ 23,130.00</u>

	LABOUR & MISCELLANEOUS:	AMOUNT S\$
1	To remove damaged panel with all necessary components/attachments apply hot-works where necessary repair/reshape dented panel replace new parts	<i>2200</i> 3,500.00
2	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	<i>1300</i> 2,200.00
3	To conduct headlamp alignment	<i>30</i> 50.00
		<u>\$ 5,750.00</u>

GRAND TOTAL : \$ 47,266.40

SINGAPORE DOLLARS : FORTY SEVEN THOUSAND TWO HUNDRED SIXTY SIX & CENTS FORTY ONLY

Vfix Auto Service Pte Ltd



Not Affected
2/5/18
6 days
19/2/18
To keep the repair