


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4274P  
Ref. No : TAX/02/18/2083  
Reg. Date : 09/04/2014  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : YONG BOON HUAT  
Type of Accident : CHAIN COLLISION  
Date / Time of Accident : 12/02/2018 03:00:00 PM  
Accident Reported Date / Time : 12/02/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by :  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024094595  
Special Instruction to ARC, if any :  
SJP2556P - EQ - LKK / *Resin after repair*  
Prepared Date : 12/02/2018 04:31:34 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U805740713

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

|                              | Quotation from ARC       | Adjusted by Surveyor, if applicable |
|------------------------------|--------------------------|-------------------------------------|
| Total Labour Charges         | : 1,014.00               | 0.00                                |
| Total Spray Painting Charges | : 1,674.00               | 0.00                                |
| Total Material Charges       | : 4,443.30               | 4,443.30                            |
| Other Charges                | : 945.00                 | 0.00                                |
| <b>TOTAL</b>                 | <b>: 8,076.30</b>        | <b>0.00</b>                         |
| <b>Lum Sum Total</b>         | <b>: 8,100.00</b>        | <b>0.00</b>                         |
| No. of Repair Days           | : 7.00                   | 0.00 <sup>6</sup> days              |
| Prepared / Adjusted By       | :                        |                                     |
| Arc / Surveyor Sign Off Date | : 12/02/2018 06:50:57 PM | 01/01/1900 12:00:00 AM              |

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/02/2018 06:50:57 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

| Job Scope              | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------|--------------------|-------------------------------------|
| TO REPAIR REAR PORTION | 1,014.00           | 0.00 500                            |
| <b>Total Labour</b>    | <b>1,014.00</b>    | <b>0.00</b>                         |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR FENDER RH                       | 378.00             | 0.00 200                            |
| TO REPSRAY REAR BUMPER                          | 378.00             | 0.00 200                            |
| TO RESPRAY BUMPER BEAM                          | 180.00             | 0.00 100?                           |
| TO RESPRAY REAR PANEL                           | 180.00             | 0.00 100                            |
| TO RESPRAY TAIL GATE                            | 378.00             | 0.00 200                            |
| TO RESPRAY TROUGH BACK DOOR RH                  | 180.00             | 0.00 9. X                           |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>1,674.00</b>    | <b>0.00</b>                         |

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

| Job Scope                                                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------------------------------|--------------------|-------------------------------------|
| TO CHECK WIRING AND SYSTEM FUNCTION                                     | 80.00              | 0.00 40                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA                                 | 100.00             | 0.00 40                             |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                       | 125.00             | 0.00 12 X                           |
| TO REMOVE & REFIT REAR QUARTER GLASS RH                                 | 120.00             | 0.00 X                              |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                                 | 120.00             | 0.00 60                             |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.    | 120.00             | 0.00 60                             |
| TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | 120.00             | 0.00 30                             |
| TO REPLACE SUNDRY PARTS                                                 | 100.00             | 0.00 20                             |
| TO WASH AND VACUUM                                                      | 60.00              | 0.00 40                             |
| <b>Total Other Costs</b>                                                | <b>945.00</b>      | <b>0.00</b>                         |

**Part 4 - Spare Parts / Material Usage**

| Part Number                        | Portion | Stock No | Part Name                      | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|------------------------------------|---------|----------|--------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 61604-47090                        |         |          | FENDER RR/RH                   | 1   | 766.80          | 25.00        | 575.10           | Replace            | <i>R Repair</i>   | No              |
|                                    |         |          | STICKER DECAL SMRT             | 1   | 7.80            | 0.00         | 7.80             | Replace            | <i>new</i>        | No              |
|                                    |         |          | STICKER DECAL 6555 8888        | 1   | 21.60           | 0.00         | 21.60            | Replace            | <i>new</i>        | No              |
| 62710-47130                        |         |          | QUARTER GLASS RR/RH            | 1   | 846.50          | 25.00        | 634.87           | Replace            | <i>X</i>          | No              |
|                                    | COMMO N |          | SEALANT W/SCREEN               | 1   | 37.00           | 0.00         | 37.00            | Replace            | <i>X</i>          | No              |
| 81551-47180                        |         | 6505462  | TAIL LAMP RH                   | 1   | 557.80          | 10.00        | 502.02           | Replace            | <i>X</i>          | No              |
| 81551-47180                        |         | 6505462  | TAIL LAMP RH                   | 1   | 557.80          | 10.00        | 502.02           | Replace            | <i>X repeated</i> | No              |
| 52563-47010                        |         |          | TAIL LAMP BRACKET, LH          | 1   | 30.70           | 25.00        | 23.02            | Replace            | <i>X</i>          | No              |
| 52562-47010                        |         |          | TAIL LAMP BRACKET, RH          | 1   | 30.70           | 25.00        | 23.02            | Replace            | <i>?</i>          | No              |
| 52159-47905                        |         | 6505548  | BUMPER REAR                    | 1   | 458.60          | 25.00        | 343.95           | Replace            | <i>DE</i>         | No              |
| 52161-16010                        |         |          | BUMPER CLIPS                   | 10  | 1.61            | 25.00        | 12.07            | Replace            | <i>new</i>        | No              |
|                                    |         |          | PIXEL STICKER                  | 2   | 60.00           | 0.00         | 120.00           | Replace            | <i>new</i>        | No              |
| 52023-12240                        |         | 6505547  | BUMPER REINFORCEMENT REAR      | 1   | 205.70          | 25.00        | 154.27           | Replace            | <i>?</i>          | No              |
| 52016-47030                        |         |          | ARM SUB-ASSY, RR BUMPER LH     | 1   | 139.60          | 25.00        | 104.70           | Replace            | <i>?</i>          | No              |
| 52015-47050                        |         |          | ARM SUB-ASSY, RR BUMPER RH     | 1   | 139.60          | 25.00        | 104.70           | Replace            | <i>?</i>          | No              |
| 89997-30070                        |         |          | ANTENNA, ELECTRICAL LOWER REAR | 1   | 157.40          | 10.00        | 141.66           | Replace            | <i>?</i>          | No              |
|                                    |         |          | SENSOR REVERSE                 | 1   | 180.00          | 0.00         | 180.00           | Replace            | <i>new</i>        | No              |
| 52576-47020                        |         | 6505550  | BUMPER SIDE RETAINER RR/LH     | 1   | 94.80           | 25.00        | 71.10            | Replace            | <i>new</i>        | No              |
| 52575-47020                        |         | 6505549  | BUMPER SIDE RETAINER RR/RH     | 1   | 94.80           | 25.00        | 71.10            | Replace            | <i>new</i>        | No              |
| 76891-47020                        |         | 6505619  | BUMPER LIP REAR                | 1   | 228.90          | 25.00        | 171.67           | Replace            | <i>new</i>        | No              |
| 58308-47011                        |         |          | UNDER COVER SUB-ASSY, RR FLOOR | 1   | 514.50          | 25.00        | 385.87           | Replace            | <i>?</i>          | No              |
| 58307-47060                        |         | 6505522  | END PANEL                      | 1   | 602.10          | 25.00        | 451.57           | Replace            | <i>R Repair</i>   | No              |
|                                    | COMMO N | 4006314  | SEALANT SIKAFLEX               | 1   | 37.00           | 0.00         | 37.00            | Replace            | <i>X</i>          | No              |
| 67005-47241                        |         |          | TAILGATE ASY                   | 1   | 1,007.90        | 25.00        | 755.92           | Replace            | <i>Repair</i>     | No              |
| 75374-47051                        |         |          | NAME PLATE (HYBRID)            | 1   | 51.90           | 25.00        | 38.92            | Replace            | <i>new</i>        | No              |
| 61621-47030                        |         |          | TROUGH, BACK DOOR              | 1   | 110.90          | 25.00        | 83.17            | Replace            | <i>?</i>          | No              |
| <b>TOTAL MATERIALS</b>             |         |          |                                |     |                 |              |                  | <b>5,554.18</b>    | <b>5,554.12</b>   |                 |
| <b>TOTAL MATERIALS(Discounted)</b> |         |          |                                |     |                 |              |                  | <b>4,443.30</b>    | <b>4,443.30</b>   |                 |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part<br>Number                       | Portion | Part Name | Qty | List Price<br>(\$) | Discount<br>(%) | Final Price<br>(\$) | ARC Check | Surveyor<br>Check | LI<br>Check |
|--------------------------------------|---------|-----------|-----|--------------------|-----------------|---------------------|-----------|-------------------|-------------|
| <b>TOTAL SUPPLEMENTARY MATERIALS</b> |         |           |     |                    |                 |                     |           |                   |             |