


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1874H
Ref. No : TAX/02/18/2085
Reg. Date : 16/07/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TAN SIOW BENG
Type of Accident : SIDE SWIPE
Date / Time of Accident : 12/02/2018 10:20:00 PM
Accident Reported Date / Time : 13/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 12/02/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094597
Special Instruction to ARC, if any :
TOWED \$40 / SLN9701K / *Alh / Resurvey after repair*
Prepared Date : 13/02/2018 09:38:37 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405747075

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,690.00	0.00
Total Spray Painting Charges	: 4,842.00	0.00
Total Material Charges	: 9,827.35	11,856.85
Other Charges	: 1,465.00	0.00
TOTAL	: 17,824.35	0.00
Lum Sum Total	: 17,800.00	0.00
No. of Repair Days	: 10.00	0.00 <i>10 days - Lumpsum</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 13/02/2018 04:09:53 PM	01/01/1900 12:00:00 AM


13/02/18 @ 1530

Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/02/2018 04:09:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 2/13/2018 4:10:10 PM

LKK Auto Consultant hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	338.00	0.00 300
TO REPAIR LH PORTION	1,352.00	0.00 1000
Total Labour	1,690.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 70
TO RESPRAY ROCKER PANEL MOULDING	360.00	0.00 100
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY RIM	540.00	0.00 50
TO RESPRAY APRON PANEL LH	180.00	0.00 100
TO RESPRAY FRONT PILLAR LH	180.00	0.00 100
Total Spray Painting & Panel Beating	4,842.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 40
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	300.00	0.00 100
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO TRANSFER DOOR MECHANISM	240.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 125?
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	0.00 90
Total Other Costs	1,465.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>SCA</i>	No
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace <i>SCA</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace <i>SCA</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>SCA</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>SCA</i>	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>SCA</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>SCA</i>	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>SCA</i>	No
53851-47040			FENDER LINER PAD, FR WHEEL. RH	1	49.30	25.00	36.97	Replace	Replace <i>SCA</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>SCA</i>	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>SCA</i>	No
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace <i>SCA</i>	No
65631-47041			SILL MEMBER PLATE RR/RH	1	57.50	25.00	43.12	Replace	Replace <i>SCA</i>	No
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Repair	Repair <i>SCA</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>SCA</i>	No
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.88	Repair	Repair <i>SCA</i>	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace <i>SCA</i>	No
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Repair	Repair <i>SCA</i>	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>SCA</i>	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>SCA</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>SCA</i>	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace <i>SCA</i>	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>SCA</i>	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>SCA</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>SCA</i>	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>SCA</i>	No
53852-47020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace <i>SCA</i>	No
53826-47010			FENDER PROTECTOR FRT/LH UPPER	1	46.10	25.00	34.57	Replace	Replace <i>SCA</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53828-47060			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	25.00	85.87	Replace	Replace ?	No
53720-12030			FENDER APRON FRT/LH	1	140.80	25.00	105.60	Replace	Replace Repair	No
62120-47021			QUARTER GLASS FRT/LH	1	234.90	25.00	176.17	Replace	Replace ? see to	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No
61132-47030			PILLAR, FR BODY, LH	1	363.10	25.00	272.32	Replace	Replace Repair	No
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace X	No
67002-47070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace RA	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace new	No
68740-12120			HINGE LOWER LHF, DOOR	1	90.10	25.00	67.57	Replace	Replace ? X	No
68720-15151			HINGE UPPER LHF, DOOR	1	80.50	25.00	60.37	Replace	Replace ?	No
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.72	Replace	Replace ?	No
75720-47021			DOOR BELT FRT/LH	1	69.20	25.00	51.90	Replace	Replace X	No
75922-47020			TAPE OUT WIN FRAME LHF, DOOR	1	45.60	25.00	34.20	Replace	Replace new	No
69210-74030			DOOR OUTER HANDLE FRT/LH	1	370.80	25.00	278.10	Replace	Replace Repair	No
69040-47070			DOOR LOCK FRT/LH	1	575.80	25.00	431.85	Replace	Replace X	No
87940-47310		6505599	MIRROR ASSY, LH	1	1,224.90	25.00	918.67	Replace	Replace ?	No
87945-74010		6505597	COVER, OUTER MIRROR, LH	1	107.40	25.00	80.55	Replace	Replace see	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
42611--47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace see	No
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace Repair	No
			PIXEL STICKER	1	60.00	0.00	60.00	Replace	Replace new	No
75740-47021			DOOR BELT RR/LH	1	69.20	25.00	51.90	Replace	Replace X	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Repair	Replace Repair	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace new	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace new	No
TOTAL MATERIALS								12,284.28	14,821.07	
TOTAL MATERIALS(Discounted)								9,827.35	11,856.85	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									