

22/02/2002

ASS. REC. BY:

REF: CS/FCI18003057 / S-H3n2 Special Instruction:

Surveyor: Sebastian ASSIGNMENT (Office)From (Person): Aung Yin Min of FCI Date/Time: 14/2/18

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDP 604 Insured: SHC 07554at Workshop m/s Trans Eurokurs Tel: 63 63 3003of 12 Sungai Kadut AvePolicy No: _____ Claim No: D18061384MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 12/2/18
(Client's Record)CA / REV / REP. / REV 24 HRS 1 wkr H.O.D. Endorsement: _____Date/Time: 5:50pm 14/2/18 Person Contacted: Jobi Vehicle IN/OUT OUT

Date/Time	Action/Instruction
	(✓) Estimate called no answer. wksp might be closed for CNY
	SDP 604 -x
	SHC 07554 - NA / III 16015829/r3 D.O.A: 23/8/16
	Part by Part \$7954- (Red. 918 :10%)

FCI

ASSIGNMENT

From: Date: 19/2/18

Estimated Cost:

OD: TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: SDP604

at: Trans Eupkeurs

Address: 12 Sungai Kadut Ave

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

Client's Record: 2pm @ owner waiting

Make of Veh: Jobi



Policy Condition:

Remark: The veh had commenced its repair at the time of inspection.

Salvage/Market Value:

DAC Accident Report: Consistent? Yes or No:

QA / PP / Sign: Consistent? Yes or No:

Est. Repairs: days Fee: Yes or No:

Lum Sum: % CVA: Yes or No:

CA / REV / REP / 24 HRS lwp

Date: Person Contacted: Vehicle IN / OUT:

Ref: SDP604 Date: 22/11/2011

Type: MC/MS/BUS/VAN/LOTR/TAKE HOME/MAJOR

Truck Trailer:

Make: Bmw 730Li No: 2996

Colour: White Insured:

Co Reading: 170653 *Part Insured:

Engine:

CNo: WBAKB22000C951225

Gen Cond: Good 20 / Poor / Burnt

Steering: 20 / Jammed / Leaked / Burnt

Brake: 20 / Jammed / Leaked / Burnt

Mod: 20 / S/RM / STD A/RM

Tyre Size: F 245/40ZR20

R 275/35ZR20

BS/DUN/EXNOVA/GY/PS/LIZA/MIC/OHTSU/PIR/SUM

TOYO/YOKO Pirelli

Front	Rear
R/Sa <u>7</u> mm	R/Sa <u>7</u> mm
L/Sa <u>7</u> mm	L/Sa <u>7</u> mm
D/A <u>12/2/18</u>	D/A <u>19/2/18</u>

Surveyed at: Trans Eupkeurs

Des of Damages: FR / Rear / OS / NS / UO / Roofed

Fit o/s

The UO / Chassis/frame / Body Structure affected due to collision

Date Time Action/Instruction

Sebastian

Pls check parts prices

26/3/2018

RECEIVED 06 APR 2018

Date Time File Pass to: : Prelim. Report

6/4 Typist ☒ Final Report

Date Time File Return to:

Days Of Repair: 5

Resurvey No. of Trip: 1

Sum. Rep:

Transporter:

Add Fee:

Steins:

Rep:

Test:

Rep:

Report Format: TP

Lum Sum: 10 7954

160
50
50
24
284



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003057/Std3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-02-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 755U	Veh. Inspected	SDP 60U
Policy No.		Coverage (\$)	0.00
Claim No.	D18001384MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/02/2018	Inspection Date	
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	14-02-2018	Our Ref No. D18001384MFSH
Accident Date	12-02-2018	Claim Type. Third Party
Insured Vehicle	SHC0755U	Third Party Vehicle. SDP60U
Survey Location	EUROKARS CENTRE 12 SUNGEI KADUT AVE	
Contact Person.	JOBI THOMAS	
Contact No.	63633003/ 63602446	Fax No. 63602899
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Jobi Thomas

From: Claim Workflow System <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, February 14, 2018 4:44 PM
To: Jobi Thomas
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG;
AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: SURVEYOR APPOINTED; OUR REF : D18001384MFSH ; YOUR REF: SDP60U

Dear Sir/Madam

PRI Request For **SDP60U** Accident Involving **SHC0755U** On 12-02-2018 AT 11:00:00HRS.

Please find below details for your reference

- **Claim number** : D18001384MFSH
- **Insured vehicle number** : SHC0755U
- **Accident date** : 12-02-2018
- **Third-party vehicle number** : SDP60U
- **Assignment type** : WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED
- **Surveyor** : LKK AUTO CONSULTANTS PTE LTD
- **Officer-in-Charge** : AUNGYM

PS: This is a system generated mail. Please do not reply to this mail.

Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Tan Kheng Leong Jacksonn
 Period of Insurance : 25 May 2017 To 21 Nov 2018
 Engine No. : 13217889N52B30AF
 Chassis No. : WBAKB22000C951225

Vehicle No. : SLP1021G
 Policy No. : 1700026364
 Endorsement No. :
 Issued Date : 10 Jul 2017

ABOUT THE COVER

Make/Model : BMW 730 Li
 Engine Capacity/Tonnage : 2,996.00 CC
 Driver Restriction : NA

Sum Insured : Market Value
 Off Peak Car : No

First Year of Registration : 2011
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

(1) The Policyholder
 (2) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if before meets the specified age condition.
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDPE") if you are or Your Authorised Driver (named or unnamed) is under the age of 22 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, during tuition, driving test, racing, speed-making, stability test or speed-seeing, the damage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (10 days) - 150000 + 160000 Optional

* Limitations imposed operative by Section II of the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189) and Section 25 of the Road Transport Act (1997) (Malaysia) are not to be included in the above headings.

EXCESS

Section 1
 Fire - \$0, Own Damage - \$800, Theft - \$0, Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreens - \$100

Named Driver and Excess (where applicable)

Tan Kheng Leong Jacksonn - \$200 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/AO Authorised Repairers (For claims related repairs)
 Any accident repairs to the Vehicle must be carried out by one of our Approved Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For larger Approved Reporting Centres/AO Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6236 6223. Alternatively, You may refer to AIG website www.aig.com.sg or AIG 955 Mobile App. Simply search and download the 955 App from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HL Bank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189, Part IV of the Road Transport Act, 1997) (Malaysia) and Motor Vehicle (Third-Party Risks) Rules, 1958 (Malaysia).

25001702017

5344 PTE LTD - MM PROGRAM

8 SHENTON WAY #44-01A AXA TOWER

SINGAPORE 06881

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

528088


REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S16429581**

Name: **JACKSONN TAN KHENG LEONG**

Birth Date: **19 Jun 1964**

Valid Until: **25 Apr 2016**

 002560979J

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S16429581**

Name: **JACKSONN TAN KHENG LEONG**



陳 矜 良

Race: **CHINESE**

Date of Birth: **19-06-1964** Sex: **M**

Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE
07 Sep 1982

Class 3

Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$

Class 4

Motor vehicles which are constructed to carry load or passengers and the unladen weight $> 2500\text{kg}$
Motor vehicles which are not constructed to carry load or passengers and the unladen weight $\leq 7250\text{kg}$

21 Apr 1986



Licence No: S16429581

NP 428A

HIN LUNG AUTO PTE LTD ☎ 64722222



NRIC No: S16429581



Blood Group: A+ Date of issue: 20-09-1999

APT BLK 7 HAIG ROAD #05-445
SINGAPORE 430007

NRIC No: S16429581

Date: 22/07/2009 (R) No: 622 1012

I, TENG PENG SIANG

S 1359689A driver Taxi SHC 75U

admitted that S reverse ^{and hit} into

SDP 60U (BMW 730U) front driver
bumper.



Teng Peng Siang

S1359689A

TRANS EUROKARS PTE LTD
NO:12 SUNGEI KADUT AVE, SINGAPORE 729648
ESTIMATE COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD		NAME : MR.JACKSONN TAN KHENG LEONG		WIP :	
36 ROBINSON ROAD		ADDRESS : BLK 7 HAIG ROAD		EXCESS :	
#16-01 CITY HOUSE		#05-445		DATE: 13-Feb-18	
SINGAPORE 068877		SINGAPORE 430007			
ATTN. : MOTOR CLAIMS		TEL : 81888181			
FAX :					
VEH NO :	SDP60U	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6360 2446
CHASSIS NO :	WBAKB22000C951225	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	BMW 730LI	DATE REG.:	22-Nov-11	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	REVISED	PRICES	
1	FRONT BUMPER	1	0	\$ 2,200.00	✓ OK
2	FRONT BUMPER BRACKET RH	1	0	\$ 30.00	✓ NEC
3	FRONT BUMPER RIVETS	10	0	\$ 30.00	✓ NEC
4	FRONT BUMPER SENSOR RH	1	0	\$ 310.00	✓ DMG
5	FRONT BUMPER SENSOR RETAINER RH	1	0	\$ 110.00	✓ NEC
6	FRONT BUMPER FOG LAMP RH	1	0	\$ 520.00	Deform
7	FRONT BUMPER LOWER GRILLE RH	1	0	\$ 110.00	✓ NW
8	FRONT BUMPER LOWER GRILLE CHROME RH	1	0	\$ 100.00	✓ NW
9	HEADLAMP RH	1	0	\$ 3,200.00	✓ CRK
10	HEADLAMP WASHER ACTUATOR NOZZLE RH	1	0	\$ 360.00	✓ CRK
11	HEADLAMP WASHER ACTUATOR NOZZLE COVER RH	1	0	\$ 110.00	✓ CRK
TOTAL PARTS				\$ 7,080.00	
LESS 10%				\$ 708.00	
TOTAL PARTS COST				\$ 6,372.00	
Labour Description					
1	TO REPLACE FRONT BUMPER, TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 600 800.00	✓ 400 / day
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.			\$ 1,000.00	✓ 400 (paint)
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00	✓ 150
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 150 150.00	✓ 120
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 200.00	✓ 150
6	SUNDRIES.			\$ 100.00	✓ NETT
TOTAL LABOUR				\$ 2,500.00	
TOTAL PARTS				\$ 6,372.00	
TOTAL				\$ 8,872.00	
LESS EXCESS				\$ -	

TOTAL AFTER EXCESS	\$	-	
GST 7%	\$	-	\$ -
GRAND TOTAL	\$	-	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Sebastian.
19/2/18.

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint

90036121

sebastianyoung@lkkauto.com.

5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TRANS EUROKARS PTE LTD
NO:12 SUNGEI KADUT AVE, SINGAPORE 729648
FINALIZATION COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: MR.JACKSONN TAN KHENG LEONG ADDRESS: BLK 7 HAIG ROAD #05-445 SINGAPORE 430007 TEL: 81888181		WIP: EXCESS: DATE: 13-Feb-18	
VEH NO:	SDP60U	DATE IN:		CONTACT PERSON:	JOBI THOMAS 6360 2446
CHASSIS NO:	WBAKB22000C951225	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	BMW 730LI	DATE REG.:	22-Nov-11	POLICY NO.:	

NATURE OF WORKS					
S/NO	Parts Description				
	QTY			REVISED	PRICES
1	FRONT BUMPER	1	0	\$ 2,200.00	\$ 2,200.00
2	FRONT BUMPER BRACKET RH	1	0	\$ 30.00	\$ 30.00
3	FRONT BUMPER RIVETS	10	0	\$ 30.00	\$ 30.00
4	FRONT BUMPER SENSOR RH	1	0	\$ 310.00	\$ 310.00
5	FRONT BUMPER SENSOR RETAINER RH	1	0	\$ 110.00	\$ 110.00
6	FRONT BUMPER FOG LAMP RH	1	0	\$ 520.00	\$ 520.00
7	FRONT BUMPER LOWER GRILLE RH	1	0	\$ -	\$ 110.00
8	FRONT BUMPER LOWER GRILLE CHROME RH	1	0	\$ -	\$ 100.00
9	HEADLAMP RH	1	0	\$ 3,200.00	\$ 3,200.00
10	HEADLAMP WASHER ACTUATOR NOZZLE RH	1	0	\$ 360.00	\$ 360.00
11	HEADLAMP WASHER ACTUATOR NOZZLE COVER RH	1	0	\$ -	\$ 110.00
TOTAL PARTS				\$ 6,760.00	\$ 7,080.00
LESS 10%				\$ 676.00	\$ 708.00
TOTAL PARTS COST				\$ 6,084.00	\$ 6,372.00
Labour Description					
1	TO REPLACE FRONT BUMPER. TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 600.00	\$ 800.00
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.			\$ 800.00	\$ 1,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 150.00	\$ 250.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 120.00	\$ 150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 150.00	\$ 200.00
6	SUNDRIES.			\$ 50.00	\$ 100.00
TOTAL LABOUR				\$ 1,870.00	\$ 2,500.00
TOTAL PARTS				\$ 6,084.00	\$ 6,372.00
TOTAL				\$ 7,954.00	\$ 8,872.00
LESS EXCESS				\$ -	\$ -

TOTAL AFTER EXCESS	\$	7,954.00	
GST 7%	\$	556.78	\$ -
GRAND TOTAL	\$	8,510.78	\$ -

NUMBER OF DAYS: 5 WORKING DAYS(EXCLUDE WAITING FOR SURVEY,AUTHORIZATION,PARTS,SAT,SUN & PH)

VEH NO :
CHASSIS NO :
MODEL :

	DESCRIPTION	PART NO	QTY	UNIT PRICE
1	REAR BUMPER			
2	REAR BUMPER LOWER SKIRT SPOILER			
3	REAR BUMPER RETAINER LH			
4	REAR BUMPER SUPPORT LH			
5	REAR BUMPER FOGLAMP LH			
6	REAR BUMPER SPLASH SHIELD LH			
7	REAR BUMPER CLIPS			
8	REAR BUMPER RIVETS			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003057/Std3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 06-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 755U	Veh. Inspected	SDP 60U
Policy No.		Coverage (\$)	0.00
Claim No.	D18001384MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	14/02/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W 730LI	c.c	2996
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAKB22000C951225	Colour	WHITE
Odometer	170653	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 ZR20	PIRELLI	7 mm
L/H Front Tyre	245/40 ZR20	PIRELLI	7 mm
R/H Rear Tyre	275/55 ZR20	PIRELLI	7 mm
L/H Rear Tyre	275/55 ZR20	PIRELLI	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/02/2018	Inspection Date	19/02/2018
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDP 60U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	CUT	2,200.00	2,200.00
1	FRONT BUMPER BRACKET RH	NECESSARY	30.00	30.00
10	FRONT BUMPER RIVETS	NECESSARY	30.00	30.00
1	FRONT BUMPER SENSOR RH	DAMAGED	310.00	310.00
1	FRONT BUMPER SENSOR RETAINER RH	NECESSARY	110.00	110.00
1	FRONT BUMPER FOG LAMP RH	DEFORMED	520.00	520.00
1	FRONT BUMPER LOWER GRILLE RH	NOT NECESSARY	110.00	-
1	FRONT BUMPER LOWER GRILLE CHROME RH	NOT NECESSARY	100.00	-
1	HEADLAMP RH	CRACKED	3,200.00	3,200.00
1	HEADLAMP WASHER ACTUATOR NOZZLE RH	CRACKED	360.00	360.00
1	HEADLAMP WASHER ACTUATOR NOZZLE COVER RH	NOT NECESSARY	110.00	-
	LESS 10% DISCOUNT		-708.00	-676.00
			6,372.00	6,084.00
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
			100.00	50.00
LABOUR				
	TO REPLACE FRONT BUMPER TO REPAIR FRONT FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT.		800.00	600.00
	TO RESPRAY FRONT BUMPER AND FRONT FENDER RH.		1,000.00	800.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		200.00	150.00
	-		-	-
	-		-	-
	-		-	-
			2,400.00	1,820.00
GRAND TOTAL			8,872.00	7,954.00



RECOMMENDED COST OF REPAIRS			7,954.00
-----------------------------	--	--	----------

Report Ref No. CS/FCI18003057/Std3n2

YEANG WAI KEEN
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.