

ASS. REC. BY:

REF: CS/FCL18003064/Kg bnz

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS Lurene Jew

of

FCL

Date/Time:

18062018 528pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 8876U

Insured:

SHC 7887B

at Workshop m/s

Optima Workz

Tel:

6484 7919

of

9A Serangoon North Ave 5

Policy No:

Claim No:

D18001363MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10022018

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

21 052018 11:11am

Person Contacted:

Sharon.

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

26/6/18 @ 3.12pm revised to Lurene by email

2/7 @ 1552.90 Cc, Lurene by email (Red B 1133.57, 42%)

22/03/2002

ASS. REQ. BY:

REF: CS3/FCI18003064/d3 Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of FCI

Date/Time: 14/2/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SK288764

Insured:

SHC7887B

at Workshop m/s

AMA Automotive

Tel:

87783636

of

36 Toh Guan Rd # 01-36

Policy No:

Claim No:

D18001363MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/02/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

12.45pm 14/2/18

Person Contacted:

Melvin

Vehicle IN / OUT

Date/Time

Action/Instruction

(X)

Estimate

wks closed @ 14/2/18

SK288764-X

SHC7887B-CS3/A1617007597/H146392

D.O.A: 10/04/2017

ASS. REC. BY:

REF: FOZ /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Segn:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

16 File pass to Customer

RECEIVED 02 JUL 2010

Date/Time, File Pass to?

17/07/18

Date/Time, File Return to?

2)

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fixturs

Others

TOTAL

110505012222

Report Format :

Lump Sum / I.B.I: (\$

TP1550.90

Veh No:

SKZ 8876U

Yr Regn:

02, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISXtrail

C.C.

1997

Colour:

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

55741

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

INJANT328 0001434Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

225/60R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

10/2/18

D.O.I.

25/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s door

The U/C / Chassis frame / Body Structure affected due to collision.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001363MFSH

Date: 26 June 2018

Our Ref: CS/FCI18003064/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKZ 8876U

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/06/2018 at the premises of M/s OPTIMA WERKZ, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>2,686.47</u>
Revised Estimate Amount	: S\$ <u>1,552.90</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear o/s door.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	13-02-2018	Our Ref No. D18001363MFSH
Accident Date	10-02-2018	Claim Type. Third Party
Insured Vehicle	SHC7887B	Third Party Vehicle. SKZ8876U
Survey Location	6 KUNG CHONG ROAD	
Contact Person.	SHARON TEN (MS)	
Contact No.	64849919/ 64849919	Fax No. 64811011
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

21052018 @ 11:11am
Sharon veh not in

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	OPTIMA WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	CHIA S ARUL LLC	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MOTOR SURVEY ASSIGNMENT

Date	13-02-2018	Our Ref No. D18001363MFSH
Accident Date	10-02-2018	Claim Type. Third Party
Insured Vehicle	SHC7887B	Third Party Vehicle. SKZ8876U
Survey Location	36 TOH GUAN ROAD #01-36	
Contact Person.	MR MELVIN	
Contact No.	87783636/ 87783636	Fax No. 67338183
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AMA AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	CHIA S ARUL LLC	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235008)



PRI Documents



Close



PRI Header Details

Claim No	D18001363MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHIA S AI
Workshop Name	AMA AUTOMOTIVE PTE LTD (Contact Person : MR MELVIN)	Survey Location & Contact Details	36 TOH GUAN ROAD #01-36 Mobile: 87783636 , Phone: 87783636 , Fax: 6733818: EmailId: ALYWIN@CHIAARUL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7887B	TP Vehicle No	SKZ8876U
PRI Recieved Date	13-02-2018 08:23:07 PM	Surveyor Appointed Date	14-02-2018 11:18:50 AM	Surveyor Accept Date	14-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-02-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 26 June 2018 3:12 PM
To: 'Claim Workflow System'; SUR
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; assignments
Subject: RE: SURVEY ASSESSMENT - D18001363MFSH/1
Attachments: CSFCI18003064Kqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SKZ 8876U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 21 May 2018 11:12 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; assignments <assignments@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001363MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 18 May, 2018 5:28 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001363MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 17 May 2018

Third Party Insurer:

FIRST CAPITAL

Vehicle No: SKZ8876U

Third Party Veh No:

SHC7887B

Model: NISSAN X-TRAIL 2.0

Date of Accident:

10/02/2018

Chassis: JN1JANT32Z0001434

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	RAER DOOR RH		13 \$1,342.77
2	REAR DOOR HINGE RH - TOP & LOWER	\$72.93	12 \$145.86
1	REAR DOOR WEATHER STRIP RH		12 \$144.95
1	REAR DOOR BLACK FRAME STICKER RH		12 \$75.66
SUB TOTAL			\$1,709.24
Less 30%			-\$512.77
PARTS TOTAL			\$1,196.47

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION

\$600.00 200

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION

\$600.00 250

TO TUFF KOTE / ANTI-RUST

\$60.00 30

TO CHECK WIRING WITH WATER LEAKAGE TEST

\$80.00 20

TO DISMANTLE & REINSTALL REAR RH DOOR INNER COMPONENT MECHANISM

TO FACILITATE REPAIR WITH CHECK FOR FUNCTION

\$150.00 60

LABOUR TOTAL \$1,490.00

WINSON

TOTAL \$2,686.47

Not withstanding
the survey by painting
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003064/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7887B	Veh. Inspected	SKZ 8876U	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18001363MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	18/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN X-TRAIL (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1JANT32Z0001434	Colour	METALLIC RED	
Odometer	55741	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	DUNLOP	7 mm	
L/H Front Tyre	225/60 R18	DUNLOP	7 mm	
R/H Rear Tyre	225/60 R18	DUNLOP	6 mm	
L/H Rear Tyre	225/60 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S DOOR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/02/2018	Inspection Date	25/06/2018	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8876U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR RH	BENT	1,342.77	1,342.77
2	REAR DOOR HINGE RH-TOP & LOWER @\$72.93	TO REPAIR SEE LABOUR	145.86	-
1	REAR DOOR WEATHERSTRIP RH	SERVICEABLE	144.95	-
1	REAR DOOR BLACK FRAME STICKER RH	NECESSARY	75.66	75.66
	LESS 30% DISCOUNT		-512.77	-425.53
			1,196.47	992.90
	LABOUR			
	TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION.INCLUSIVE OF THE REPAIR OF REAR DOOR HINGE RH-TOP & LOWER.		600.00	200.00
	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION.		600.00	250.00
	TO TUFF KOTE/ANTI-RUST.		60.00	30.00
	TO CHECK WIRING WITH WATER LEAKAGE TEST.		80.00	20.00
	TO DISMANTLE & REINSTALL REAR RH DOOR INNER COMPONENT MECHANISM TO FACILITATE REPAIR WITH CHECK FOR FUNCTION.		150.00	60.00
			1,490.00	560.00
	GRAND TOTAL		2,686.47	1,552.90
	RECOMMENDED COST OF REPAIRS			1,552.90

Report Ref No. CS/FCI18003064/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.