

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0201/2018/CCS  
**Date** : 14-Feb-18

**Vehicle NOT IN workshop. Kindly arrange for survey.**  
**Your insured vehicle no: SLS 6786 J**

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms Helen Too Mei Gek  
**Address** : 16 Upper Serangoon View  
#04-12  
Singapore 534201  
**Telephone** : HP +65 92388322  
**Type of Claim** : Third Party Claims  
**Policy No.** : 5075232053-02  
**Vehicle No** : ~~SKK-3135C~~ SKK 3135C  
**Model Code** : Audi A3 SB 1.4 TFSI  
**Model / Year** : Nov-12  
**Engine No** : CAX B41369  
**Chassis No** : WAUZZZ8P4DA004309  
**Mileage** : -  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 13-Feb-18  
**Place of Accident** : Basement 2 carpark Raffles City Shopping Centre

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKH 3135 C.

| S/N                  | Nature of Jobs                                                                                                                                                          | Estimated Charges            | Surveyor's Recommendation |
|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|---------------------------|
| 1                    | To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.                                       | S/N \$ 360.00 ✓              |                           |
| 2                    | To remove and transfer both lhs front and rear door's multi-lock system and power window devices.                                                                       | S/N \$ 560.00 ✓              |                           |
| 3                    | To remove and transfer rear parking aid.                                                                                                                                | S/N \$ 280.00 ✓              |                           |
| 4                    | To dismantle front bumper, renew lhs front fender, lhs front and rear doors, lhs wing mirror assy and rear bumper. Repair lhs rear fender. Reinstall all parts removed. | \$ <del>4,200.00</del> 2500. |                           |
| 5                    | To respray lhs front fender, lhs front and rear doors, door covers, wing mirror cover, lhs rear fender and rear bumper.                                                 | \$ <del>4,600.00</del> 2950. |                           |
| 6                    | To renew lhs front and rear rims. Carry out wheel alignment.                                                                                                            | S/N \$ 320.00 ✗              |                           |
| 7                    | To carry out diagnostic checks.                                                                                                                                         | S/N \$ 192.00 ✓              |                           |
| TOTAL LABOUR CHARGES |                                                                                                                                                                         | : <u>\$ 10,512.00</u>        |                           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SKH 3135 C.

| S/N                  | Parts Description                                 | Damage Parts & Prices |         |
|----------------------|---------------------------------------------------|-----------------------|---------|
|                      |                                                   | S/NETT                | REMARKS |
| 1                    | FRONT FENDER - LH <i>Dented</i>                   | \$ 665.00             | ✓       |
| 2                    | FRONT FENDER BRACKET - LH FRT / CTR / REAR ?      | 3 \$ 86.00            | ?       |
| 3                    | FRONT FENDER RIVET SET <i>new</i>                 | \$ 24.00              | ✓       |
| 4                    | FRONT FENDER BRACE - LH <i>new</i>                | \$ 47.00              | +       |
| 5                    | FRONT FENDER CLOSING ELEMENT - LH <i>new</i>      | \$ 81.00              | +       |
| 6                    | FRONT WHEEL HOUSING LINER - LH <i>new</i>         | \$ 151.00             | +       |
| 7                    | WHEEL HOUSING LINER ATTACHMENT PARTS ?            | \$ 62.00              | ?       |
| 8                    | FRONT DOOR - LH <i>Dented</i>                     | \$ 1,912.00           | ✓       |
| 9                    | FRONT DOOR PROTECTIVE STRIP - LH <i>at</i>        | \$ 176.00             | ✓       |
| 10                   | FRONT DOOR COVER - LH <i>new</i>                  | \$ 265.00             | ✓       |
| 11                   | SIDE MIRROR MOUNTING - LH <i>new</i>              | \$ 902.00             | +       |
| 12                   | SIDE MIRROR CAP - LH <i>new</i>                   | \$ 501.00             | +       |
| 13                   | SIDE MIRROR TURN SIGNAL INDICATOR - LH <i>new</i> | \$ 88.00              | +       |
| 14                   | REAR DOOR - LH <i>Dented</i>                      | \$ 1,912.00           | ✓       |
| 15                   | REAR DOOR ATTACHMENT PARTS ?                      | \$ 64.00              | ?       |
| 16                   | REAR DOOR PROTECTIVE STRIP - LH <i>at</i>         | \$ 117.00             | ✓       |
| 17                   | REAR DOOR COVER - LH <i>new</i>                   | \$ 247.00             | ✓       |
| 18                   | REAR BUMPER <i>Regis</i>                          | \$ 1,147.00           | +       |
| 19                   | REAR BUMPER GUIDE - LH <i>new</i>                 | \$ 57.00              | +       |
| 20                   | ALUMINIUM RIM - LH FRONT / LH REAR <i>Not New</i> | 2 \$ 1,688.00         | +       |
| 21                   | SUNDRIES ?                                        | \$ 300.00             | ?       |
| TOTAL SPARE PARTS    |                                                   | : \$ 10,492.00        |         |
| TOTAL LABOUR CHARGES |                                                   | : \$ 10,512.00        |         |
| GRAND TOTAL          |                                                   | : <u>\$ 21,004.00</u> |         |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Adrian  
Surveyed Date : 01/03/18  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : Not Authorised, 08 Days.

## Please Note

: This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant