

VIC

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16/18 S(128236)

INSURANCE

Your Ref Vehicle No:
PC4033Z - TP

Date: 14/2/2018
Vehicle No: SJU3622G
Model: AVANTE
Date of loss: 14/2/2018
Our ref: LSA252TJS
Year: 2009

Qty	Description
1.00	BOOTLID
1.00	REAR BUMPER
10.00	REAR BUMPER CLIPS
1.00	REAR BUMPER RETAINER
1.00	REAR BUMPER BRACKET
1.00	END PANEL
1.00	RH REAR FENDER
1.00	RH TAILLAMP

List Price	Remarks
	REPAIR
\$ 849.70	86
\$ 30.00	11
\$ 60.9	121.80 (1pc)
\$ 44.20	188.40 (1pc)
	REPAIR
	REPAIR
\$ 451.80	740

TOTAL: \$ 1,641.70
LESS 20 %: \$ 328.34
\$ 1,313.36
1,486.6
297.32
1,189.28

S/NET

Qty	Description
1.00	REVERSE SENSOR

Unit Price	Remarks
\$ 250.00	200 ? 11
TOTAL: \$ 250.00	200

LABOUR AND PAINT

Qty	Description
1.00	LABOUR FOR REPAIR ON AFFECTED AREA
1.00	SPRAY PAINT ON AFFECTED AREA
1.00	CHECK WIRING
1.00	APPLY RUST PROOF ON AFFECTED PANEL
1.00	REMOVE & REFIT AFFECTED REAR TRIM TO FACILITATE REPAIR
1.00	TO REMOVE AND REFIT REVERSE SENSOR
1.00	SUNDARIES

Unit Price	Remarks
\$ 900.00	400
\$ 200.00	600
\$ 50.00	30
\$ 60.00	11
\$ 150.00	60
\$ 80.00	40
\$ 50.00	20
	1150

TOTAL: \$ 2,190.00
SUBTOTAL: \$ 3,753.36
Pats - \$1,189.28
S/N - \$200
lab - \$1,150

Estimate prepared by: WINSON

Telephone : 97684247

winsona@yahoo.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rahul
Hp 9000068
4 days
4/5
26/02/18 @ 1220
Resy after repair
Total - \$2,539.28
LS = \$2,000/-
4 days