

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 14/2/2018
Vehicle No: SJU3622G
Model: AVANTE
Date of loss: 14/2/2018
Our ref: LSA252TJS
Year: 2009

INSURANCE

Your Ref Vehicle No:
PC4033Z - TP

Qty	Description	List Price	Remarks
1.00	BOOTLID		REPAIR
1.00	REAR BUMPER	\$ 849.70	85
10.00	REAR BUMPER CLIPS	\$ 30.00	30
1.00	REAR BUMPER RETAINER	\$ 121.80	121.80 (1 pc)
1.00	REAR BUMPER BRACKET	\$ 188.40	188.40 (1 pc)
1.00	END PANEL		REPAIR
1.00	RH REAR FENDER		REPAIR
1.00	RH TAILLAMP	\$ 451.80	451.80

TOTAL: \$ 1,641.70
LESS 20 %: \$ 328.34
\$ 1,313.36

S/NET

Qty	Description	Unit Price	Remarks
1.00	REVERSE SENSOR	\$ 250.00	250.00 ?
TOTAL:		\$ 250.00	

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 900.00	900
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 900.00	900
1.00	CHECK WIRING	\$ 50.00	50
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 60.00	60
1.00	REMOVE & REFIT AFFECTED REAR TRIM TO FACILITATE REPAIR	\$ 150.00	150
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 80.00	80
1.00	SUNDARIES	\$ 50.00	50

TOTAL: \$ 2,190.00

SUBTOTAL: \$ 3,753.36

Estimate prepared by: WINSON

Telephone : 97684247

winsonls@yahoo.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90000068
4 days
4/3
26/02/18 @ 1220
Resy after repair