

INS. CASE OWNER:

NORSHAH

CC 3 / AIG1800

7076, R1 16/2/18

LKK:

IDAC:

Surveyor:

KASOL

DOI:

ASSIGNMENT

19/03/18

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKJ 1603X

Name of Insured:

UU LEE L100 SHARON

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

13/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LOO WEI LOON BRIAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

18687229054

Policy No.:

700372800

Make / Model:

DAIHATSU

Place of Accident:

TAMUN R9

OI GIA REPORT: YES / NO:

YES / NO

Insured Liability:

%

Final? Yes / No

SKU 238K



INSRS:

WSP:

Tel:

Liability:

RMKS:

performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
70/2/18	SKU 238K	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
23/02/18	PUE REVIEWED. OLD REAR-ENDED TP. SEND LETTER TO OI.	Call OI: 02/02/18 - PIC	
	EMAIL LIABILITY CLERK.	After call ltr to OI: 23/02/18 - VIC	
02/03/18 @ 3:20PM	SPOKE TO OI. HE CONFIRMED ACCIDENT DETAILS & REAR-ENDED TP. INFORMED TP CLAIM, AGREED TO SETTLE IN AMOUNT NCD LEAVES.	Documentation Check List: Handler	Typist
	FINALIZED	Notification ltr (if non-pickup)	
	ORIGINAL TP LOG IN.	After call ltr to OI	
24/03/18	CONFIRMED AMOUNT SAME AS LOG.	Authorisation To Act:	
	ALL DOCS IN ORDER.	Release Voucher:	
	TO CLOSE.	Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

RECEIVED 24 MAY 2018

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: P/P	SS 3,923.70 (3 days)	Reduction: 30 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 24/05/18	Confirm with: CAROLINE	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	27
Repair Cost: (w/loss)	SS 4,198.36		
Loss of Rental (LOR):	SS - (days)		
Loss of Use (LOU):	SS 300.00 x 3 (days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 4,500.36	Global Sum SS: -	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 4,200.36	Name 1:	PERFORMANCE MOTORS LIMITED
Payee 2: (Strike if N.A.)	SS 300.00	Name 2:	TAO YI-HOU LIMITED
Payee 3: (Strike if N.A.)	SS -	Name 3:	-

COPY SENT

24/5/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$520.00

Form

h

81871

INSURANCE

SKU 238R

2015 May

C

B.M.W 435I

2979

BLUE

30897

WBA 3R 120 30 F887805

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

C

Insured
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No
at Workshop no
Insured
Policy No
Claims No
Sum Insured
Excess
(Client's Record)
Make of Vch
(Policy Condition)
Remarks: The vch had commenced its repair at the time of inspection.
Date of Market Value
IDAC Accident Report
Consistent? Yes or No
GIA / PR Seen
Consistent? Yes or No
Est. Repairs
days
Res: Yes or No
Lump Sum
%
J Val Yes or No
CA / REV / REP / 24 HRS
Vehicle IN / OUT
Date
Person Contacted



Year Mo
Type of Vch
Truck / Trailer
Make
Color
Sp Reading
Eng No
G No
Gen Good / Good / Fair / Poor / Burnt
Steering in order / Jammed / Leaked / Burnt
Brake in order / Jammed / Leaked / Burnt
Mod Nil / S/Rim / STD / R/Rim
Tyre Size
F: 255/35 R19
R: 255/35 R19
BS / OUN / EXNOVA / GY / PS / LZA / MIC / OHTSU / PIR / SUMI
TOYO / YOKO
Front
R/Ral 6 mm
L/Ral 6 mm
D.O.A 13/02/18
Survey field at PERFORMANCE
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop, or
The UIC / Chassis frame / Body Structure affected due to collision

P/P \$3,923.70
CRAB: \$2,412.70 / 60%

1. Add New / Del Part
2. Final Report
3. Add New / Del Exhibit
4. Report Format
5. Lump Sum / M.C.C
Days Of Repair
Resurvey No. of Trip
Survey Fee
6. Add Fee
7. Add Fee
8. Add Fee
9. Add Fee
10. Add Fee
11. Add Fee
12. Add Fee
13. Add Fee
14. Add Fee
15. Add Fee
16. Add Fee
17. Add Fee
18. Add Fee
19. Add Fee
20. Add Fee
21. Add Fee
22. Add Fee
23. Add Fee
24. Add Fee
25. Add Fee
26. Add Fee
27. Add Fee
28. Add Fee
29. Add Fee
30. Add Fee
31. Add Fee
32. Add Fee
33. Add Fee
34. Add Fee
35. Add Fee
36. Add Fee
37. Add Fee
38. Add Fee
39. Add Fee
40. Add Fee
41. Add Fee
42. Add Fee
43. Add Fee
44. Add Fee
45. Add Fee
46. Add Fee
47. Add Fee
48. Add Fee
49. Add Fee
50. Add Fee
51. Add Fee
52. Add Fee
53. Add Fee
54. Add Fee
55. Add Fee
56. Add Fee
57. Add Fee
58. Add Fee
59. Add Fee
60. Add Fee
61. Add Fee
62. Add Fee
63. Add Fee
64. Add Fee
65. Add Fee
66. Add Fee
67. Add Fee
68. Add Fee
69. Add Fee
70. Add Fee
71. Add Fee
72. Add Fee
73. Add Fee
74. Add Fee
75. Add Fee
76. Add Fee
77. Add Fee
78. Add Fee
79. Add Fee
80. Add Fee
81. Add Fee
82. Add Fee
83. Add Fee
84. Add Fee
85. Add Fee
86. Add Fee
87. Add Fee
88. Add Fee
89. Add Fee
90. Add Fee
91. Add Fee
92. Add Fee
93. Add Fee
94. Add Fee
95. Add Fee
96. Add Fee
97. Add Fee
98. Add Fee
99. Add Fee
100. Add Fee




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18003076/hb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 15-02-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 1603X	Veh. Inspected	SKU 238R	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/02/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190933/930 (Motorrad)
Fax. 64796401 (AfterSales)
64796424 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

14 FEB 2018

Estimate No. : b1 45944
Date Estimated : 14/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Tao Yi-Hou Mildred
38 Bin Tong Park

Singapore 269819

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU238R	F887805	29/05/2015	435iA/2	0

DESCRIPTION

To replace rear bumper assembly & all attachments
cause by accident

850 ~~2,550.00~~

Painting on rear bumper assembly

934 ~~1,038.00~~

To check electrical wiring systems at the rear section
for proper function.

150 ~~177.00~~

Sundries.

hll

80 ~~90.00~~

Total Labour 1: 3,845.00

DESCRIPTION

TAILPIPE TRIM CHROME
RR BUMPER CARRIER ECE
REAR BUMPER CENTRE GUIDE
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
TRIM PANEL BUMPER REAR BOTTOM (ZWEI
REINFORCEMENT BUMPER REAR BOTTOM (M
FLAP TOWING EYE PRIMED (M)
REAR BUMPER PANEL PRIMED (M/PDC)
SET MOUNTS PDC SENSOR REAR (M)
RR RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE

QTY	PRIC	VALUE
2	99.65	199.30
1	432.90	432.90
1	55.40	55.40
1	48.10	48.10
1	48.10	48.10
1	212.50	212.50
1	80.25	80.25
1	42.20	42.20
1	1,264.30	1,264.30
1	62.95	62.95
1	35.20	35.20
4	5.05	20.20

Total Parts : 2,501.40

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401539W GST Reg. No. M2-0020081-X



309, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190889 (AfterSales)
Fax. 62449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190831/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45944
Date Estimated : 14/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU238R	F887805	29/05/2015	435iA/2	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 19/03/18 P1440 Claim No. _____

Date & Time 19/03/18 P1440 Excess \$5 _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010068 Authorized Yes / No _____

Authorized Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PM Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days

Labour 1	:	3,845.00
Parts	:	2,501.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	444.25
Grand Total	:	6,790.65

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

6,790.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45944
Date Estimated : 14/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Tao Yi-Hou Mildred
38 Bin Tong Park

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 269819

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKU238R	F887805	29/05/2015	435iA/2	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident		850.00		850.00
To spray paint rear bumper		934.00		934.00
To check electrical wiring systems at the rear section for proper function.		150.00		150.00
Sundries.		80.00		80.00

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
RR BUMPER CARRIER ECE	432.90	1.00		432.90
TRIM PANEL BUMPER REAR BOTTOM (ZWEI	212.50	1.00		212.50
REAR BUMPER PANEL PRIMED (M/PDC)	1,264.30	1.00		1,264.30

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,909.70
Total Labour & Parts :	3,923.70
Deduction for Excess :	
Total Repair Costs less Excess:	3,923.70
GST @7%:	274.66
Grand Total :	4,198.36

Vic (LKKAuto)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Tuesday, 15 May, 2018 6:37 PM
To: Rasul (LKKAuto); Vic (LKKAuto)
Subject: FINAL REPORT / SKU238R
Attachments: Final Report SKU238R.pdf

Dear Vic and Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour :2,014.00
Total Parts : 1,909.70
Total Labour & Parts : 3,923.70

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SKU 228 R	Model:	
Date of Accident:	13.2.2018		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	\$	6790.65	
Final Repair Cost	\$	4198.36	
Loss of Use	\$	300.00	3 days at \$100 per day
Rental (if any)	\$		days
LTA / GIA Search Fee	\$	2.00	
Others:	\$		
	\$		
Final Settlement Sum	\$	4500.36	

Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	\$	4198.36
2)	Performance Motors Ltd	\$	2.00
3)	Tao Yi-Hou Mildred	\$	300.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

23 FEBRUARY 2018

LIU LEE CHOO SHARON
BLOCK 411 EUNOS ROAD 5
#10-116
SINGAPORE 400411

Dear Sir/Madam,

OUR REF : CC3/AIG18003076/hb3
YOUR REF : SKJ 1603X
ACCIDENT INVOLVING SKJ 1603X AND SKU 238R ALONG TANGLIN ROAD ON
13.02.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SKU 238R against your motor insurance policy.

Based on the accident report, accident scenario and all available evidence and information at hand, it was reported that your vehicle had rear-ended to the Third-Party vehicle SKU 238R. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Tao Yi-Hou Mildred (the third party claimant) of 38 Bin Tong
Park Singapore 269819 (address), owner of SKU 238R (vehicle no.)
hereby authorize Performance Motors Limited ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SKU 238R that was damaged pursuant to the accident which occurred on 13/2/18
(date) along Tanglin Road towards Orchard Road (location) involving vehicle no/s
SKJ1603X ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.


I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 19 (day) of 07 (month) 2018 (year)

Mildred Indog

Signed by "the third party claimant"
(with chop if applicable)

PERFORMANCE MOTORS LIMITED
303 Alexandra Road
Singapore Performance Centre
Singapore 150041
TEL: 63190100 (Sales)
63199111 (AfterSales)


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 4198.36 (Repair Cost), S\$ 30.00 Loss of ~~rental~~/use), S\$ 2.00 (Disbursement), for vehicle no. SKU238R that was damaged pursuant to the accident which occurred on 13.2.18 (date) along TANGLIN ROAD (location) involving vehicle no/s SKS1603X. This is pursuant to the inspection conducted on 19.3.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tao Yi-Hou Mildred ("the third party claimant") of vehicle no. SKU238R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKU238R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 24 (day) of 03 (month) 2018 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

(vic)

SERVICE TAX INVOICE

Repair Order No. : B1 1252024

Date IN : 19/03/2018

Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 1 of 2

Invoice Number : 1966761 / WSB

Invoice Date : 21/05/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mdm Tao Yi-Hou Mildred
38 Bin Tong Park

Singapore 269819

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKU238R	F887805	29/05/2015	435IA/2	30896

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to
remove and install body parts in order to carry out painting
job.

To respray rear bumper.

To check electrical wiring systems at the rear section
for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR, DIRECT SETTLEMENT.

DATE OF ACCIDENT : 13.2.2018. 3RD PARTY CAR : SKJ1603X.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO
CONSULTANTS PTE LTD ON 19.3.2018 AT 2.40 PM.
AUTHORISED REPAIR BY MR VIC ALPEH FROM LKK ON
23.2.2018 VIA E-MAIL.

PROPOSE LOSS OF USE = \$100X3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

850.00

934.00

150.00

80.00

0.00

0.00

0.00

Total Labour 1: 2,014.00

- - - - PARTS - - - -

RR BUMPER CARRIER ECE

REAR BUMPER PANEL PRIMED (M/PDC)

TRIM PANEL BUMPER REAR BOTTOM (ZWEI)

Qty	Retail Price
1	432.90
1	1,264.30
1	212.50

NETT

432.90

1,264.30

212.50

Total Parts : 1,909.70

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 430180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64798601 (AfterSales)
64798624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. :	B1 1252024	Page No. :	2 of 2
Date IN :	19/03/2018	Invoice Number :	1966761 / WSB
Cust. Svc. Advisor:	Kevin Leong Wai Kit	Invoice Date :	21/05/2018
		Payment Terms :	30 Days From Invoice
		Invoice By :	Sharon Heng

Labour Charges :	1,934.00	Total Labour & Parts Charges :	S\$ 3,923.70
Parts Charges :	1,909.70	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 3,923.70
		GST @ 7% :	S\$ 274.66
		Invoice Total Amount Include GST :	S\$ 4,198.36

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 4,198.36**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-025052

Date of Request: 14/02/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 14/02/2018
Enquiry By Caroline Tan Shirui
TP Vehicle No. SKJ1603X
Accident Date 13/02/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKJ1603X	AIG Asia Pacific Insurance Pte. Ltd.	26/02/2017-25/02/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-025052

Date of Request: 14/02/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date: 14/02/2018
Enquiry By: Caroline Tan Shirui
TP Vehicle No: SKJ1603X
Accident Date: 13/02/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018 Edit Reg		19 Mar 2018 00:00 Edit Adj Rpt	S\$3,923.70 Edit Estimates	S\$3,923.70 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Liu Lee Choo Sharon, ID: S69419251								
Main Claimant:	TAO YI-HOU MILDRED, ID: S21581871								
Vehicle Reg. No.:	SKU238R	Date of Loss:	13/02/2018 15:00 - :59 [32 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1868772890SG	Policy/Cover Note No.:	2100332800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKJ1603X	Policy No. (Claimant):	P1621397						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 27/02/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU238R (1868772890SG)
[SKJ1603X]
TP
TAO YI-HOU MILDRED
Feb 13 2018 3:00PM
[Liu Lee Choo Sharon]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/02/18 09:52	Accident Statement <small>From: SC - Reg. No: SKJ1603X, Claimant: LIU LEE CHOO SHARON</small>		Load HTM
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 09:53	Odometer Reading		Load JPG
2	18/05/18 09:53	Chassis Number		Load JPG
3	18/05/18 09:54	General View		Load JPG
4	18/05/18 09:54	General View		Load JPG
5	18/05/18 09:54	General View		Load JPG
6	18/05/18 09:54	General View		Load JPG
7	18/05/18 09:54	General View		Load JPG
8	18/05/18 09:54	General View		Load JPG
9	18/05/18 09:54	General View		Load JPG
10	18/05/18 09:54	General View		Load JPG
11	18/05/18 09:54	General View		Load JPG
12	18/05/18 09:54	General View		Load JPG
13	18/05/18 09:54	General View		Load JPG
14	18/05/18 09:54	General View		Load JPG
15	18/05/18 09:54	General View		Load JPG
16	18/05/18 09:54	General View		Load JPG
17	18/05/18 09:54	General View		Load JPG
18	18/05/18 09:54	General View		Load JPG
19	18/05/18 09:54	General View		Load JPG
20	18/05/18 09:54	General View		Load JPG
21	18/05/18 09:54	Reinspection Photo		Load JPG
22	18/05/18 09:54	Reinspection Photo		Load JPG
23	18/05/18 09:54	Reinspection Photo		Load JPG
24	18/05/18 09:54	Reinspection Photo		Load JPG
25	18/05/18 09:54	Reinspection Photo		Load JPG
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/02/18 09:35	TP ESTIMATE		Load PDF
2	15/02/18 10:30	TP GIA REPORT		Load PDF
3	23/02/18 16:19	LETTER TO OI		Load PDF

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
4	20/03/18 18:49	TP ESTIMATE- MARKED		Load PDF
5	25/05/18 11:10	WORKSHOP INVOICE		Load PDF
6	25/05/18 11:10	AUTHORISATION TO ACT FORM		Load PDF
7	25/05/18 11:10	Release Voucher		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKJ1603X (Insd veh)	Model:	BMW 435i 3.0 COUPE M
	SKU238R (TP veh)		SPORT (F32) (A)
Date of Accident:	13/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	6,790.65	
Final Repair Cost	:	\$	4,198.36	
Loss of Use	:	\$	300.00	3.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	4,500.36	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 4,200.36
2)	Tao Yi-Hou Mildred	:	\$ 300.00
3)		:	\$

JOANNE LEE KHANG MIN

25 May
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18003076/R1HB3Q2

Date: 25/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100332800
Claimant Vehicle No : SKU238R **Insured Vehicle No :** SKJ1603X
 Date of Loss: 13/02/2018 Nature of Claim: TP Claim No: 1868772890SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU238R**
 Make & Model: BMW 435i, 3.0 Coupe M Sport (F32) (A) Engine No: 06469195N55B30A
 Reg. Date: 29/05/2015 (Man. Year: 2015) Chassis No: WBA3R12030F887805
 Colour: Blue Odometer: 30897 km
 Engine Capacity: 2979 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,581.40	1,989.70	591.70	22.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,765.00	1,934.00	1,831.00	48.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,346.40	3,923.70	2,422.70	38.17
+ GST 7.00/7.00% (S\$)	444.25	274.66	169.59	38.17
Nett Amount (S\$)	6,790.65	4,198.36	2,592.29	38.17
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,500.36		

INSPECTION

Date of Assignment: 19/03/2018
 Date Inspected: 19/03/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	2		*TAILPIPE TRIM CHROME	Serviceable	199.30 FS	*- FS
3	1		*RR BUMPER CARRIER ECE	Bent	432.90 FS	*432.90 FS
4	1		*REAR BUMPER CENTRE GUIDE	Serviceable	55.40 FS	*- FS
5	1		*RR BUMPER LH SIDE GUIDE	Serviceable	48.10 FS	*- FS
6	1		*RR BUMPER RH SIDE GUIDE	Serviceable	48.10 FS	*- FS
7	1		*TRIM PANEL BUMPER REAR BOTTOM (ZWEI)	Deformed	212.50 FS	*212.50 FS
8	1		*REINFORCEMENT BUMPER REAR BOTTOM (M)	Serviceable	80.25 FS	*- FS
9	1		*FLAP TOWING EYE PRIMED (M)	Serviceable	42.20 FS	*- FS
10	1		*REAR BUMPER PANEL PRIMED (M/PDC)	Deformed	1,264.30 FS	*1,264.30 FS
11	1		*SET MOUNTS PDC SENSOR REAR (M)	Not Necessary	62.95 FS	*- FS
12	1		*RR RH REFLECTOR	Serviceable	35.20 FS	*- FS
13	4		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **2,581.40** **1,989.70**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ASSEMBLY & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	2,550.00	850.00
2	PAINTING ON REAR BUMPER ASSEMBLY	New	1,038.00	934.00
3	TO CHECK ELECTIRCAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			3,765.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >