

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8048 E

1 pc	Bootlid cRdi ✓	\$ 29.00
1 pc	Bootlid emblem ✓	\$ 27.00
1 pc	Rear bumper ✓	\$ 696.00
1 pc	Rear bumper lower cover ✓	\$ 206.00
2 pcs	Rear bumper n/s & o/s side bracket @ \$29.00 ✓	\$ 58.00
1 pc	Rear bumper inner sponge ✓	\$ 114.00
1 pc	Rear bumper reinforcement ✓	\$ 607.00
2 pcs	Rear bumper n/s & o/s stay @ \$53.00 ✓	\$ 106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✓	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✓	\$ 36.00
1 pc	Rear muffler assy ✓	\$ 1,009.00
1 pc	Rear exhaust pipe hanger ✓	\$ 49.00
		\$ 2,973.00
	<i>Rear End Panel</i> ✓	
	Less 10%	\$ 297.30
		\$ 2,675.70

S/NETT

1 set	Rear bumper clips ✓	\$ 48.00
1 pc	Rear bumper top protector ✓	\$ 80.00 50
1 set	Reverse sensor ✓	\$ 280.00 200
1 set	Bootlid stickers ✓	\$ 100.00
	Sundry	\$ 50.00 20
	To dismantle / replace / test reverse sensor to new bumper and reset to the same	\$ 120.00 20
	To dismantle / replace exhaust pipe	\$ 120.00 50
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$ 1,000.00 600
	To putty and spray painting on rear bumper, bootlid, bootlid lower garnish, end panel	\$ 800.00 540
	To apply rustproofing on the repaired and replaced panels.	\$ 200.00 50
		\$ 5,653.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kah / CLK

14/2/18 1020h

4 Days

PP Before Panel pth