

INS. CASE OWNER:

CC 4/LPC1800 3084, U Wb3m2

LKK:

IDAC:

Surveyor:

MAROB

DOI:


01/02/18

Date / Time:

15/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFX 358X

Name of Insured:

YIEW MIN SEW

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A.:

12/01/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

DARREN NATHANIEL YIEW YUSTEN

Driver Tel No.:

(VA / YES / NO)

OI GIA REPORT: YES NO ; TP GIA REPORT: YES NO

Insured Liability:

%

Final ? Yes / No

SGA 340A



INSRS:

WSP:

Tel:

Liability:

RMKS:

progressive
(un)

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
15/1/18	SGA 340A - W	Non-Reporting ltr (1st):	
	SFX 358X - P	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
02/03/18	MUS KEBUKUHO. OLD REAR-ENDED TP.	Documentation Check List: Handler	Typist
	BUMIL LIABILITY CHECK.	Notification ltr (if non-pickup)	
	FINALISED.	After call ltr to OI:	
03/03/18	TYPE REPORT WHILE WAITING FOR TP LOD	Authorisation To Act:	
	REPORT DONE	Release Voucher:	
12/12/18	TP LOD IN BY BUMIL	Final Repair Bill:	
13/12/18	BOOK WARRANTS APPROVAL TO LPC	Car Rental Invoice:	
	LPC APPROVED WARRANTS.	Towing Invoice	
18/12/18	SEND ACCEPTANCE BUMIL TO TP.	LTA / GIA:	
	RECEIVED DV.	Medical Bill:	
	ALL DOCS IN ORDER.	PIR:	
	TO CLOSE.	Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: 02/03/18 Sent By: B2

FINALIZATION		Date/Time:	Confirm with:	Confirm by:
Repair Cost:	US	SS 2,350.00	(4 days) Reduction: 53 %	Email ☐ Call ☐
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost:	(with GST)	SS 2,728.50		
Loss of Rental (LOR):	SS	500.00	(5 days) X \$100.00	
Loss of Use (LOU):	SS	-	(\$ x days)	
Loss of Income (LOI):	SS	-	(\$ x days)	
LOR only ☐ LOU only ☐		LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS	2.00		
Medical:	SS	-		
Disbursement:	SS	-	(e.g. Tow/ Independent)	
Legal Cost	SS	-		
Total:	SS	3,260.50	Global Sum S\$:	-
FINAL PAYMENT		Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1:	SS	3,260.50	Name 1:	PROGRESSIVE AUTOMOTIVE PTB LTD
Payee 2. (Strike if N.A.)	SS	-	Name 2:	-
Payee 3. (Strike if N.A.)	SS	-	Name 3:	-

COPY SENT
15/1/181) Claim status: Normal/Reject/Private Settle
2) Report Format:
3) Survey fee: \$450.00

(08/11/13) waf

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGA 3496

at Workshop m/s PA 46.

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction 274 10153

Veh No: SGA 3496 Yr Regn: 4 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Mazda 3 SP G.C. 1598

Colour: S. Me A/C: Insured / Std / NI / NA

Sp. Reading: 113927 T/Radio: Insured / Std / NI / NA

Eng/No.

C/No: JM63K106280449593

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 205/55-210

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or

Front

Rear

R/Bal. 5- mm R/Bal. 5- mm

L/Bal. 5- mm L/Bal. 5- mm

D.O.A. 12/1/18 D.O.I. 1/3/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐
☐

Preli. Report

Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐
☐
☐
☐

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

L16 @ 2,550.00
 (CRSD: @ 2,845.40 (55%))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18003084/hb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 15-02-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFX 358X	Veh. Inspected	SGA 349C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/02/2018	Inspection Date		
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE L #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18003084/Uhb3

Date: 02.03.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGA349G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.03.2018 at the premises of M/s Progressive Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	5,395.40
Revised Estimate Amount	: S\$	3,476.60
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Nivitha (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Wednesday, 14 February 2018 12:51 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: Our Ref: 18/18/18/VP05/020404 Accident involving SFX358X & SGA349G along Braddell Rd on 12/2/18
Attachments: 14022018121624.pdf

1:50 pm @ 14/2/18
Wksp closed for CNY
Requirer will call back after CNY.

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SGA 349G on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2737B
Vehicle Details	
Vehicle No.:	SGA349G
Vehicle to be Exported:	No
Intended De-registration Date:	01 Mar 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SP
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	Z6760485
Chassis No.:	JM6BK106280449593
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$18,730.00
Original Registration Date:	01 Apr 2009
First Registration Date:	01 Apr 2009
Transfer Count:	0
Actual ARF Paid:	\$18,730.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2019
PARF Rebate Amount:	\$10,301.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$5,116.00
COE Rebate Amount:	\$552.00
Total Rebate Amount:	\$10,853.00

The information contained herein is correct as at 01 Mar 2018

OK

PARTS 1421.60

SN 615.00

LAB. 1174.00

3206.60

1/3 = 2550

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg

GST:201006949C RCB NO:201006949C

confirmed 23/3/18

not Affected
4/5 2530
4 day
Chye Ah Lee
repairM/S: SUSANNA KHOR SIEW SUAN
BLK 106 LENGKONG TIGA #06-313
SINGAPORE 410106Estimate No: EST1503304
Date: 13 Feb 2018
Policy No: 17-MY001836-R04
Veh Reg No: SGA349G
Make/Model: MAZDA MAZDA3 SP
Chassis No: JM6BK106280449593
Engine No: Z6760485
Reg. Date: 01/04/2009

ATTN: LONPAC

Your Ref No: TP 0218-4958

Claim Type: Third Party

Accident Date: 12/02/2018

TP Veh Reg No: SFX 358 X

TP 4958

Estimate Repair Cost to Vehicle No :SGA349G

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER	862.0000	1 PC	862.00	
2 REAR BUMPER CLIPS	5.0000	10 PC	50.00	
3 REAR BUMPER SIDE HOLDER - LH	41.0000	1 PCS	41.00	
4 REAR BUMPER SIDE HOLDER - RH	41.0000	1 PCS	41.00	
5 REAR BUMPER REINFORCEMENT	404.0000	1 PC	404.00	
6 REAR BUMPER REFLECTORS - LH	67.0000	1 PC	67.00	
7 REAR BUMPER REFLECTORS - RH	67.0000	1 PC	67.00	
8 REAR NUMBER PLATE LAMP ASSY	228.0000	1 PC	228.00	
9 REAR BOOT MAZDA WORDING	28.0000	1 PCS	28.00	
10 REAR BOOT 3 WORDING	22.0000	1 PCS	22.00	
11 REAR BOOT SP WORDING	12.0000	1 PCS	12.00	
12 REAR BOOT MAZDA LOGO	59.0000	1 PCS	59.00	
13 REAR PANEL	383.0000	1 PC	383.00	
14 REAR PANEL TOP GARNISH	142.0000	1 PCS	142.00	
			2,438.00	
		Less 20%	487.60	1,950.40

Special Net

15 REAR BUMPER SIDE SPOILER - LH	650.0000	1 PC	650.00	
16 REAR BUMPER SIDE SPOILER - RH	650.0000	1 PC	650.00	
17 REAR BUMPER SENSOR	220.0000	1 SET	220.00	
18 REAR NUMBER PLATE WITH CASING	35.0000	1 PC	35.00	
			1,555.00	1,555.00

Labour

19 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	
20 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	
21 TO CHECK WIRING	20.0000	1 JOB	20.00	
22 TO TRANSFER REAR BUMPER SENSOR	50.0000	1 JOB	50.00	
23 TO TUFF-KOTE	60.0000	1 JOB	60.00	
24 TO REMOVE, REFIX REAR GARNISH	80.0000	1 JOB	80.00	
25 TO REMOVE, REPAIR REAR EXHAUST PIPE	80.0000	1 JOB	80.00	
			1,890.00	1,890.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST 201006949C RCB NO 201006949C

M/S : SUSANNA KHOR SIEW SUAN
BLK 106 LENGKONG TIGA #06-313
SINGAPORE 410106

ATTN: LONPAC

Your Ref No: TP 0218-4958
Claim Type: Third Party
Accident Date: 12/02/2018
TP Veh Reg No: SFX 358 X

Estimate No: EST1503304
Date: 13 Feb 2018
Policy No: 17-MY001836-R04
Veh Reg No: SGA349G
Make/Model: MAZDA MAZDA3 SP
Chassis No: JM6BK106280449593
Engine No: Z6760485
Reg. Date: 01/04/2009

Estimate Repair Cost to Vehicle No :SGA349G

Description	U/Price	Quantity	Price SS	Amount SS
			Total	SS 5,395.40
			Add GST @ 7%	377.68
			Total Amount Payable	SS 5,773.08

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED SEVENTY THREE AND CENTS EIGHT ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST: 201006949C RCB NO: 201006949C

not Ahmed
2/5/18
4 Day
Cheng Ah
1/3/18

M/S : SUSANNA KHOR SIEW SUAN
BLK 106 LENGKONG TIGA #06-313
SINGAPORE 410106

Estimate No: EST1503304
Date: 13 Feb 2018
Policy No: 17-MY001836-R04
Veh Reg No: SGA349G
Make/Model: MAZDA MAZDA3 SP
Chassis No: JM6BK106280449593
Engine No: Z6760485
Reg. Date: 01/04/2009

ATTN: LONPAC
Your Ref No: TP 0218-4958
Claim Type: Third Party
Accident Date: 12/02/2018
TP Veh Reg No: SFX 358 X

Estimate Repair Cost to Vehicle No :SGA349G

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER <i>20/ae</i>	862.0000	1 PC	862.00	<i>✓</i>
2 REAR BUMPER CLIPS <i>re</i>	5.0000	10 PC	50.00	<i>✓</i>
3 REAR BUMPER SIDE HOLDER - LH <i>re</i>	41.0000	1 PCS	41.00	<i>✓</i>
4 REAR BUMPER SIDE HOLDER - RH <i>re</i>	41.0000	1 PCS	41.00	<i>✓</i>
5 REAR BUMPER REINFORCEMENT <i>re</i>	404.0000	1 PC	404.00	<i>✓</i>
6 REAR BUMPER REFLECTORS - LH <i>11</i>	67.0000	1 PC	67.00	<i>✓</i>
7 REAR BUMPER REFLECTORS - RH <i>11</i>	67.0000	1 PC	67.00	<i>✓</i>
8 REAR NUMBER PLATE LAMP ASSY <i>5/2</i>	228.0000	<i>1 PC 1 set</i>	228.00	<i>✓</i>
9 REAR BOOT MAZDA WORDING <i>re</i>	28.0000	1 PCS	28.00	<i>✓</i>
10 REAR BOOT 3 WORDING <i>re</i>	22.0000	1 PCS	22.00	<i>✓</i>
11 REAR BOOT SP WORDING <i>re</i>	42.0000	1 PCS	42.00	<i>✓</i>
12 REAR BOOT MAZDA LOGO <i>re</i>	59.0000	1 PCS	59.00	<i>✓</i>
13 REAR PANEL <i>re</i>	385.0000	1 PC	385.00	<i>✓</i>
14 REAR PANEL TOP GARNISH <i>re</i>	142.0000	1 PCS	142.00	<i>✓</i>
			2,438.00	
		Less 20%	487.60	1,950.40
Special Net				
15 REAR BUMPER SIDE SPOILER - LH <i>> 380 S.N</i>	650.0000	1 PC	650.00	<i>✓</i>
16 REAR BUMPER SIDE SPOILER - RH	650.0000	1 PC	650.00	<i>✓</i>
17 REAR BUMPER SENSOR <i>shel</i>	220.0000	1 SET	220.00	<i>200</i>
18 REAR NUMBER PLATE WITH CASING <i>set</i>	35.0000	1 PC	35.00	<i>✓</i>
			1,555.00	1,555.00
Labour				
19 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	<i>420</i>
20 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	<i>600</i>
21 TO CHECK WIRING	20.0000	1 JOB	20.00	<i>✓</i>
22 TO TRANSFER REAR BUMPER SENSOR	50.0000	1 JOB	50.00	<i>✓</i>
23 TO TUFF-KOTE	60.0000	1 JOB	60.00	<i>11 ✓</i>
24 TO REMOVE, REFIX REAR GARNISH	80.0000	1 JOB	80.00	<i>✓</i>
25 TO REMOVE, REPAIR REAR EXHAUST PIPE	80.0000	1 JOB	80.00	<i>11 ✓</i>
			1,890.00	1,890.00



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd
(Co. Reg. No. 201006949C)
Blk 3022A Ubi Road 1 #01-45/ 46 S408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg

Date : 14/12/2018

Our Ref: TP 0218-4958

Your Ref: 18/18/18/VP05/020404

Attention : Mr Vic Alpeh

LKK Auto Consultants Pte Ltd
Blk 51 Paya Ubi Industrial Park
Ubi Avenue 1 #02-25
Singapore 408933

Dear Sir

RE: ACCIDENT ON 12/02/2018 INVOLVING SGA 349 G & SFX 358 X


We refer to the above-mentioned.

We are pleased to return the duly signed Discharge Voucher for you to process payment of **\$3230.50** in favour of **PROGRESSIVE CAR CARE PTE LTD** and mail to our address at **Blk 3022A Ubi Road 1 #01-45/46 S(408716)**

Please note that it is a condition of any settlement reached that it shall be without Prejudice to any personal injury (if any) of the owner/claimant.

Thank you

Yours faithfully,


.....
Lily Lim



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18003084/Uhb3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 20-12-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFX 358X	Veh. Inspected	SGA 349G
Policy No.	Z18VP05016859	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020404	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3 SP (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JM6BK106280449593	Colour	SILVER
Odometer	113927	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/02/2018	Inspection Date	01/03/2018
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 349G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED / DEFORMED	862.00	862.00
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER SIDE HOLDER -LH	NECESSARY	41.00	41.00
1	REAR BUMPER SIDE HOLDER-RH	NECESSARY	41.00	41.00
1	REAR BUMPER REINFORCEMENT	DENTED	404.00	404.00
1	REAR BUMPER REFLECTORS -LH	NOT NECESSARY	67.00	-
1	REAR BUMPER REFLECTORS -RH	NOT NECESSARY	67.00	-
1	SET REAR NUMBER PLATE LAMP ASSY	BROKEN	228.00	228.00
1	REAR BOOT MAZDA WORDING	NECESSARY	28.00	28.00
1	REAR BOOT 3 WORDING	NECESSARY	22.00	22.00
1	REAR BOOT SP WORDING	NECESSARY	42.00	42.00
1	REAR BOOT MAZDA LOGO	NECESSARY	59.00	59.00
1	REAR PANEL	TO REPAIR SEE LABOUR	385.00	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	142.00	-
	LESS 20% DISCOUNT		-487.60	-355.40
			1,950.40	1,421.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER SIDE SPOILER -LH (SN) }	TORN	650.00	380.00
1	REAR BUMPER SIDE SPOILER -RH (SN) }	TORN	650.00	-
1	SET REAR BUMPER SENSOR (SN)	SHORTED	220.00	200.00
1	REAR NUMBER PLATE WITH CASING (SN)	BENT	35.00	35.00
			1,555.00	615.00
<u>LABOUR</u>				
	TO KNOCK OUT DENTS ,CUT/WELD REAR PANEL REMOVE REPLACE ACCIDENT PARTS .INCLUSIVE OF THE REPAIR OF REAR PANEL .		800.00	420.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		800.00	600.00
	TO CHECK WIRING .		20.00	20.00
	TO TRANSFER REAR BUMPER SENSOR .		50.00	50.00

Report Ref No. CC4/LPC18003084/Uhb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFF -KOTE .	NOT NECESSARY	60.00	-
	TO REMOVE REFIX REAR GARNISH .		80.00	80.00
	TO REMOVE,REPAIR REAR EXHAUST PIPE.	NOT NECESSARY	80.00	-
			1,890.00	1,170.00
	GRAND TOTAL		5,395.40	3,206.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,550.00

Report Ref No. CC4/LPC18003084/Uhb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.