

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

not Alvin
4 day
Chye Ah
1/3/18

M/S : SUSANNA KHOR SIEW SUAN
BLK 106 LENGKONG TIGA #06-313
SINGAPORE 410106

Estimate No: EST1503304
Date: 13 Feb 2018
Policy No: 17-MY001836-R04
Veh Reg No: SGA349G
Make/Model: MAZDA MAZDA3 SP
Chassis No: JM6BK106280449593
Engine No: Z6760485
Reg. Date: 01/04/2009

ATTN: LONPAC
Your Ref No: TP 0218-4958
Claim Type: Third Party
Accident Date: 12/02/2018
TP Veh Reg No: SFX 358 X

Estimate Repair Cost to Vehicle No :SGA349G

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BUMPER <i>no/ae</i>	862.0000	1 PC	862.00	<i>✓</i>
2 REAR BUMPER CLIPS <i>nr</i>	5.0000	10 PC	50.00	<i>✓</i>
3 REAR BUMPER SIDE HOLDER - LH <i>nr</i>	41.0000	1 PCS	41.00	<i>✓</i>
4 REAR BUMPER SIDE HOLDER - RH <i>nr</i>	41.0000	1 PCS	41.00	<i>✓</i>
5 REAR BUMPER REINFORCEMENT <i>nr</i>	404.0000	1 PC	404.00	<i>✓</i>
6 REAR BUMPER REFLECTORS - LH <i>11</i>	67.0000	1 PC	67.00	<i>✓</i>
7 REAR BUMPER REFLECTORS - RH <i>11</i>	67.0000	1 PC	67.00	<i>✓</i>
8 REAR NUMBER PLATE LAMP ASSY <i>5/2</i>	228.0000	<i>1 PC 1 set</i>	228.00	<i>✓</i>
9 REAR BOOT MAZDA WORDING <i>nr</i>	28.0000	1 PCS	28.00	<i>✓</i>
10 REAR BOOT 3 WORDING <i>nr</i>	22.0000	1 PCS	22.00	<i>✓</i>
11 REAR BOOT SP WORDING <i>nr</i>	42.0000	1 PCS	42.00	<i>✓</i>
12 REAR BOOT MAZDA LOGO <i>nr</i>	59.0000	1 PCS	59.00	<i>✓</i>
13 REAR PANEL <i>nr</i>	385.0000	1 PC	385.00	<i>✓</i>
14 REAR PANEL TOP GARNISH <i>nr</i>	142.0000	1 PCS	142.00	<i>✓</i>
			2,438.00	
	Less 20%		487.60	1,950.40
Special Net				
15 REAR BUMPER SIDE SPOILER - LH <i>> 3805.2</i>	650.0000	1 PC	650.00	<i>✓</i>
16 REAR BUMPER SIDE SPOILER - RH	650.0000	1 PC	650.00	<i>✓</i>
17 REAR BUMPER SENSOR <i>shw 6</i>	220.0000	1 SET	220.00	<i>200</i>
18 REAR NUMBER PLATE WITH CASING <i>set</i>	35.0000	1 PC	35.00	<i>✓</i>
			1,555.00	1,555.00
Labour				
19 TO KNOCK OUT DENTS, CUT/WELD REAR PANEL, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	<i>420</i>
20 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	<i>600</i>
21 TO CHECK WIRING	20.0000	1 JOB	20.00	<i>✓</i>
22 TO TRANSFER REAR BUMPER SENSOR	50.0000	1 JOB	50.00	<i>✓</i>
23 TO TUFF-KOTE	60.0000	1 JOB	60.00	<i>11</i>
24 TO REMOVE, REFIX REAR GARNISH	80.0000	1 JOB	80.00	<i>✓</i>
25 TO REMOVE, REPAIR REAR EXHAUST PIPE	80.0000	1 JOB	80.00	<i>11</i>
			1,890.00	1,890.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : SUSANNA KHOR SIEW SUAN
BLK 106 LENGKONG TIGA #06-313
SINGAPORE 410106

ATTN: LONPAC

Your Ref No: TP 0218-4958
Claim Type: Third Party
Accident Date: 12/02/2018
TP Veh Reg No: SFX 358 X

Estimate No: EST1503304
Date: 13 Feb 2018
Policy No: 17-MY001836-R04
Veh Reg No: SGA349G
Make/Model: MAZDA MAZDA3 SP
Chassis No: JM6BK106280449593
Engine No: Z6760485
Reg. Date: 01/04/2009

Estimate Repair Cost to Vehicle No :SGA349G

Description	U/Price	Quantity	Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	S\$ 5,395.40
			Add GST @ 7%	377.68
			Total Amount Payable	S\$ 5,773.08

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED SEVENTY THREE AND CENTS EIGHT ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: