

15/5/2010

INS. CASE OWNER:

Sharon

CC 3/CT118003087 1/k1j5/312

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

14/02/18

Date / Time:

14/02/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GY 1392Y

Name of Insured:

PRO-J RPD - CONDITIONING
ENGINEERING

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 13/02/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

CM1180090100V

Policy No.:

0M1K1M10183110V

Make / Model:

MG447

Place of Accident:

BT 870K EKT AVE 2 TMS 9066

If NO. Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SHC 7110J



INSRS:

WSP: CD43 (copy)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHC 7110J - NA/110802456/pl DOA: 02/01/18

STAGE

DATE / PIC

01/03/18 (joy)

*OI NR - SEND FIRST LETTER TO OI.

01 - 8482 4118 87500500

9008 - 4767 9008 4767

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

NA

204 16-3-18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

☒☒☒☒☒☒☒☒☒☒☒☒☒☒☒

PRELIMINARY ADVICE

Date/Time: 15/02/18

Sent By:

shirley How

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

28-3-18

Confirm with:

WILLIAM

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.: 27

Repair Cost:

SS

1,209.61

Loss of Rental (LOR):

SS

175.50

(S

x 15 days)

x 117

Loss of Use (LOU):

SS

(S

x

days)

Loss of Income (LOI):

SS

75

(S

50

x 15 days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LOU

☐

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1,467.60

Total:

SS

1,465

Global Sum SS:

1,465

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

1,465.xx

Name 1:

COMFORTDELGRU ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

x

Name 2:

x

Payee 3: (Strike if N.A.)

SS

x

Name 3:

x

COPY SENT

Surrey: Calvin

ASSIGNMENT

Veh No: SHC 7110 J Yr Regn: 4A, 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda 240 C.C. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading 339382 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB 44464035499

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

N/S	O/S

Tyre Size: F: 205/60/14 6

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Ken / Ken*

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 13/2/8 D.O.I. 14/2/8

Survey held at CAGE (boys)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rea.

The U/C / Chassis frame / Body Structure affected due to collision

[illegible]

677

P/P

$$R(\$1,331.10/54\%)$$

1-11-1971

Days Of Repair: _____

Resurvey No. of Trip: _____ Survey Fee: _____

Transportation: _____

Site Insp. (\$	S + RS	SI
----------------	--------	----

Site Insp	(S		
Intendaw	(S		

Interview (\$)	Photos
(\$)	

	Tech. Invs (\$	Others
--	----------------	--------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18003087/K1js3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 15-02-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 1392Y	Veh. Inspected	SHC 7110J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	15/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/02/2018	Inspection Date	14/02/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI18003087/K1js3

Date: 15/02/2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 7110J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.02.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	2,461.58
Revised Estimate Amount	: S\$	1,130.48
"Check" Items Amount	: S\$	845.40
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Remarks :

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Shirley Hiew (LKK Auto)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Monday, 19 February 2018 11:15 AM
To: Shirley Hiew (LKK Auto); Joy Irene (LKKAuto)
Cc: Adeline Chng; Vivian Lau (LKKAuto); Admin A; Sharon Han; Claims Dept of CTI
Subject: RE: Direct Settlement - Accident Involving GY1392Y (OI : CTI - TBA) AND SHC7110J (TP : LKK REF - CC3/CTI18003087/K1js3) on 13/02/2018
Attachments: SNM18D00901C02 20180219 TO LKK -ASSIGNMENT LTR -NON REPORTING.pdf

Dear Shirley/ Joy,

We refer to your email of 15th February 2018.

We attached a copy of our NON Reporting Letter for your necessary action.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Thursday, 15 February, 2018 11:23 AM
To: Claims Dept of CTI; Sharon Han; Joy Irene (LKKAuto)
Cc: Adeline Chng; Vivian Lau (LKKAuto); Admin A
Subject: Direct Settlement - Accident Involving GY1392Y (OI : CTI - TBA) AND SHC7110J (TP : LKK REF - CC3/CTI18003087/K1js3) on 13/02/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 7110J at M/s ComfortDelGro Engineering Pte Ltd - Loyang..

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D00901/C02/2**

Date: **19 FEBRUARY 2018**

via Ordinary & Registered Mail

**PRO-J AIR-CONDITIONING ENGINEERING
48 HILLVIEW TERRACE
#05-05 HILLVIEW BUILDING
SINGAPORE 669269**

Dear Sir / Madam

**ACCIDENT INVOLVING GY1392Y AND SHC7110J ON 13 FEBRUARY 2018
ALONG BUKIT BATOK EAST AVE 2 TOWARDS BUKIT BATOK EAST**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHC7110J**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of **our authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : JOY
Ref : (TP : LKK REF - CC3/CT118003087/K1js3)
Contact No : 6841 2409
via Email : Joylrene@lkkauto.com

CC : Agent - (AN0590A) - TECK WEI CREDIT PTE LTD

F02/LKKDSANR-2013



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC3/CTI18003087/K1js3

1st March 2018

PRO-J AIR-CONDITIONING ENGINEERING
48 HILLVIEW TERRACE
#05-05 HILLVIEW BUILDING
SINGAPORE 669269

Dear Sir / Madam,

ACCIDENT INVOLVING GY1392Y AND SHC7110J ON 13 FEBRUARY 2018
ALONG BUKIT BATOK EAST AVE 2 TOWARDS BUKIT BATOK EAST

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** to settle a **THIRD PARTY** claim against you for an accident which happened on the above-mentioned date and location.

Our record shows that to date, you/your driver have not reported the accident to us. We would appreciate it if you could urgently file a report at any of **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** Authorized workshops/reporting centre. You may refer to your Certificate of Insurance for the list of the reporting centre.

Please note you had been notified via post from **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** dated 19th February 2018.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter (by 26th February 2018).

Please be reminded that in accordance with the terms and conditions under your policy, failure of compliance, our principal M/s **CHINA TAIPING INSURANCE SINGAPORE PTE LTD** reserves the right to repudiate liability.

If you need further assistance or clarifications, please contact the undersigned.

Yours faithfully,

Joy
Case Handler
DID: 6841 2409
FAX: 6741 4108
Email: JoyIrene@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO: 305116567

OWNER CITYCAB PTE LTD IS 7010070 OWNER NO 383 SIN MING DRIVE TESS Singapore SINGAPORE 575717 65551188 (R) (P)	REGN NO SHC7110J MAKE HYUNDAI MODEL I-40 YR OF MANU 04.03.2016 CHASSIS CODE KMHLB41UMGU085499	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 13.02.2018 14:40 TARGET DATE COMPLETION DATE/TIME
---	--	---

JUNT CARD NO.

JOB DESCRIPTION

ccident Date: 13.02.2018
ATURE: 3P 13.02.18

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

CKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHC7110J JU CHINA LKK

Vehicle No.: SHC7110J

Signature/Date

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

MAKE :

DATE 13/2/2018 15:00

Jumani

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper i40 Plate ✓			\$ 50.00
				\$ 185.70
	Labour Charge			200
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,461.58
	Kalish (KK)			
	M 14/2/8 1115L			
	2 Pys			
	P/P			
	Before P.H plate			
	LKK Auto Centre is hereby notify the Repairer of the following: • To resurvey before spray painting • To display damage during resurvey • Parts prices are subject to confirmation • Third party survey on a "Without prejudice" basis • No illegal practices shall be allowed • Supplementary items may be surveyed and is subject to final approval by insurance Company Acknowledged by Repairer Signature: Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7110J

DATE 13/2/2018 15:00

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper — <i>Rebuilt</i>			\$ 603.60	
	Rear Bumper Reinforcement <i>X</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X</i>		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket <i>X</i>			\$ 49.00	
	Rear Bumper Clips — <i>new</i>			\$ 22.00	
	Rear Bumper Sponge <i>X</i>			\$ 143.40	
	Rear Bumper Under Cover — <i>new</i>			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70	Nett
	Rear Bumper i40 Plate — <i>new</i>			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge			200	
	Panel Beating			\$ 380.00	
	Spray Painting Charge			\$ 200.00	180
	Wiring Charge			\$ 50.00	X 22
	R/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,461.58	
	<i>Ka hui (KK)</i>				
	<i>14/2/18 1115L</i>				
	<i>2 P's</i>				
	<i>PIP</i>				
	<i>Before P.H. ph</i>				
	<div> <p>LKK Auto Consultants hence notify the Repairer of the following</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey on a "without prejudice" basis • No illegal modification is allowed • Supplementary items must be approved and is subject to prior approval from the Insurance Company <p>Acknowledged by Repairer</p> <p>Signature</p> <p>Date</p> </div>				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305116567
Date : 15/02/2018

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SHC7110J

Fax :
Date of Accident : 13/02/2018

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: CHINA --- GY 1392Y
###
- The finalized amount shall be:
(a) Spare Parts after List discount \$ 730.48
(b) Labour Charges ### \$ 400.00
Total for Part-By-Part Repair Cost \$ 1130.48
(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

- Estimated normal period for repairs: 2 working days
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature :
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature :
Name :
Date : 15/2/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

CHECK ITEMS:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI18003087/K1jb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-04-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GY 1392Y	Veh. Inspected	SHC 7110J
Policy No.	DMCVSN3018301700	Coverage (\$)	0.00
Claim No.	SNM18D00901/C02/2	Excess (\$)	0.00
Assign From		Assign Date	14/02/2018
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU085499	Colour	YELLOW
Odometer	339382	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/02/2018	Inspection Date	14/02/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7110J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	603.60	603.60
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	-
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	-
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	49.00	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	-
1	REAR BUMPER UNDER COVER	CUT	225.00	225.00
	LESS 20% DISCOUNT		-381.47	-170.12
			1,525.88	680.48
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR BUMPER I40 PLATE (SN)	NECESSARY	50.00	50.00
			185.70	50.00
<u>LABOUR</u>				
	PANEL BEATING.		380.00	200.00
	SPRAY PAINTING CHARGE.		200.00	180.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	R/REFIX REVERSE SENSOR.		120.00	20.00
			750.00	400.00
GRAND TOTAL			2,461.58	1,130.48
RECOMMENDED COST OF REPAIRS				1,130.48

Report Ref No. CC3/CT118003087/K1jb3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.