

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7110J

DATE 13/2/2018 15:00 Jumani

MAKE :

MODEL : HYUNDAI i40

MODEL	: HYUNDAI i40			
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper i40 Plate ✓			\$ 50.00
				\$ 185.70
	Labour Charge			200
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 2,461.58
	K. Loh'1 (KK)			
	M 14/2/8 1115L			
	2 PIP			
	P/P			
	Before Paint plan			
	LKK Auto Co. is hence notify the Repairer of the following: • To resurvey before painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party surveying on a "Without Prejudice" basis • No illegal practices shall be allowed • Supplementary details shall be resurveyed and is subject to final approval from insurance Company			
	Acknowledged by Repairer Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			