

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0626/2018
DATE : 10-FEB-2018

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 63387288
FAX : 68804838/ 3382522
MS LINA EXT: 824

OWNER'S NAME : GOH YU SHEN
ADDRESS : BLK 21 HOLLAND DRIVE
#03-415
S(271021)
TELEPHONE NO : 90701628

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100324471-05
VEHICLE NO : SKB5521P
MODEL CODE : SH9AK9T
MODEL/YEAR : FORESTER 2.5XT
ENGINE NO : EJ25D503053
CHASSIS NO : JF1SH9KT59G009498(*)
MILEAGE : 1 KM
DATE IN : 10/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 09/02/2018

Print Date : 10/02/2018
Print Time : 12:13:14

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKB5521P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AXA LOC:PIE TOWARDS CHANGI BEFORE TOA PAYOH LORONG 6 EXIT DATE:09/02/18 TIME:1530H		
3	ZZ/002	CONDUCT REAR BUMPER,PANEL,TAILGATE,REAR LH&RH FENDER	2800.00	
4	ZZ/003	RESPRAY REAR BUMPER,PANEL,TAILGATE,REAR LH&RH FENDER	2100.00	
5	ZZ/004	DISMENTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	300.00	
6	ZZ/005	REMOVE AND REFIX EXHAUST	150.00	
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	
8	ZZ/007	TRANSFER(TAILGATE)MECHANISM	150.00	
9	ZZ/008	REMOVE&INSTALL(REAR)WINDSCREEN	300.00	
10	ZZ/009	TO REMOVE&REFIX FUEL TANK	200.00	
11	ZZ/011	TO SUPPLY&INSTALL REVERSE SENSOR-2 EYES	300.00	
12	ZZ/012	SUNDRIES	100.00	
13	ZZ/10	TO CONDUCT(REAR)LIGHTING TEST	50.00	
		TOTAL LABOUR CHARGES	6550.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKB5521P

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
					S/LIST REMARKS
1	DISC WHEEL 17"	28111SC040	850.00		
2	REAR TAIL PIPE CUTTER	44370FG001	72.00		
3	REAR QTR PNL RH	51439SC0409P	864.00		
4	LH REAR FENDER	51439SC0509P	864.00		
5	FLOOR PAN RR 4D	52122FG0719P	370.80		
6	END PANEL	52401SC0119P	288.00		
7	BUMPER FACE REAR	57704SC010	432.00		
8	REAR BUMPER BEAM	57711FG0109P	208.80		
9	COVER HOOK R	57731SC050MD	14.40		
10	TAILGATE	60809SC0009P	1072.80		
11	TAILGATE GLASS	63019SC000	799.20		
12	REAR TAILGATE LOCK MECHANISM	63032FG111	176.40		
13	REAR WINDSCREEN DAM RUBBER (2PCS)	63232SC000	7.20		
14	MOULDING REAR WINDSCREEN	63232SC010	14.40		
15	REAR TAILGATE WEATHERSTRIP	63516SC000	126.60		
16	REFLEX AY RH	84281SC000	20.40		
17	REFLEX AY LH	84281SC010	20.40		
18	REAR TAILLAMP ASSY RH	84912SC101	438.60		
19	LH TAIL LAMP	84912SC111	438.60		
20	LABEL TAILGATE	91572SC000	14.40		
21	LETTER MK FORESTER	93073SC000	44.20		
22	LETTER MK SUBARU	93073SC010	43.20		
SUB TOTAL			7180.40	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1436.08	0.00	0.00
GRAND TOTAL			5744.32	0.00	0.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKB5521P

			DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
OVERALL TOTAL			5744.32				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKB5521P

TOTAL LABOUR CHARGES 6550.00
TOTAL SPARE PARTS CHARGES 5744.32

GRAND TOTAL 12294.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.