



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLG8540B
Chassis No : JHMGK5850HX200275
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : LOH WAI MENG
Ins Policy No. :
Date of Accident : 23/1/2018

Document No. : SQT18000354
Date : 23. Jan 2018
Customer No. : WZA006
Svc Advisor : PATRICK MOK LIP KAY
Engine No : L15B31190169
Date | Time : 23. Jan 2018 6:03:30 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LOH WEI MENG OWNER INSURER: LIBERTY INSURANCE ACC DATE: 23/01/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: PC2274H						
BOSUN	SUNDRIES	1 ³⁰	50.00		50.00	3.50	53.50
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1 ¹⁴⁰⁰	1500.00	20	1200.00	84.00	1284.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1 [✓]	80.00	20	64.00	4.48	68.48
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1 ¹¹²⁵	1200.00	20	960.00	67.20	1027.20
Sum Labor					<u>2274.00</u>	<u>159.18</u>	<u>2,433.18</u>
60261-T5R-A00ZZ	PANELL.FR.FENDER	1 ^{bt}	390.80	35	254.02	17.78	271.80
60690-T5A-300ZZ	BRACKET COMP,L.FR.FENDER	1 [?]	40.90	35	26.58	1.86	28.44
67050-T5A-N10ZZ	PANEL COMP,L.FR.DOOR	1 ^X	757.20	35	492.18	34.45	526.63
67364-T5A-003	TAPE SETL.FR.DOOR	1 ^X	32.90	35	21.38	1.50	22.88
76251-T5A-J31ZF	CAPL.SKULL	1 ^{cut ✓}	50.90	35	33.08	2.32	35.40
76258-T5A-J32	MIRROR ASSY,L.	1 ^{cut ✓}	496.60	35	322.79	22.60	345.39
73350-T5A-T40	GLASS ASSYL.FR.DOOR	1 ^X	344.20	35	223.73	15.66	239.39
Sum Item					<u>1373.76</u>	<u>96.17</u>	<u>1,469.93</u>

Survey By

Tan Jia 97495749

Date & Time

15/3/18

Excess

WP

Status

5 days

Resurvey before paint
sur@lkkauto.com

Total Amount 3,647.76 255.35 3,903.11

LKK Auto Total (Inclusive of GST)
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3,903.11