

15/5/2010

INS. CASE OWNER:

Stacey

CC @ ASA 1800 3096, G 203 52

LKK:
IDAC:

Surveyor:

XGQ

DOI:

ASSIGNMENT

24/7/18

Date / Time :

15/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SJT 584H

Claim No. :

88MOU90F 1 3037

Name of Insured :

BUTLER III BYRON THOMAS

Policy No. :

CN 809326

Insured Tel No. :

HP:

96431746

Make / Model :

MINI COOPER

Excess Sec II : \$\$

D.O.A. :

13/2/18

Place of Accident :

SIMS ARE JUST PASS THE FUNDS.

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability : % Final ? Yes / No

SCENARIO



INSRS:
WSP:
Tel:
Liability:
RMKS:

kn motor



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
24/7/18	SCENARIO - 4	Non-Reporting ltr (1st):	
	#Smartclaim	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
28/7/18	Email to TP. unclear. Request for evidence	Documentation Check List:	
5/8/18	NO response from TP.	Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/>
		Authorisation To Act:	<input type="checkbox"/>
		Release Voucher:	<input type="checkbox"/>
		Final Repair Bill:	<input type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/>
		LOD	<input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>
07-05-18	TO REJECT TP CLAIM BASED ON DAMAGE PROFILE & ACCIDENT SCENARIO.		
11/6/19	File -> shu per to close		

PRELIMINARY ADVICE	Date/Time:	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	\$\$	(days) Reduction:	% Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	\$\$		
Loss of Rental (LOR):	\$\$	(days)	
Loss of Use (LOU):	\$\$	(\$ x days)	
Loss of Income (LOI):	\$\$	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search	SS		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/ Independent)	1) Claim status: Normal/Reject/Private Settle (MP)
Legal Cost	SS		2) Report Format: TP #250W
			3) Survey fee:
Total:	SS	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS	Name 1:	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT 14/6/19

Yed.

ASM

P

ASSIGNMENT

Ref: _____ Date: 22/02/18

Estimated Cost: _____

OD: TP RES / OD RES / EVA / INV / MV

To: (Agent / Employer) SCE 899L
Kah Motor
15 Ubi Road 4

Make of car: _____

Model: _____

Sum Insured: _____ Excess: _____

Client's Record: 10-30 am @ owner waiting

Make of car: Mr-tiew

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Salvage / Market Value: \$90k

DAC Accident Report: _____ Consistent? : Yes or No


GIA / PP / Seen: _____ Consistent? : Yes or No

Est. Repair: 6 days Res: Yes or No

W/L / Sum: JBI Res: Yes or No

CA / REV / REP. / 24 HRS 'wp

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Car No: SCE 899L Date: 29 Sep 2016

Make: Honda Civic Reg: ~~1597~~

Colour: purple

Bo Reading: 93837

Eng No: _____

CNG: ~~MRH~~ MRHFC56506T000354

Gen Cond: D / Fair / Poor / Burnt

Steering: Jammed / Leaked / Burnt or

Brake: Jammed / Leaked / Burnt or

Mod: Nil STD / RIM or

Tyre Size: F: 215/55 R16
R: 11

BS / DUN / EKNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or: Hankook

Front	---	Rear	---
R/Sa	7	R/Sa	7
L/Sa	7	L/Sa	7

D/OA: _____ Date: 22-02-18. 10:30AM

Survey Report: W/S

Date of Damages: Front / Rear / OS NS LIC / Roof/door

The Chassis/frame / Body Structure affected due to collision

Plp ~~\$~~ \$5,305.84 (Rat ~~\$~~ \$1,668.76 / 23.93%)

Date/Time File Pass: Prel. Report Final Report

Date/Time File Return: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Surveys Fee: _____

Add Fee: Site Fee \$ _____
 Traffic \$ _____
 Test \$ _____
 Transport \$ _____

Receipt Printed: _____

Signature: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18003096/pb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 15-02-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 584H	Veh. Inspected	SCE 899L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/02/2018	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

LKK.

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SCE899L

Chassis No : MRHFC5650GT000354

Model : CIVIC 1.6 VTI YM2016

Owner's Name : LEE MAH CHUAN

Ins Policy No. :

Date of Accident : 13/2/2018

Document No. : SQT18000702 Page 1

Date : 14. Feb 2018

Customer No. : WZA006

Svc Advisor : LIEW THYE WEI

Engine No : R16B21600474

Date | Time : 14. Feb 2018 6:00:53 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LEE MAH CHUAN OWNER INSURER: TOKIO MARINE ACC DATE: 13/2/18 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SJT584H						
71500-TEC-Q00ZZ	FACE ASSYRR.BUMPER <i>/ DE</i>	1	617.20	35	401.18	28.08	429.26
71502-TEX-Y00	GARNISHRR.BUMPER LOWER <i>/ SCR DE</i>	1	35.30	35	22.94	1.61	24.55
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>/</i>	1	2.20	35	1.43	0.10	1.53
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>/ M.C.</i>	1	2.20	35	1.43	0.10	1.53
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>/</i>	1	11.50	35	7.47	0.52	7.99
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>/</i>	1	11.50	35	7.47	0.52	7.99
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE <i>/ X NN</i>	1	7.60	35	4.94	0.35	5.29
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE <i>/ SCR</i>	1	7.60	35	4.94	0.35	5.29
39680-TEX-Y41ZT	SENSOR ASSYPARKING <i>/ M's</i>	4	79.80	35	207.48	14.52	222.00
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS <i>/ M.C.</i>	1	27.20	35	17.68	1.24	18.92
74592-TEA-T00	FENDERL.RR.INNER <i>/ TNV</i>	1	61.20	35	39.78	2.78	42.56
91501-TR0-003	CLIPINNER FENDER <i>/ M.C.</i>	7	2.30	35	10.46	0.73	11.19
71850-TEA-T01ZB	GARNISH ASSYL.SIDE SILL <i>/ Cut</i>	1	114.40	35	74.36	5.21	79.57
91505-TM8-003	CLIPBUMPER <i>/ M.C.</i>	9	2.00	35	11.70	0.82	12.52
33550-TEA-T01	TAILLIGHT ASSYL. <i>/ SCR</i>	1	273.10	35	177.51	12.43	189.94
67550-TEA-T00ZZ	PANELL.RR.DOOR <i>/ BT</i>	1	696.60	35	452.79	31.70	484.49
72965-TBA-A01	MOLDING ASSYL.RR.DOOR SASH <i>/ M.C.</i>	1	28.30	35	18.39	1.29	19.68
72950-TEA-T01	MOLDING ASSY.L.RR.DOOR <i>/</i>	1	24.50	35	15.92	1.11	17.03
42700-TEA-T61	DISKALUMINIUM WHEEL <i>/ Cut</i>	1	289.10	35	187.91	13.15	201.06
42200-TBA-A02	BEARING ASSYRR.HUB UNIT <i>/ ? X'm</i>	1	155.70	35	101.20	7.08	108.28
52215-TBA-A00	KNUCKLE COMPL.RR. <i>/ ? Y'm</i>	1	148.70	35	96.65	6.77	103.42



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SCE899L
Chassis No : MRHFC5650GT000354
Model : CIVIC 1.6 VTI YM2016
Owner's Name : LEE MAH CHUAN
Ins Policy No. :
Date of Accident : 13/2/2018

Document No. : SQT18000702 **Page** 2
Date : 14. Feb 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : R16B21600474
Date | Time : 14. Feb 2018 6:00:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
52355-TEA-T00	ARM COMP BL.RR.LOWER ? Xnn	1	59.80	35	38.87	2.72	41.59
52365-TEA-T00	ARM COMPL.RR.TRAILING ? Xnn	1	39.90	35	25.93	1.82	27.75
52510-TEA-T00	ARM COMPRR.UPPER ? Xnn	1	69.50	35	45.17	3.16	48.33
Sum Item					1973.60	138.16	2,111.76
BO-WHEEL ALIGN X4 WHEEL ALIGNMENT		1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60
BOSUN	SUNDRIES n.e.a		30.00		30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	320.00		320.00	22.40	342.40
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	350.00		350.00	24.50	374.50
BMU21R	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS. (N)	1	540.00		540.00	37.80	577.80
BKFE21K	STRAIGHTEN ALIGN RR L FENDER, RR PANEL & L/FRT DR. (450)	1	1500.00		1500.00	105.00	1605.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2000.00		2000.00	140.00	2140.00
Sum Labor					4820.00	337.40	5,157.40

Survey By: Lim Kiang - 82880282
Date & Time: 22/2/18
Excess: _____
Status: 60 days.
Signature: _____
before paint photos.

Total Amount 6,973.60 488.16 7,461.76
Total (Inclusive of GST) 7,461.76

Printed on 14/2/2018 6:42:37 PM

This is a computer generated invoice. No signature is required.
Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.
GST Amount is calculated from individual line(s)

Customer/Insurer must hence notify the repairer of the following:
• Resurvey only after spray painting
• To repair damaged part(s) during resurvey
• Part prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 28 February 2018 8:46 AM
To: Liew Thye Wui
Cc: Admin A; Zaini (LKK Auto)
Subject: RE: SCE 899L / SJT 584H ; TP ; WP ; AXA ; D.O.A: 13/02/2018 *LKK REF: CC4/ASM18003096/Gpb3
Attachments: Statement of SJT 584H.pdf

Without Prejudice

Hi Sirs,

We refer to the above matter.

Please be informed that liability is unclear as our insured driver reported that your client cut into his lane and resulted the accident. Attached here with a copy of our insured driver accident report for your easy reference.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) in order for us to look into the matter.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Liew Thye Wui [<mailto:twliew@honda.com.sg>]
Sent: Monday, 19 February 2018 5:39 PM
To: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Subject: RE: SCE 899L / SJT 584H ; TP ; WP ; AXA ; D.O.A: 13/02/2018

Dear Nivitha,

Vehicle not in, I unable to reach owner. Can we have a direct settlement on this case?
Hope to receive your reply soon.

Thank you and have a Nice Day.

Best Regards

TW LIEW
Kah Motor Co. Sdn. Bhd.
15 Ubi Road 4
Singapore 408610
DID: 6514 5687
Fax: 6748 0770

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Monday, 19 February, 2018 5:28 PM
To: Liew Thye Wui <twliew@honda.com.sg>
Subject: SCE 899L / SJT 584H ; TP ; WP ; AXA ; D.O.A: 13/02/2018

Dear, Mr.Liew,

Is the vehicle SCE 899L in the workshop?

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

<< **<Seek Approval to Reject TP claim> - S8M0090F
[ACCIDENT INVOLVING SJT 584H(OI) & SCE 899L(TP)
ON 13/02/2018]**

Type

 Question

Message

Hi, we have reviewed the matter. Based on both parties report and damage profile, it seems like third party swerved to left and hit onto the right front portion of OI vehicle. The bumper of OI vehicle was peeled off. In view of this, we are intending to reject third party claim. For your approval/comments please. Hsiao Tong - 08/05/2018

Reply



**RE: <Seek Approval to Reject TP claim> - S8M0090F
[ACCIDENT INVOLVING SJT 584H(OI) & SCE 899L(TP) ON
13/02/2018]**

Type

🗉 Question

Message

Hi, We refer to the E-mail below. We appreciate if you could let us have your comments / instruction. Poh Kin -
04/06/2018

Reply

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Monday, 2 July 2018 10:47 AM
To: Hsiao Tong (LKKAuto)
Cc: Admin A
Subject: RE: New message for service request 31037, vehicle number SCE899L

◀ Re:RE: <Seek Approval to Reject TP claim> - S8M0090F [ACCIDEN
SCE 899L(TP) ON 13/02/2018]

Type

Information

Message

TP converted to OD claim. Please submit wp report

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto)
Sent: Monday, 2 July 2018 10:30 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 31037, vehicle number SCE899L

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue
1, #02-25 | S(408933)

-----Original Message-----

From: stacey.ng@axa.com.sg [mailto:stacey.ng@axa.com.sg]
Sent: Monday, 2 July 2018 10:28 AM
To: admin-d@lkkauto.com
Subject: New message for service request 31037, vehicle number SCE899L

AXA Insurance has sent you a message for claim number S8M0090F.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been checked for viruses by AVG.
<https://www.avg.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18003096/Gfb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 18-06-2019



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJT 584H	Veh. Inspected	SCE 899L
Policy No.	CN809395	Coverage (\$)	0.00
Claim No.	S8M0090F	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHFC5650GT000354	Colour	PURPLE
Odometer	013837	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R16	HANKOOK	7 mm
L/H Front Tyre	215/55R16	HANKOOK	7 mm
R/H Rear Tyre	215/55R16	HANKOOK	7 mm
L/H Rear Tyre	215/55R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/02/2018	Inspection Date	22/02/2018
Survey held at	15 UBI ROAD 4		
Repairer	KAH MOTOR CO SDN BERHAD		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCE 899L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FACE ASSYRR.BUMPER (SN) (CONSISTENT)	DEFORMED	401.18	401.18
1	GARNISHRR.BUMPER LOWER (SN) (CONSISTENT)	DEFORMED	22.94	22.94
1	BRACKETR.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	1.43	1.43
1	BRACKETL.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	1.43	1.43
1	SPACERR.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	7.47	7.47
1	SPACERL.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	7.47	7.47
1	GARNISHR.RR.BUMPER SIDE (SN) (CONSISTENT)	NOT NECESSARY	4.94	-
1	GARNISHL.RR.BUMPER SIDE (SN) (CONSISTENT)	SCRATCHED	4.94	4.94
4	SENSOR ASSYPARKING (SN) (CONSISTENT)	MISSING	207.48	207.48
1	SUB CORDRR.BUMPER CORNER SENS (SN) (CONSISTENT)	NECESSARY	17.68	17.68
1	FENDERL.RR.INNER (SN) (CONSISTENT)	TORN	39.78	39.78
7	CLIPINNER FENDER (SN) (CONSISTENT)	NECESSARY	10.46	10.46
1	GARNISH ASSYL.SIDE SILL (SN) (CONSISTENT)	CUT	74.36	74.36
9	CLIPBUMPER (SN) (CONSISTENT)	NECESSARY	11.70	11.70
1	TAILLIGHT ASSYL. (SN) (CONSISTENT)	SCRATCHED	177.51	177.51
1	PANELL.RR.DOOR (SN) (CONSISTENT)	BENT	452.79	452.79
1	MOLDING ASSYL.RR.DOOR SASH (SN) (CONSISTENT)	NECESSARY	18.39	18.39
1	MOLDING ASSY,L.RR.DOOR (SN) (CONSISTENT)	NECESSARY	15.92	15.92
1	DISKALUMINIUM WHEEL (SN) (CONSISTENT)	CUT	187.91	187.91
1	BEARING ASSYRR.HUB UNIT (SN) (CONSISTENT)	NOT NECESSARY	101.20	-
1	KNUCKLE COMPL.RR. (SN) (CONSISTENT)	NOT NECESSARY	96.65	-
1	ARM COMP BL.RR.LOWER (SN) (CONSISTENT)	NOT NECESSARY	38.87	-
1	ARM COMPL.RR.TRAILING (SN) (CONSISTENT)	NOT NECESSARY	25.93	-
1	ARM COMPRR.UPPER (SN) (CONSISTENT)	NOT NECESSARY	45.17	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	30.00	10.00
			2,003.60	1,670.84
<u>LABOUR</u>				
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		80.00	80.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK		320.00	150.00

Report Ref No. CC4/ASM18003096/Gfb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST.	NOT NECESSARY	350.00	350.00
	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS.		540.00	-
	STRAIGHTEN ALIGN RR L FENDER, RR PANEL & L/FRT DR.		1,500.00	1,125.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,000.00	1,750.00
	WHEEL ALIGNMENT.		180.00	180.00
			4,970.00	3,635.00
	GRAND TOTAL		6,973.60	5,305.84
	RECOMMENDED COST OF REPAIRS			5,305.84

Report Ref No. CC4/ASM18003096/Gfb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.