



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD

Ref : CC4/ASM18003096/Gfb3s2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 18-06-2019



ATTN: LYNN KHONG

Code : ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SJT 584H	<b>Veh. Inspected</b>	SCE 899L
<b>Policy No.</b>	CN809395	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M0090F	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	LYNN KHONG	<b>Assign Date</b>	15/02/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA CIVIC	<b>c.c</b>	1597
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2016
<b>Chassis No.</b>	MRHFC5650GT000354	<b>Colour</b>	PURPLE
<b>Odometer</b>	013837	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/55R16	HANKOOK	7 mm
<b>L/H Front Tyre</b>	215/55R16	HANKOOK	7 mm
<b>R/H Rear Tyre</b>	215/55R16	HANKOOK	7 mm
<b>L/H Rear Tyre</b>	215/55R16	HANKOOK	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	13/02/2018	<b>Inspection Date</b>	22/02/2018
<b>Survey held at</b>	15 UBI ROAD 4		
<b>Repairer</b>	KAH MOTOR CO SDN BERHAD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**