



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

LKK.

Customer : AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No. : SQT18000702	Page 1
Registration No : SCE899L	Date : 14. Feb 2018	
Chassis No : MRHFC5650GT000354	Customer No. : WZA006	
Model : CIVIC 1.6 VTI YM2016	Svc Advisor : LIEW THYE WEI	
Owner's Name : LEE MAH CHUAN	Engine No : R16B21600474	
Ins Policy No. :	Date Time : 14. Feb 2018 6:00:53 PM	
Date of Accident : 13/2/2018	Surveyor Name :	
	Survey Date :	
	Authorisation Date :	

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LEE MAH CHUAN OWNER INSURER: TOKIO MARINE ACC DATE: 13/2/18 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SJT584H						
71500-TEC-Q00ZZ	FACE ASSYRR.BUMPER <i>DR</i>	1	617.20	35	401.18	28.08	429.26
71502-TEX-Y00	GARNISHRR.BUMPER LOWER <i>SCR DR.</i>	1	35.30	35	22.94	1.61	24.55
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>MC.</i>	1	2.20	35	1.43	0.10	1.53
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>MC.</i>	1	2.20	35	1.43	0.10	1.53
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>MC.</i>	1	11.50	35	7.47	0.52	7.99
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>MC.</i>	1	11.50	35	7.47	0.52	7.99
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE <i>X NN</i>	1	7.60	35	4.94	0.35	5.29
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE <i>SCR.</i>	1	7.60	35	4.94	0.35	5.29
39680-TEX-Y41ZT	SENSOR ASSYPARKING <i>MIS</i>	4	79.80	35	207.48	14.52	222.00
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS <i>MC.</i>	1	27.20	35	17.68	1.24	18.92
74592-TEA-T00	FENDERL.RR.INNER <i>TN</i>	1	61.20	35	39.78	2.78	42.56
91501-TR0-003	CLIPINNER FENDER <i>MC</i>	7	2.30	35	10.46	0.73	11.19
71850-TEA-T01ZB	GARNISH ASSYL.SIDE SILL <i>Cut</i>	1	114.40	35	74.36	5.21	79.57
91505-TM8-003	CLIPBUMPER <i>MC</i>	9	2.00	35	11.70	0.82	12.52
33550-TEA-T01	TAILLIGHT ASSYL. <i>SCR</i>	1	273.10	35	177.51	12.43	189.94
67550-TEA-T00ZZ	PANELL.RR.DOOR <i>BT</i>	1	696.60	35	452.79	31.70	484.49
72965-TBA-A01	MOLDING ASSYL.RR.DOOR SASH <i>MC.</i>	1	28.30	35	18.39	1.29	19.68
72950-TEA-T01	MOLDING ASSY.L.RR.DOOR <i>MC.</i>	1	24.50	35	15.92	1.11	17.03
42700-TEA-T61	DISKALUMINIUM WHEEL <i>Cut</i>	1	289.10	35	187.91	13.15	201.06
42200-TBA-A02	BEARING ASSYRR.HUB UNIT <i>?</i>	1	155.70	35	101.20	7.08	108.28
52215-TBA-A00	KNUCKLE COMPL.RR. <i>?</i>	1	148.70	35	96.65	6.77	103.42



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SCE899L
Chassis No : MRHFC5650GT000354
Model : CIVIC 1.6 VTI YM2016
Owner's Name : LEE MAH CHUAN
Ins Policy No. :
Date of Accident : 13/2/2018

Document No. : SQT18000702 **Page** 2
Date : 14. Feb 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : R16B21600474
Date | Time : 14. Feb 2018 6:00:53 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
52355-TEA-T00	ARM COMP BL.RR.LOWER	1	59.80	35	38.87	2.72	41.59
52365-TEA-T00	ARM COMPL.RR.TRAILING	1	39.90	35	25.93	1.82	27.75
52510-TEA-T00	ARM COMPRR.UPPER	1	69.50	35	45.17	3.16	48.33
Sum Item					1973.60	138.16	2,111.76
BO-WHEEL ALIGN X4 WHEEL ALIGNMENT		1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60
BOSUN	SUNDRIES	1	30.00	10	30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	320.00	150	320.00	22.40	342.40
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST	1	350.00		350.00	24.50	374.50
BMU21R	REMOVE & REPLACE RR L UNDERCARRIAGE PARTS. (N)	1	540.00	(450)?	540.00	37.80	577.80
BKFE21K	STRAIGHTEN ALIGN RR L FENDER, RR PANEL & L/FRT DR. (450)	1	1500.00	1125	1500.00	105.00	1605.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2000.00	1750	2000.00	140.00	2140.00
Sum Labor					4820.00	337.40	5,157.40

Survey By

King King - 82880282

Date & Time

22/2/18

Excess

Status

60 days.

Signature

before paint photos.

Total Amount 6,973.60 488.16 7,461.76

Total (Inclusive of GST) 7,461.76

Printed on 14/2/2018 6:42:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.
The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Insurance Companies hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: