

ASS. REC. BY:

REF: CS/MSG18003103/TZ+dz02

Surveyor

ASSIGNMENT (Office)

Menimen

From (Person): Clara Milah Yeo

of MSG

Date/Time: 14/2/18 @ 5.01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 767IP

Insured:

at Workshop in/s

Cycle & Carriage Industries

Tel: 91865300

of

188 penden terop

Policy No: 28722192QMY

Claim No: 549604

Sum Insured:

Excess: \$500.00

Make of Veh:

(Client's Record)

D.O.A. 13/02/2018

19/2/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:38am @ 15/2/18

Person Contacted:

Yik Chan

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLB 767IP - CS/MSG18003103/MHdz

D.O.A: 13/02/18

20/2 @ 8:13am - approve by Ng Chen How

20/2 @ 9:11am - email Yik and cheong authorise repair excess \$500

Part by Part \$4538.33 (Ref: 2612.93)

Tanfer

MSIG

ASSIGNMENT

Date 19/2/18

Estimated Cost

CD TR / WS / TP RES / OD RES / EVA / INV / MY

To: Asset Value No SLB7671P
an: Workshop Cycle & Carriage Industries
188 Pandan Loop

Insured

Policy No

Claim No


Sum Insured Excess \$500.00

Claims Record Yik Chan

Market Val

Policy Condition

Remark: The van had commenced its repair at the time of inspection.



Salvage/Market Value \$112K

CAC Accident Report Consistent? Yes or No

CAC PP Seen Consistent? Yes or No

Est Repair days Fee Yes or No

Lim Sum % 3 Yr Yes or No

CA (REL) REF 24 HRS

Date Person Contacted

Vehicle IN / OUT

Date Time Action / Instruction

SLB7671P 20/6 April

Model: MCycle, Bus, Van, Lorry, Taxi, Motorcycle

Truck, Trailer

Make Mercedes Benz 19180 style 1595

Colour Grey

Sp. Rating 35940

Eng No

CAC W0017604225439544

Gen. Cond. Good Fair / Poor Burnt

Steering Inoper. Jammed / Locked Burnt or

Brake Inoper. Jammed / Locked Burnt or

Mod. M / S / T / STD A / R / H / O

Tyre Size F 225/45R17
R

BS / DUN / EXNOVA / BY / PS / LIZA / MO / OHTEL / PR / SUM

TOYO / YOKO or Continental

Front 6 Rear 6

R.R. 6

L.R. 6

CAC 19/2/18 1040

Surveyed at 188 Pandan Loop

Dist. of Damages (F) Front (R) Rear (S) Side (U) Under (O) Other

The U/C Chassis frame Body Structure affected Level of Str

3/7/2018

RECEIVED 3 JUL 2018

Date Time File Ref of

37 Typist

Date Time File Ref of

Preli. Report
Final Report

Days Of Repair 4

Resurvey No. of Trip

Single Fee

Add Fee

Site Fee
Material
Tool
Fuel

Transportation

Other Fee

Report Format

Auto Sum

OD
4538.88

200
10
200

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018		14 Feb 2018 17:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:		ANG HWEE NEE, ID: S7602452I, Tel: +6596717449, Email: NOEMAIL		[Created by insurer]
Vehicle Reg. No.:		SLB7671P	Date of Loss:	13/02/2018 09:00 - :59
Claim Type:		OD / 549604	Policy/Cover Note No.:	28722192QMY (Comprehensive) Coverage: 11/04/2017 - 10/04/2018
			Excess:	S\$500.00
Repairer:		Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/02/2018]		
Driver/Custodian:		ANG HWEE NEE (42 / Female), NRIC: S7602452I, Tel: +6596717449		
Adj Asg. Remarks:		to survey on 19/02/2018. Please revert. Thanks		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

ASS. REC. BY:

REF: CS/MSG18003103/TZtd3ed

Surveyor
Menmen

ASSIGNMENT (Office)

From (Person): Clara Milah Yeo of MSIG Date/Time: 14/2/18 @ 5:01pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLB 7671P Insured:

at Workshop m/s Cycle & Carriage Industries Tel: 91865300

of 188 penden loop

Policy No: 28722192QMY Claim No: 549604

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A. 13/02/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

19/2/2018

Date/Time: 11:38am @ 15/2/18 Person Contacted: Yikchan H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SLB 7671P - CS/MSG18003103/MHd3 D.O.A: 13/02/18

20/2 @ 8:13am - approve by Ng Chen How

20/2 @ 9:11am - email Yik and cheong authorise repair excess \$500

Part by Part \$4538.33 (Red: 26/2/93)

Tanfer

MSIG

ASSIGNMENT

Room: _____ Date: 19/2/18

Estimated Cost:

☒ TP / WS / TP RES / CO RES / EVA / INV / M

To: Insured/Endo No: SLB7671P
 at Workshop: Cycle & Carriage Industries
 of: 188 pandan loop

Insured:

Policy No:

Damage:


Sum Insured: _____ Excess: \$500.00

Claims Record: Yik Chan

Make of Van:

(Policy Condition)

Remark: The van had commenced its repair at the time of inspection



Est. of Market Value: \$112K

CAC Accident Room: _____ Consistent? Yes or No

CAC RR Seen: _____ Consistent? Yes or No

Est. Repair: _____ days Fee: _____ Yes or No

L.H. Sum: _____ \$ Val: _____ Yes or No

CA: ☒ PREL / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Date / Time: _____ Action / Instruction: _____

SLB7671P 20/6 April

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Other Vehicle

Truck / Trailer:

Make: Mercedes Benz A180 style 1595

Color: Grey

Co-Feeding: 35940

Eng No:

C/V: W0017624225439544

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In good / Jammed / Leaked / Burnt

Brake: ☒ In good / Jammed / Leaked / Burnt

Mod: ☒ M / S / T / STD / A / R / M /

Tyre Size: ☒ 275/45R17

BS / DUN / EXNOVA / GY / PS / LIZ / MO / DTEL / PR / S / V

TOYO / YOKO / Continental

Size: ☒ 6

R/S: ☒ 6

L/S: ☒ 6

D/O: 19/2/18 1040

Survey/Recd: 188 Pandan loop

Des of Damages: ☒ Rear / D/S / N/S / U/O / Reflection

The U/O / Chassis/frame / Body Structure affected: _____

3/7/2018

RECEIVED 3 JUL 2018

Days Time File Pass:

37 Typist

Days Time File Return:

☐ Prel. Report
☒ Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Surveys Fee:

200

Add Fee:

☐ Eng Fee \$
☐ Test \$
☐ Test Fee \$
☐ Test Fee \$

Test Fee:

Test Fee:

Test Fee:

Test Fee:

Test Fee:

Test Fee:

10

20

Report Form:

OD

Sumo Sum: 4538.88

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018		14 Feb 2018 17:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]			
Insured:	ANG HWEE NEE, ID: S7602452I, Tel: +6596717449, Email: NOEMAIL		
Vehicle Reg. No.:	SLB7671P	Date of Loss:	13/02/2018 09:00 - :59
Claim Type:	OD / 549604	Policy/Cover Note No.:	28722192QMY (Comprehensive) Coverage: 11/04/2017 - 10/04/2018
		Excess:	S\$500.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/02/2018]		
Driver/Custodian:	ANG HWEE NEE (42 / Female), NRIC: S7602452I, Tel: +6596717449		
Adj Asg. Remarks:	to survey on 19/02/2018. Please revert. Thanks		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003103/T1td3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-02-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLB 7671P
Policy No.	28722192QMY	Coverage (\$)	0.00
Claim No.	549604	Excess (\$)	500.00
Assign From	MERIMEN (CLARA MILAH YEO)	Assign Date	15/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/02/2018	Inspection Date	
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Clara Milah Yeo

From: Woon Choo Kwok
Sent: Wednesday, 14 February 2018 9:50 AM
To: Clara Milah Yeo
Cc: Christopher Chionh; Foo Ai Ngoh; Jason Sim
Subject: FW: SLB7671P OD Claim
Attachments: img-213181322-0001.pdf

Dear Milah

fya

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services Direct line +65 6643 1330 | Direct fax +65 6225 7402 |
woonchoo_kwok@sg.msigg-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msigg.com.sg

-----Original Message-----

From: Koh Lay Hoon
Sent: Wednesday, February 14, 2018 9:29 AM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msigg-asia.com>
Subject: FW: SLB7671P OD Claim

-----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]
Sent: Tuesday, February 13, 2018 6:15 PM
To: Claims <claims@sg.msigg-asia.com>
Subject: SLB7671P OD Claim

Dear Sir/Mdm,

Kindly arrange survey on the 19th Feb.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 20 February 2018 9:11 AM
To: Yik Chan Hoe; Cheong Chin Leong
Cc: SUR
Subject: SLB 7671P / OD / MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLB 7671P (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLB7671P (549604)**

OD

Feb 13 2018 9:00AM

[ANG HWEE NEE]

Cycle & Carriage Industries Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 20/02/2018 08:18 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4541.39) - SLB7671P - Claim Handler: Clara Milah Yeo

Approved:4541.39.

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2018 16:35
Date Of Accident	13/02/2018 09:05
Exact Location Of Accident	KALLANG BAHRU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB7671P
Insured/Policyholder	
Name Of Registered Owner	ANG HWEE NEE
NRIC No	S7602452I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96717449
Alternative Phone No	OFFICE-96717449

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A180
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28722192QMY
Cover Note Number	

Driver

Name of Driver	ANG HWEE NEE
NRIC No	S7602452I
Date Of Birth	27/01/1976
Occupation	INDOOR
Date Of Driving Pass	15/07/2002
Driving Experience	15 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96717449
Fax Number	
Contact Number	OFFICE-96717449
EMail Address	NOEMAIL

Address	3 PHILLIPS AVENUE #04-02 SINGAPORE
Postcode	546920
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

TRAFFIC WAS HEAVY, CAR B BRAKE I DID NOT BRAKE INTIME TO AVOID KNOCKING INTO THE BACK OF CAR B.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	REFER YIK
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGL8850P
Vehicle Make/Model/Colour	TOYOTA VIOS
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Centre
TEL: 6771 4353 HP: 9186 5109 Fr
Email: yikchanhoe.yik@cyclecarriage.com

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Traffic was heavy, Car B braked, I did not brake in time to avoid knocking into the back of Car B.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Person's
Name:
NRIC/FIN No.:

Yik Chare
Cycle & Carriage
Body Care &
0771 4353 HP: 9
Email: chaubee-yik@yik.com.sg
6872 121



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel: +65 6827 7888, Fax: +65 6827 7000
Co. Reg. No: 200412212G GST Reg. No: 20-0412212G

MOTOR MAX PLUS

RENEWAL CERTIFICATE

Policy Number	Period of Insurance	Place of Issue
A 28722192 QMY	11/04/2017 to 10/04/2018	SINGAPORE
Name and Address of Insured		Date of Issue
Ang Hwee Nee (Hong Huini) 3 Phillips Avenue #04-02 Singapore 546920		05/04/2017
		Account Number
		190005
Premium	GST	Total Due
SGD1,156.82	SGD80.98	SGD1,237.80

RISK NUMBER 1

MOTORMAX PLUS

OCCUPATION

Account Manager

FINANCIAL INTEREST

DBS Bank Ltd
as Hire Purchase Owners

SCOPE OF COVER Comprehensive

INTEREST INSURED

REGISTRATION NO.	SLB7671P	SUM INSURED	MARKET VALUE
MAKE/MODEL	Mercedes Benz A180 FL STYLE	INCL. COE/PARF	YES
ENGINE NUMBER	27091030893895	OFF-PEAK CAR	NO
CHASSIS NUMBER	WDD1760422J439544	NO CLAIM DISCOUNT	10.00% (or F/D)
YEAR OF MFG	2015	NCD PROTECTOR	NOT COVERED
CAPACITY	1595 C.C.	EXCESS	SGD500
SEATING CAPACITY	5 (INCL. DRIVER)	ANNUAL PREMIUM	SGD1,156.82
WINDSCREEN	UNLIMITED		

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit, rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Ang Hwee Nee (Hong Huini)

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S76024521

Name:

ANG HWEE NEE
(HONG HUINI)

Birth Date: 27 Jan 1976

Issue Date: 14 Jul 2003



000656875F

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

15 Jul 2002

FOR C&C USE ONLY

NP 428A



Licence No: S76024521



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLB7671P

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 21347
Reg No/Reg Date SLB7671P / 11/04/2016
Date In/Mileage / 0
Chassis No WDD1760422J439544
Engine No 27091030893895
Make/Model MB/MB A 180 (W176) "STYLE"
Colour/Trim 027 787 Mountain Gr/ 044 471 ARTICO/Fabr

Account No	Terms	Date/Time Printed	CSE	Operator					
WI000558	Credit	13/02/2018/ 18:08		395 / Yik Chan Hoe					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
M BPNSUB									
POLICY NO/ACC DATE : A28722192QMY // 13/02/2018									
DRIVE IN/EXCESS : 13/02/2018 // TBA									
DATE IN/DATE SURVEY:									
BY/AUTHORIZED ON :									
S BPNSUB									
1 PC FRONT REG. PLATE WITH CASING.									
A BPILAB									
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW									
BODY PANELS WITH REFINISH.									
A BPIRES									
RESPRAY FRONT BUMPER									
A BPILAB									
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO									
STANDARD SETTINGS.									
A BPILAB									
CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT									
M	FRONT COVER F CROSS MEMBER	1.00	66.98	00.00				66.98	
M	FRONT CROSS MEMBER	1.00	310.54	00.00				310.54	
M	FRONT CPA RADAR SENSOR	1.00	1157.08	00.00				1157.08	
M	FRONT MERCEDES STAR	1.00	130.65	00.00				130.65	
M	FRONT MB STAR HOLDER	1.00	72.06	00.00				72.06	
M	RADIATOR GRILLE TRIM ORNAMENTAL TRIM	1.00	72.60	00.00				72.60	
M	RADIATOR GRILLE TRIM ORNAMENTAL TRIM	1.00	72.60	00.00				72.60	
M	RADIATOR GRILLE TRIM	1.00	116.50	00.00				116.50	
M	RADIATOR GRILLE	1.00	564.59	00.00				564.59	
M	FRONT LICENSE PLATE MOLDING	1.00	58.68	00.00				58.68	
M	MB EMBLEM GROMMET	2.00	2.23	00.00				4.46	
M	FRONT MB EMBLEM	1.00	59.73	00.00				59.73	
M	FRONT BASIC MOUNTING FOR BUMPER	1.00	130.55	00.00				130.55	
M	FRONT IMPACT ABSORBER	1.00	120.19	00.00				120.19	
M	FRONT BUMPER UNDER SUPPORT	1.00	315.08	00.00				315.08	
M	FRONT BUMPER LOWER ORNAMENTAL TRIM	1.00	122.51	00.00				122.51	

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 9388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLB7671P

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No **21347**
Reg No/Reg Date **SLB7671P / 11/04/2016**
Date In/Mileage **/ 0**
Chassis No **WDD1760422J439544**
Engine No **27091030893895**
Make/Model **MB/MB A 180 (W176) "STYLE"**
Colour/Trim **027 787 Mountain Gr/ 044 471 ARTICO/Fabr**

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	13/02/2018/ 18:08		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M. FRONT BUMPER GRILLE	1.00	120.86	00.00	120.86
M. FRONT BUMPER	1.00	1146.15	00.00	1146.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to market
- Third party survey is not applicable
- No illegal modification is allowed
- Supplementary work is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date:

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5100 Fax: 6872 1372
Email: chanhoe.yik@cyclacarriage.com.sg

Confirmed & accepted by

Nett 7,151.81
7% GST on 7151.81 500.63
Total Payable 7,652.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLB7671P

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

WIP No

21347

Reg No/Reg Date

SLB7671P / 11/04/2016

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

WDD1760422J439544

27091030893895

MB/MB A 180 (W176) "STYLE"

027 787 Mountain Gr/ Q44 471 ARTICO/Fabr

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	13/02/2018/ 18:08		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : A28722192QMY // 13/02/2018 DRIVE IN/EXCESS : 13/02/2018 // TBA DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				60.00
S BPNSUB 1 PC FRONT REG. PLATE WITH CASING.				1200.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				750.00
A BPIRES RESPRAY FRONT BUMPER			0.10	380.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.				120.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT NET.	1.00	66.98	00.00	66.98
M FRONT COVER F CROSS MEMBER	1.00	310.54	00.00	310.54
M FRONT CROSS MEMBER	1.00	1157.08	00.00	1157.08
M FRONT CPA RADAR SENSOR	1.00	130.65	00.00	130.65
M FRONT MERCEDES STAR	1.00	72.06	00.00	72.06
M FRONT MB STAR HOLDER	1.00	72.60	00.00	72.60
M RADIATOR GRILLE TRIM ORNAMENTAL TRIM	1.00	72.60	00.00	72.60
M RADIATOR GRILLE TRIM ORNAMENTAL TRIM	1.00	116.50	00.00	116.50
M RADIATOR GRILLE TRIM	1.00	564.59	00.00	564.59
M RADIATOR GRILLE	1.00	58.68	00.00	58.68
M FRONT LICENSE PLATE MOLDING	2.00	2.23	00.00	4.46
M MB EMBLEM GROMMET	1.00	59.73	00.00	59.73
M FRONT MB EMBLEM	1.00	130.55	00.00	130.55
M FRONT BASIC MOUNTING FOR BUMPER	1.00	120.19	00.00	120.19
M FRONT IMPACT ABSORBER	1.00	315.08	00.00	315.08
M FRONT BUMPER UNDER SUPPORT	1.00	122.51	00.00	122.51
M FRONT BUMPER LOWER ORNAMENTAL TRIM				

Confirmed & accepted by

Authorized signatory and company stamp

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Taufik 97495749
Ex \$500 Revent
19/2/18 @ 1040
*Resurvey before paint
sur@lkkent.com 3-4 days

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

Panatier Loop Service Center



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLB7671P

MSIG INSURANCE (S'PORE) PTE LTD
MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

WIP No
Reg No/Reg Date
Date in/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

21347
SLB7671P / 11/04/2016
WDD1760422J439544
27091030893895
MB/MB A 180 (W176) "STYLE"
027 787 Mountain Gr/ 044 471 ARTICO/Fabr

Account No	Terms	Date/Time Printed	CSE	Operator
W1000558	Credit	13/02/2018/ 18:08		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M FRONT BUMPER GRILLE	1.00	120.86	00.00	120.86
M FRONT BUMPER	1.00	1146.15	00.00	1146.15

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to the repairer's
- Third party survey is to be conducted on a separate basis
- No illegal modification is allowed
- Supplementary work is to be done and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date:

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	7,151.81
7% GST on	7151.81	500.63
Total Payable		7,652.44

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLB7671P

Finalization

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
18 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 21347
Reg No/Reg Date SLB7671P / 11/04/2016
Date In/Mileage 20/02/2018 / 35940
Chassis No WDD1760422J439544
Engine No 27091030893895
Make/Model MB/MB A 180 (W176) "STYLE"
Colour/Trim 027 787 Mountain Gr/ 044 471 ARTICO/Fabr

Account No	Terms	Date/Time Printed	CSE	Operator
W1000558	Credit	20/06/2018/ 09:22		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNUN POLICE NO ACC DATE : A287221920MY / 13/02/2018 DRIVE IN/EXCESS : 13/02/2018 // \$500.00 DATE IN/DATE SURVEY : 19/02/2018 // TAUFIKH LKK BY/AUTHORIZED ON : 20/02/2018 // DENISE LKK				
S BPNUN SUPPLY ONE PC NO PLATE. ON 7007				60.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				960.00
A BPIRES RESPRAY FRONT BUMPER				600.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT, REPT				120.00
X BPNEXC INSURANCE EXCESS				-500.00
X FRONT MERCEDES STAR	1.00	130.65	00.00	130.65
X FRONT MB STAR HOLDER	1.00	72.06	00.00	72.06
X RADIATOR GRILLE TRIM ORNAMENTAL TRIM	1.00	72.60	00.00	72.60
X RADIATOR GRILLE TRIM ORNAMENTAL TRIM	1.00	72.60	00.00	72.60
X RADIATOR GRILLE TRIM	1.00	116.50	00.00	116.50
X RADIATOR GRILLE	1.00	564.59	00.00	564.59
X FRONT LICENSE PLATE MOLDING	1.00	58.68	00.00	58.68
X MB EMBLEM GROMMET	2.00	2.23	00.00	4.46
X FRONT MB EMBLEM	1.00	59.73	00.00	59.73
X FRONT BUMPER GRILLE	1.00	120.86	00.00	120.86
X FRONT BUMPER	1.00	1146.15	00.00	1146.15

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Nett 4,038.88
7% GST on 4038.88 282.72

Authorized signatory and company stamp

Total Payable 4,321.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2018		14 Feb 2018 17:01 Edit Adj Rpt	S\$4,538.88 Edit Estimates	S\$4,538.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ANG HWEE NEE , ID: S76024521, Tel: +6596717449, Email: NOEMAIL									
Vehicle Reg. No.: SLB7671P		Date of Loss: 13/02/2018 09:00 - :59 [22 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 549604		Policy/Cover Note No.: 28722192QMY (Comprehensive) Coverage: 11/04/2017 - 10/04/2018							
		Excess: S\$500.00							
Repairer: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/03/2018]									
Driver/Custodian: ANG HWEE NEE (42 / Female) , NRIC: S76024521, Tel: +6596717449									
Adj Asg. Remarks: to survey on 19/02/2018. Please revert. Thanks									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (20/02/2018): Alert - Adj Mandate Approved (S\$4541.39) - SLB7671P - Claim Handler: Clara Milah...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLB7671P (549604)
OD
Feb 13 2018 9:00AM
[ANG HWEE NEE]
Cycle & Carriage Industries Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)		Thumbnail	Print
1	13/02/18 17:23	Accident Statement	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/02/18 14:41	Adjuster Immediate Advice	1	Load HTM	
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	14/02/18 10:58	Repair Estimate	1	Load PDF	
2	14/02/18 10:58	Email from w.shop to request for survey	1	Load PDF	
3	14/02/18 10:58	TPD SLB7626X GIA REPORT From: TP - Reg. No: SGL885DP, Claimant: B&O VEHICLE RENTAL	1	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/02/18 14:42	ESTIMATE	1	Load PDF	

Linked Accident Report Documents

		View View in Browser	
Assessment Reports		1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail Print
1	13/02/18 17:23	Accident Statement	1 Load HTM
Photos/Images		3 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail Print
1	13/02/18 17:19	Accident Photo	1 Load JPG ☒
2	13/02/18 17:19	Accident Photo	1 Load JPG ☒
3	13/02/18 17:19	Accident Photo	1 Load JPG ☒
4	13/02/18 17:19	Accident Photo	1 Load JPG ☒
5	13/02/18 17:20	Accident Photo	1 Load JPG ☒
6	13/02/18 17:20	Accident Photo	1 Load JPG ☒
7	13/02/18 17:20	Accident Photo	1 Load JPG ☒
8	13/02/18 17:20	Accident Photo	1 Load JPG ☒
9	13/02/18 17:20	Accident Photo	1 Load JPG ☒
10	13/02/18 17:20	Accident Photo	1 Load JPG ☒
Documentation		1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail Print
1	13/02/18 17:18	Sketch Plan	1 Load JPG ☒
2	13/02/18 17:18	Sketch Plan #2	1 Load JPG ☒
3	13/02/18 17:18	Accident Sketch Plan	1 Load JPG ☒
4	13/02/18 17:18	Accident Sketch Plan	1 Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003103/T1TD3E2

Date: 05/07/2018

REFERENCE

Insured/Claimant: ANG HWEE NEE Policy No: 28722192QMY
Date of Loss: 13/02/2018 Nature of Claim: OD Claim No: 549604

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB7671P**
Make & Model: MERCEDES-BENZ A180, 1.6 FL STYLE (R17 HLG) (A) Engine No: 27091030893895
Reg. Date: 11/04/2016 (Man. Year: 2015) Chassis No: WDD1760422J439544
Colour: Grey Odometer: 35940 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$112,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,701.81	2,478.88	2,222.93	47.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	2,060.00	390.00	15.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,151.81	4,538.88	2,612.93	36.54
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	6,651.81	4,038.88	2,612.93	39.28
+ GST 7.00/7.00% (S\$)	465.63	282.72	182.91	39.28
Nett Amount (S\$)	7,117.44	4,321.60	2,795.84	39.28

INSPECTION

Date of Assignment: 14/02/2018
Date Inspected: 19/02/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2018)
Parts:	144	MERCEDES-BENZ A180 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB7671P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT REG. PLATE WITH CASING	Bent	60.00 FS	*60.00 FS
2	1		*FRONT COVER F CROSS MEMBER	Not Necessary	66.98 FS	*- FS
3	1		*FRONT CROSS MEMBER	Not Necessary	310.54 FS	*- FS
4	1		*FRONT CPA RADAR SENSOR	Not Necessary	1,157.08 FS	*- FS
5	1		*FRONT MERCEDES STAR	Cut	130.65 FS	*130.65 FS
6	1		*FRONT MB STAR HOLDER	Distorted	72.06 FS	*72.06 FS
7	1		*RADIATOR GRILLE TRIM ORNAMENTAL TRIM	Necessary	72.60 FS	*72.60 FS
8	1		*RADIATOR GRILLE TRIM ORNAMENTAL TRIM	Necessary	72.60 FS	*72.60 FS
9	1		*RADIATOR GRILLE TRIM	Cracked	116.50 FS	*116.50 FS
10	1		*RADIATOR GRILLE	Cracked	564.59 FS	*564.59 FS
11	1		*FRONT LICENSE PLATE MOLDING	Deformed	58.68 FS	*58.68 FS
12	2		*MB EMBLEM GROMMET	Necessary	4.46 FS	*4.46 FS
13	1		*FRONT MB EMBLEM	Necessary	59.73 FS	*59.73 FS
14	1		*FRONT BASIC MOUNTING FOR BUMPER	Not Necessary	130.55 FS	*- FS
15	1		*FRONT IMPACT SENSOR	Not Necessary	120.19 FS	*- FS
16	1		*FRONT BUMPER UNDER SUPPORT	Not Necessary	315.08 FS	*- FS
17	1		*FRONT BUMPER LOWER ORNAMENTAL TRIM	Not Necessary	122.51 FS	*- FS
18	1		*FRONT BUMPER GRILLE	Deformed	120.86 FS	*120.86 FS
19	1		*FRONT BUMPER	Deformed	1,146.15 FS	*1,146.15 FS
Total Parts (S\$)					4,701.81	2,478.88

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,200.00	960.00
2	RESPRAY FRONT BUMPER	New	750.00	600.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
Gross Labour Cost (\$\$)			2,450.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >