

22/03/2018

ASS. REC. BY:

REF:

CS/MSG18003111/4td3⁷²

Special Instruction:

Surveyor

MARCEUS

ASSIGNMENT (Office)

From (Person):

Christine Wong

of

MSG

Date/Time:

14/02/18 @ 3:06pm

Estimated Cost:

Bill to:

OD-IT/WS/TP REST/OD-RES/EVA/INV/MV/CS

To Inspect Vehicle No.:

SLU 5070L

Insured:

SJX 7337M

at Workshop m/s

Kim Chawee

Tel:

6744 8183

of Blk 1, Kaki Bk Ave 6 # 01-106 Autobay

Policy No.:

28711069SMP

Claim No.:

519600

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13/2/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp

H.O.D. Endorsement:

Date/Time:

10:25am @ 15/2/18

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate called no answer. wksp closed for CNY

SLU 5070L - CC4/ASM18003047/ea3

D.O.A: 13/2/2018

SJX 7337M - CS3/CA14023744/R/bud

D.O.A: 21/12/2014

(08/11/13) wef

ASS. REC. BY: MORIS

REF:

MS16/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 5070Lat Workshop m/s K. M. Chae

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Repairs:

im:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1) 2014 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Report Format:

Lump Sum / I.B.I.: (\$ 17028)Days Of Repair: 10Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

450

10

460

RECEIVED 20 APR 2018

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	14 Feb 2018		14 Feb 2018 15:06 Assign			
						New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAI KOK PHANG, ID: S0121312A, Tel: +6591500907, Email: NOEMAIL		
Main Claimant:	ENG TECK SENG, ID: S8234326A		
Vehicle Reg. No.:	SLU5070L	Date of Loss:	13/02/2018 08:00 - :59
Claim Type:	TP / 549600	Policy/Cover Note No.:	28711069SMF (Comprehensive) Coverage: 01/04/2017 - 31/03/2018
Vehicle Reg. No. (Insured):	SJX7337M	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	A S Auto Service (HQ) Blk 1, Kaki Bukit Avenue 6,, #01-106 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 67448183		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/02/2018]		
Driver/Custodian (Insured):	TAI KOK PHANG (63 / Male), NRIC: S0121312A, Tel: +6591500907		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18003111/Utd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 15-02-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJX 7337M	Veh. Inspected	SLU 5070L	
Policy No.	28711069SMF	Coverage (\$)	0.00	
Claim No.	549600	Excess (\$)	0.00	
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	15/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/02/2018	Inspection Date		
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Nancy Lam

From: Nancy Lam <nancy.lam@fastechauto.com.sg>
Sent: Tuesday, February 20, 2018 3:28 PM
To: 'jason@fastechauto.com.sg'
Subject: FW: Request for PRS SLU5070L DOA 13/02/2018

Regards,
Nancy Lam
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Nancy Lam [mailto:nancy.lam@fastechauto.com.sg]
Sent: Monday, February 19, 2018 10:36 AM
To: 'claims@sg.msiga.com' <claims@sg.msiga.com>
Subject: Request for PRS SLU5070L DOA 13/02/2018

Without Prejudice

Hi Sir

My client claiming your insured SJX 7337M.

Please kindly arrange PRS for SLU5070L.

Date of accident 13.02.2018

Thank you

Regards,
Jason Tang
Kim Chwee Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

MSME18022218 / BME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 13/02/2018 16:04
 SUBMITTED BY: Chio Pui Yeng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 13/02/2018 16:04
 Date Of Accident 13/02/2018 08:00
 Exact Location Of Accident KJE TOWARDS TUAS
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU5070L
 Insured/Policyholder
 Name Of Registered Owner ENG TECK SENG
 NRIC No S8234326A
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-91450810
 Alternative Phone No OFFICE-91450810

Vehicle Particulars

Manufacturer HONDA
 Model VEZEL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AXA INSURANCE PTE LTD
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number GA298922
 Cover Note Number

Driver

Name of Driver ENG TECK SENG
 NRIC No S8234326A
 Date Of Birth 10/10/1982
 Occupation INDOOR
 Date Of Driving Pass 12/06/2004
 Driving Experience 13 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91450810
 Fax Number
 Contact Number OFFICE-91450810

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLP6843T
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SKR7988D
Vehicle Make/Model/Colour
Details Of Properties VEHICLE D
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SJT8492L
Vehicle Make/Model/Colour
Details Of Properties VEHICLE E
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13th February 2018, around 8 am, I was travelling along KTO to work. Suddenly, vehicle SJ18492L emergency brake abating. I tried to negotiate by swerving out to another lane, at this moment, vehicle SJX7337M collided into rear right of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time: 13/02/18

Driver's Signature

(If driver is not the policyholder)

Date & Time: 13/02/18

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 13/2/18

Driver's Signature

(If driver is not the policyholder)

Date & Time: 13/2/18

Reporting Centre Personnel's Signature

Name:

NRIC/PIR No:

LIU'S BROTHER

Address 96 EDGEDALE PLAINS #03-33
Postcode 828688
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: JANICE WAN
GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON 13/02/2018 AROUND 8AM, I WAS TRAVELLING ALONG KJE TO WORK. SUDDENLY, VEHICLE (SJT8492L) EMERGENCY BRAKE ABRUPTLY. I TRIED TO AVOID BY SWITCHING TO ANOTHER LANE. AT THIS MOMENT, VEHICLE (SJX7337M) COLLIDED INTO REAR RIGHT OF MY CAR.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJX7337M
Vehicle Make/Model/Colour
Details Of Properties VEHICLE B
Vehicle Category PRIVATE CAR
Name of Driver STEVEN TAI KOK PHANG
NRIC/Passport Number
Contact Number 91500907
Address
Postcode
Insurance Company Name

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4326A

Vehicle Details

Vehicle No.: SLU5070L
Vehicle to be Exported: No
Intended De-registration Date: 19 Feb 2018
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5X CVT
Primary Colour: White
Manufacturing Year: 2017
Engine No.: L15B4428602
Chassis No.: RU11228600
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$20,848.00
Original Registration Date: 04 Dec 2017
First Registration Date: 04 Dec 2017
Transfer Count: 0
Actual ARF Paid: \$11,188.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 03 Dec 2027
PARF Rebate Amount: \$8,391.00

Intended COE Rebate Details

COE Expiry Date: 03 Dec 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$41,617.00
COE Rebate Amount: \$40,737.00
Total Rebate Amount: \$49,128.00

The information contained herein is correct as at 19 Feb 2018

OK

2014

Denise

List	Supp List	Special Nett	Labour
820	490.6	40	30
128	366.2	40	100
3518.4	68.5	50	60
90	66.8	40	100
348.5	992.1	200	80
35	793.68		100
366.2		370	120
801.7			1600
62.5			1600
321			3790
58			
351			
86.2			
25			
264.8			
789			
245.3			
951			
105			
135.8			
38.5			
298.5			
945.1			
517			
122.3			
425.1			
388.2			
362.3			
762.7			
195			
41.7			
504.6			
774.28			
70		17028.04	
145.3			
15092.90			
12074.36			
12074.32			

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Not Delivered 19/7/18
17028.00
1/12/18
1017.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date: 18.04.2018

Vehicle Number: SEU 5070L

Make/Model: HONDA VEZEL

Chassis/Engine no:

Accident Date: 13.02.2018

Claim No: 0218-20143

Reference:

Policy No:

Qty Particular

List Item:

1 pc Front bonnet 820.00
1 pc Front bonnet lock 128
2 pc Front head lamp @ 1952.20 1759.20 x 2 = 3518.40
2 pc Front head lamp lower bracket @ 169.30 45 x 2 = 90
1 pc Front grille 348.50
1 pc Front grille emblem 35.00
1 pc Front grille base 366.20
2 pc Front grille outer chrome garnish @ 201.20
1 pc Front bumper 801.70
2 pc Front bumper fog lamp @ 354.20
2 pc Front bumper fog lamp cover @ 99.60 62.50
1 pc Front bumper reinforment 321.00
2 pc Front bumper side retainer @ 29.00
1 pc Front bumper lower 351
1 pc Front bumper lower grille 86.20
1 pc Front bumper sponge
1 pc Front bumper towing cover 25
1 pc Front support panel
1 pc Front support panel top garnish
1 pc Radiator
1 pc Radiator fan motor
1 pc Radiator fan blade
1 pc Radiator cowling 789
1 pc A/C condenser
1 pc A/C fan motor
1 pc A/C fan blade
1 pc A/C fan cowling
2 pc Front fender @ 785.20
2 pc Front fender cowling @ 158.20
2 pc Front fender wheel arch @ 588.60 245.30

\$ Buc 1,569.60 ✓
\$ Tm 265.80 ✓
\$ Cm 3,904.40 ✓
\$ Cm 338.60 ✓
\$ Cm 689.60 ✓
\$ Rm 52.50 ✓
\$ Cm 425.20 ✓
\$ 11 402.40 X
\$ D.S 1,289.60 ✓
\$ 11 708.40 X
\$ o/s tm 199.20 140
\$ D.S 685.50 ✓
\$ Suf 58.00 ✓
\$ De 945.50 ✓
\$ Tm 485.20 ✓
\$ NF 133.10 X
\$ Tm 36.90 ✓
\$ R 998.50 X
\$ De 264.80 ✓
\$ 11 1,452.50 X
\$ 11 562.20 X
\$ 11 110.20 X
\$ 11 185.60 X
\$ p 11 1,569.60 ✓
\$ 11 495.50 X
\$ 11 108.50 X
\$ 11 345.20 X
\$ R 1,570.40 X
\$ 11 316.40 X
o/s \$ Tm 1,177.20 1pc
Continue =

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Date : 18.04.2018

Vehicle Num : SLU 5070L

Make/Model : HONDA VEZEL

Chassis/Engine no :

Accident Date : 13.02.2018

Claim No : 0218-20143

Reference :

Policy No :

Qty Particular

List Item :

1 pc	Rear boot	957
1 pc	Rear boot lock	105
1 pc	Rear boot lock catch	
1 pc	Rear boot rubber	135.80
2 pc	Rear boot absorber @	123.50
1 pc	Rear boot emblem (vezel)	38.50
1 pc	Rear boot inner board	298.50
1 pc	Rear boot centre emblem	
1 pc	Rear boot inner pull garnish	
2 pc	Rear boot hinge @	99.50
1 pc	Exhaust centre pipe	945.10
1 pc	Rear boot centre garnish	
2 pc	Rear number plate lamp @	88.50
1 pc	Rear end panel	517.00
1 pc	Rear end panel trim	122.30
1 pc	Rear floor panel	
1 pc	Rear floor panel sponge	425.10
1 pc	Rear floor panel top cover board	388.20
2 pc	Rear fender trim @	825.20
1 pc	Rear bumper	762.70
2 pc	Rear bumper side @	562.30
2 pc	Rear bumper sensor @	235.20
1 pc	Rear bumper top beam	
2 pc	Rear bumper side retainer @	41.70
2 pc	Tail lamp @	836.50
1 pc	Rear exhaust silencer	774.20
2 pc	Rear exhaust rubber @	35.00
1 pc	Rear exhaust heat shield	

List Item total :

Discount 20 % :

3.65	\$ 20	1,852.20	✓
	\$ 20	495.20	✓
	\$ 11	56.20	X
	\$ 20	265.90	✓
	\$ 11	247.00	X
	\$ 20	85.20	✓
Ref	\$ 20	715.20	✓
	\$ 11	81.50	X
	\$ 11	102.20	X
	\$ 11	199.00	X
Ref	\$ 20	1,250.40	✓
	\$ 11	562.20	X
	\$ 11	177.00	X
3.65	\$ 20	952.20	✓
	\$ 20	451.20	✓
	\$ 2	1,996.30	X
	\$ 20	513.20	✓
Ref	\$ 20	465.90	✓
0/5	\$ 20	1,650.40	✓
	\$ 20	1,652.20	✓
0/5	\$ 20	1,124.60	✓
	\$ 20	470.40	2005.1
	\$ 20	165.30	X
0/5	\$ 20	83.40	TPC
0/5	\$ 20	1,673.00	TPC
Ref	\$ 20	996.30	✓
	\$ 20	70.00	✓
	\$ 20	145.30	✓
	\$	39,845.00	
	\$	7,969.00	
	\$	31,876.00	

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Date : 18.04.2018

Vehicle Num : SLU 5070L

Make/Model : HONDA VEZEL

Chassis/Engine no :

Accident Date : 13.02.2018

Claim No : 0218-20143

Reference :

Policy No :

Qty	Particular	B/F	\$	31,876.00
-----	------------	-----	----	-----------

Special Nett Item :

10 pc	Front bonnet insulator clips @ 7.00	\$	rec	70.00	40
4 pc	Front grille clips @ 7.00	\$	11	28.00	X
1 pc	Front number plate	\$	sent	45.00	40
20 pc	Front wheel arch clips @ 7.00	\$	11	140.00	X
1 pc	Radiator coolant	\$	11	80.00	X
1 pc	Rear floor panel insulator	\$	11	250.00	X
1 pc	Rear glass sealant	\$	11	100.00	X
1 pc	Rear end panel sealant	\$	rec	100.00	50
1 set	Rear licence plate w/holder	\$	Bel	350.00	40
Special Nett Total		\$		1,163.00	

Labour Charge :

To check wiring	\$	180.00	30
Tuff kote	\$	180.00	100
Towing charge (king roller)	\$	150.00	60
Remove and replace aircond condenser and refill gas	\$	160.00	100
Remove and replace radiator	\$	11	100.00 X
Remove and refix upholstery and roof lining	\$	160.00	80
Remove and replace rear exhaust pipe	\$	160.00	100
Remove and refix rear windscreen	\$	160.00	120
To remove and replace spare part and panel beating	\$	3,500.00	1600
To spray painting and etc	\$	3,500.00	1600
Labour Charge Total :	\$	8,250.00	

4100

Singdollars : Fourty One Thousand Two Hundred And Eighty Nine Only.

E & O . E

Total Amount : \$ 41,289.00

42228.28

KIM CHWEE AUTO PTE LTD

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Date : 18.04.2018

Vehicle Num : SLU 5070L

Make/Model : HONDA VEZEL

Chassis/Engine no :

Accident Date : 13.02.2018

Claim No : 0218-20143

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

2 pc Rear fender outer protector @ 245.30
1 pc Rear bumper under cover 366.20
1 pc Rear bumper reflector O/S
1 pc Front bumper air guide O/S
List Item Total :

\$	Turn	490.60	✓
\$	Dis	548.20	✓
\$	crn	68.50	✓
\$	Dis	66.80	✓
\$		1,174.10	
\$			
\$			

E & O . E

Total Amount : \$

KIM CHWEE AUTO PTE LTD

P-160ft
202
12868
sin 370
12868-3790
17028

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003111/UTD3N2

Date: 24/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28711069SMF
Claimant Vehicle No :	SLU5070L	Insured Vehicle No :	SJX7337M
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	549600

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5070L	Engine No:	L15B4428602
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Chassis No:	RU11228600
Reg. Date:	04/12/2017 (Man. Year: 2017)	Odometer:	6068 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 9 mm	Rear Left Side:	Dunlop 9 mm
Front Right Side:	Dunlop 9 mm	Rear Right Side:	Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,978.28	13,238.00	20,740.28	61.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,250.00	3,790.00	4,460.00	54.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	42,228.28	17,028.00	25,200.28	59.68
+ GST 7.00/7.00% (S\$)	2,955.98	1,191.96	1,764.02	59.68
Nett Amount (S\$)	45,184.26	18,219.96	26,964.30	59.68

INSPECTION

Date of Assignment:	20/04/2018
Date Inspected:	19/02/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2018)	
Parts: M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SLU5070L)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BONNET	Buckled	1,569.60 FL	*820.00 FL
2	1	*FRONT BONNET LOCK	Twisted	265.80 FL	*128.00 FL
3	2	*FRONT HEAD LAMP	Cracked	3,904.40 FL	*3,518.40 FL
4	2	*FRONT HEAD LAMP LOWER BRACKET	Cracked	338.60 FL	*90.00 FL
5	1	*FRONT GRILLE	Cracked	689.60 FL	*348.50 FL
6	1	*FRONT GRILLE EMBLEM	Necessary	52.50 FL	*35.00 FL
7	1	*FRONT GRILLE BASE	Cracked	425.20 FL	*366.20 FL
8	2	*FRONT GRILLE OUTER CHROME GARNISH	Not Necessary	402.40 FL	*. FL
9	1	*FRONT BUMPER	Distorted	1,289.60 FL	*801.70 FL
10	2	*FRONT BUMPER FOG LAMP	Not Necessary	708.40 FL	*. FL
11	1	*FRONT BUMPER FOG LAMP COVER	O/s Twisted	199.20 FL	*62.50 FL
12	1	*FRONT BUMPER REINFORCEMENT	Dented	685.50 FL	*321.00 FL
13	2	*FRONT BUMPER SIDE RETAINER	Bent	58.00 FL	*58.00 FL
14	1	*FRONT BUMPER LOWER	Deformed	945.50 FL	*351.00 FL
15	1	*FRONT BUMPER LOWER GRILLE	Twisted	485.20 FL	*86.20 FL
16	1	*FRONT BUMPER SPONGE	Not fitted	133.10 FL	*. FL
17	1	*FRONT BUMPER TOWING COVER	Torn	36.90 FL	*25.00 FL
18	1	*FRONT SUPPORT PANEL	Repair	998.50 FL	*. FL
19	1	*FRONT SUPPORT PANEL TOP GARNISH	Deformed	264.80 FL	*264.80 FL
20	1	*RADIATOR	Not Necessary	1,452.50 FL	*. FL
21	1	*RADIATOR FAN MOTOR	Not Necessary	562.20 FL	*. FL
22	1	*RADIATOR FAN BLADE	Not Necessary	110.20 FL	*. FL
23	1	*RADIATOR COLWING	Not Necessary	185.60 FL	*. FL
24	1	*A/C CONDENSER	Punctured	1,569.60 FL	*789.00 FL
25	1	*A/C FAN MOTOR	Not Necessary	495.50 FL	*. FL
26	1	*A/C FAN BLADE	Not Necessary	108.50 FL	*. FL
27	1	*A/C FAN COWLING	Not Necessary	345.20 FL	*. FL
28	2	*FRONT FENDER	Repair	1,570.40 FL	*. FL
29	2	*FRONT FENDER COWLING	Not Necessary	316.40 FL	*. FL
30	1	*FRONT FENDER WHEEL ARCH	O/s Torn	1,177.20 FL	*245.30 FL
31	1	*REAR BOOT	Badly Dented	1,852.20 FL	*951.00 FL
32	1	*REAR BOOT LOCK	Twisted	495.20 FL	*105.00 FL
33	1	*REAR BOOT LOCK CATCH	Not Necessary	56.20 FL	*. FL
34	1	*REAR BOOT RUBBER	Twisted	265.90 FL	*135.80 FL
35	2	*REAR BOOT ABSORBER	Not Necessary	247.00 FL	*. FL
36	1	*REAR BOOT EMBLEM (VEZEL)	Necessary	85.20 FL	*38.50 FL
37	1	*REAR BOOT INNER BOARD	Deformed/Cracked	715.20 FL	*298.50 FL
38	1	*REAR BOOT CENTRE EMBLEM	Not Necessary	81.50 FL	*. FL
39	1	*REAR BOOT INNER PULL GARNISH	Not Necessary	102.20 FL	*. FL
40	2	*REAR BOOT HINGE	Not Necessary	199.00 FL	*. FL
41	1	*EXHAUST CENTRE PIPE	Bent/Twisted	1,250.40 FL	*945.10 FL
42	1	*REAR BOOT CENTRE GARNISH	Not Necessary	562.20 FL	*. FL
43	2	*REAR NUMBER PLATE LAMP	Not Necessary	177.00 FL	*. FL
44	1	*REAR END PANEL	Badly Dented	952.20 FL	*517.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
45	1	*REAR END PANEL TRIM	Twisted	451.20 FL	*122.30 FL
46	1	*REAR FLOOR PANEL	Repair	1,996.30 FL	*- FL
47	1	*REAR FLOOR PANEL SPONGE	Torn	513.20 FL	*425.10 FL
48	1	*REAR FLOOR PANEL TOP COVER BOARD	Deformed/Warped	465.90 FL	*388.20 FL
49	1	*REAR FENDER TRIM	O/s Torn	1,650.40 FL	*362.30 FL
50	1	*REAR BUMPER	Distorted	1,652.20 FL	*762.70 FL
51	1	*REAR BUMPER SIDE	O/s Deformed	1,124.60 FL	*195.00 FL
52	1	*REAR BUMPER TOP BEAM	No such part	165.30 FL	*- FL
53	1	*REAR BUMPER SIDE RETAINER	O/s Bent	83.40 FL	*41.70 FL
54	1	*TAIL LAMP	O/s Cracked	1,673.00 FL	*504.60 FL
55	1	*REAR EXHAUST SILENCER	Bent/Dented	996.30 FL	*774.20 FL
56	2	*REAR EXHAUST RUBBER	Necessary	70.00 FL	*70.00 FL
57	1	*REAR EXHAUST HEAT SHIELD	Distorted	145.30 FL	*145.30 FL
58	2	*REAR FENDER OUTER PROTECTOR	Torn	490.60 FL	*490.60 FL
59	1	*REAR BUMPER UNDER COVER	Distorted	548.20 FL	*366.20 FL
60	1	*REAR BUMPER REFLECTOR O/S	Cracked	68.50 FL	*68.50 FL
61	1	*FRONT BUMPER AIR GUIDE O/S	Distorted	66.80 FL	*66.80 FL
62	1	*REAR BUMPER SENSOR	Shorted	376.32 FS	*200.00 FS
63	10	*FRONT BONNET INSULATOR CLIPS	Necessary	70.00 FS	*40.00 FS
64	4	*FRONT GRILLE CLIPS	Not Necessary	28.00 FS	*- FS
65	1	*FRONT NUMBER PLATE	Bent	45.00 FS	*40.00 FS
66	20	*FRONT WHEEL ARCH CLIPS	Not Necessary	140.00 FS	*- FS
67	1	*RADIATOR COOLANT	Not Necessary	80.00 FS	*- FS
68	1	*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
69	1	*REAR GLASS SEALANT	Not Necessary	100.00 FS	*- FS
70	1	*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
71	1	*SET REAR LICENCE PLATE W/HOLDER	Bent	350.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	42,088.02	16,455.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	8,109.74	3,217.00
Total Parts (\$\$)	33,978.28	13,238.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	180.00	30.00
2	TUFF KOTE	New	180.00	100.00
3	TOWING CHARGE (KING ROLLER)	New	150.00	60.00
4	REMOVE AND REPLACE AIRCOND CONDENSER AND REFILL GAS	New	160.00	100.00
5	REMOVE AND REPLACE RADIATOR	New	100.00	-
6	REMOVE AND REFIX UPHOLTERY AND ROOF LINING	New	160.00	80.00
7	REMOVE AND REPLACE REAR EXHAUST PIPE	New	160.00	100.00
8	REMOVE AND REFIX REAR WINDSCREEN	New	160.00	120.00
9	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	3,500.00	1,600.00
10	TO SPRAY PAINTING AND ETC	New	3,500.00	1,600.00
Gross Labour Cost (S\$)			8,250.00	3,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >