


Farm

REF: NS/INC18003116/R/vd302

2013/01/18

From: _____	Date: _____	File No: SHB 939L	Page: 2013 Jan
Estimated Cost: _____		Type: <input checked="" type="radio"/> M/Cycle Bus / van / Lorry <input type="radio"/> Prime Mover	
<u>OD / TP / WS / TP RES / OD RES / EVA / INV / MV</u>		Truck / Trailer: _____	
To inspect vehicle No: _____		Make: CHEVROLET EPICA	Yr: 1991
at Workshop No: _____		Colour: MARON	Insured / Std IN: NA
of _____		So Reading: 598 391	TP Paid / Insured / Std IN: NA
Insured: GBE 9209G		Eng No: _____	
Policy No: 5080127283-01	29/1/17-28/1/18	C No: KLILA69JBB137674	
Claims No: MT/0982151-003		Gen. Cond: <input checked="" type="radio"/> Good / <input type="radio"/> Fair / <input type="radio"/> Poor / <input type="radio"/> Burnt	
Sum Insured: _____	Excess: _____	Steering: <input checked="" type="radio"/> Order / <input type="radio"/> Jammed / <input type="radio"/> Leaked / <input type="radio"/> Burnt or	
Client's Record: _____		Brake: <input checked="" type="radio"/> Order / <input type="radio"/> Jammed / <input type="radio"/> Leaked / <input type="radio"/> Burnt or	
Make of Veh: _____		Mod: <input checked="" type="radio"/> Nil / <input type="radio"/> S/B/B / <input type="radio"/> STD A/Rim or	
(Policy Condition)		Tyre Size: F: 205/65 R15	
		R: ~	
Remark: The veh had commenced its repair at the time of inspection.		BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI	
		TOYO / YOKO or FALKEN	
Beh or Market Value: _____		Front: _____	Rear: _____
IDAC Accident Report: _____	Consistent? Yes or No	R.Ba: 5 mm	R.Ba: 5 mm
GIA / PP Seen: _____	Consistent? Yes or No	L.Ba: 5 mm	L.Ba: 5 mm
Est. Repairs: _____ days	Res: Yes or No	D/OA: 12/02/18	DO: 13/02/18
Lump Sum: _____ %	3 Yrs: Yes or No	Survey recd at: SMRT	
OA / REV / REP. / 24 HRS		Des. of Damages: <input checked="" type="radio"/> F / <input checked="" type="radio"/> Rear / <input type="radio"/> O/S / <input type="radio"/> N/S / <input type="radio"/> U/C	Rooftop: _____
Date: _____	Person Contacted: _____	Vehicle IN / OUT	
		The U/C / Chassis frame / Body Structure affected due to collision	



Date Time Action Instruction
SHB 939L - 004 / III 17000329 / Klyb 3s2 **13/02/2018** **02/18/2084**
GBE 9209G - v
13/4/18 LS \$14,650 confirmed by email (Red 20,810.29, 5990) **NTNL**
Rasul **GBE 29096**
See mirror

RECEIVED

[Signature] 26/2

Day Time File Passed: <input type="checkbox"/> Prel. Report	Days Of Repair: 14	Survey Fee: 160
Day Time File Returned: <input type="checkbox"/> Final Report	Resurvey No. of Trip: 1	Day Time: 35
13/4 - typist	Add Fee: <input type="checkbox"/> Steered 5	
	<input type="checkbox"/> Clutch 5	
	<input type="checkbox"/> Tyre 5	
	<input type="checkbox"/> Brake 5	
Report Format: TP		
Lump Sum / LB: LS \$14,650		

160
35
145

Survey Department Check List (Case Handler)

Reference No. : **NS/ INC 18003116/ R1vd3**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 13/11/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003116/R1vd3				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 19-02-2018	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 9209G	Veh. Inspected	SHB 939L	
Policy No.	5080127283-01	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/02/2018	Inspection Date	13/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Veron Chen (LKKAuto)

From: mtreg <mtreg@income.com.sg>
Sent: Friday, 13 April 2018 10:38 AM
To: Veron Chen (LKKAuto)
Subject: REQUEST FOR CLAIM NUMBER

Hi,

Claim created

With Regards

Samsia
Senior Admin Assistant, Motor Insurance
www.income.com.sg



From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Friday, April 13, 2018 9:50 AM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Please provides us the claim number

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/0982151-003	SMRT TAXIS PTE LTD	SHB 939L	GBE 9209C

D.O.A	Time of Accident	Estimate	Tentative repair cost
12/2/2018	15:00	\$35,460.29	\$14,650.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.

Date of Accident

Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5080127283-01	CENTURY EVERGREEN PTE LTD	200911439Z	GCV	Comprehensive	GBE9209G	GBE9209G	29/04/2017	28/04/2018

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 5369K

Vehicle Details

Vehicle No.: SHB939L

Vehicle to be Exported: No

Intended De-registration Date: 26 Feb 2018

Vehicle Make: CHEVROLET

Vehicle Model: EPICA 2.0DSL AT ABS/AB 2WD 4DR TURBO

Primary Colour: Maroon

Manufacturing Year: 2012

Engine No.: Z20S1462666K

Chassis No.: KL1LA69RJBB137674

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$13,994.00

Original Registration Date: 25 Jan 2013

First Registration Date: 25 Jan 2013

Transfer Count: 0

Actual ARF Paid: \$13,994.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 24 Jan 2021

PARF Rebate Amount: \$9,795.00

Intended COE Rebate Details

COE Expiry Date: 24 Jan 2021

COE Category: A - Car (1600cc & below)

CQE Period(Years):	8
PQP Paid:	\$60,655.00
COE Rebate Amount:	\$22,073.00
Total Rebate Amount:	\$31,868.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 26 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2018 15:57
Date Of Accident	12/02/2018 15:00
Exact Location Of Accident	YISHUN AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB939L
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	TAN CHOON HENG
NRIC No	S0101582F
Date Of Birth	09/08/1954
Occupation	OUTDOOR
Date Of Driving Pass	29/08/1979
Driving Experience	38 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	158 BISHAN STREET 13 08-126
Postcode	570158
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : JANICE GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG YISHUN AVE 2 AT THE CENTRE LANE WITH THREE PASSENGERS ON BOARD AND HAD STOPPED DUE TO THE FRONT VEHICLE SJP2556Y HAD STOPPED. SUDDENLY THE VEHICLE GBE9200G FROM BEHIND FAILED TO STOP AND COLLIDED ONTO THE REAR PORTION OF MY TAXI. THE GREAT IMPACT THEN PUSHED MY TAXI SURGED FORWARD AND HIT ONTO THE VEHICLE SJP2556Y. WHEN I ALIGHTED AND CHECKED, I DISCOVERED THAT THERE WAS ANOTHER VEHICLE SHC4274P WHICH WAS IN FRONT OF THE VEHICLE SJP2556Y ALSO INVOLVED IN THIS ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE9209G
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	WANG ZHAOLI
NRIC/Passport Number	G5914000R
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJP2556Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHONG BEE HONG
NRIC/Passport Number	S1809640D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SHC4274P
Vehicle Make/Model/Colour	SMRT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

D-SHC 4274P

C - SJP 2556Y

A - SHB 939L

B - GBE 92096



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

~~_____~~

Driver's Signature
(If driver is not the policyholder)

Date & Time:

12/2/2011

Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

G11A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB939L
Ref. No : TAX/02/18/2084
Reg. Date : 25/01/2013
Vehicle Type : TAXI
Make : CHEVROLET EPICA 2.0 VCDI
Model : EPICA-2.0
Name of Driver : TAN CHOON HENG
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 12/02/2018 03:00:00 PM
Accident Reported Date / Time : 12/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094593
Special Instruction to ARC, if any :
GBE2909G / note / Ready after repair
Prepared Date : 12/02/2018 04:23:18 PM



Chassis No : KL1LA69RJBB137674

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	2,197.00	0.00
Total Spray Painting Charges	3,528.00	0.00
Total Material Charges	19,767.30	19,767.30
Other Charges	2,330.00	0.00
TOTAL	27,822.30 <i>35,460.29</i>	0.00
Lum Sum Total	27,800.00	0.00
No. of Repair Days	14.00	0.00
Prepared / Adjusted By		<i>12 days Lump sum</i> <i>14</i>
Arc / Surveyor Sing Off Date	13/02/2018 08:26:28 AM	01/01/1900 12:00:00 AM

[Signature]

[Signature]

13/02/18 @ 1440

[Signature]
26/2/18

Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/02/2018 06:59:43 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 2/12/2018 7:01:38 PM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	845.00	0.00
TO REPAIR REAR PORTION	1,352.00	0.00
Total Labour	2,197.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00
TO REPSRAY FRONT HOOD	378.00	0.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY REAR BOOT LID	378.00	0.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR MEMBER, LH	180.00	0.00
TO RESPRAY REAR MEMBER, RH	180.00	0.00
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00
TO RESPRAY TAIL LAMP PANEL RH	180.00	0.00
TO RESPRAY REAR FENDER RH	378.00	0.00
TO RESPRAY REAR FENDER LH	378.00	0.00
Total Spray Painting & Panel Beating	3,528.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

	Quotation from AXO	Adjusted by Surveyor, if applicable
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY. & INNER COOLER & AIR CON CONDENSER	120.00	0.00 80
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 140
TO TOP UP A/C GAS	120.00	0.00 80
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO REMOVE & REFIT EXHAUST	120.00	0.00 60
TO REMOVE & REFIT FUEL TANK	120.00	0.00 X
TO ALIGN CHASSIS	350.00	0.00 200
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 X
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00 X
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 140
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	2,330.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
93744489	FRONT	6504592	BUMPER FRT ASSY	1	1,238.00	10.00	1,114.20	Replace	Replace <i>TORN</i>	No
96634053	FRONT	6504681	ABSORBER ENGY FRT BUMPER	1	219.00	10.00	197.10	Replace	Replace <i>CRA</i>	No
96634054	FRONT	6504593	BEAM FRT BUMPER IMPACT	1	465.00	10.00	418.50	Replace	Replace <i>PA</i>	No
	COMMO N		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace <i>SCU</i>	No
	COMMO N		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>CRA</i>	No
96633975	FRONT	6504679	GRILLE BUMPER AIR INL FRT (CTR)	1	41.00	10.00	36.90	Replace	Replace <i>DE</i>	No
96633843	FRONT		GRILLE RADIATOR	1	252.00	10.00	226.80	Replace	Replace <i>CRA</i>	No
96634055	FRONT	6504573	STIFFENER LWR BUMPER	1	120.00	10.00	108.00	Replace	Replace <i>PA</i>	No
96633983			BRACKET FRT BUMPER SIDE LH	1	9.00	10.00	8.10	Replace	Replace <i>ne</i>	No
96633984	FRONT		BRACKET FRT BUMPER SIDE RH	1	9.00	10.00	8.10	Replace	Replace <i>ne</i>	No
96636551	FRONT	6504557	PANEL FRT HOOD	1	1,044.00	10.00	939.60	Replace	Replace <i>PA</i>	No
96635251	FRONT	6504683	GARNISH HOOD (MOULDING)	1	142.00	10.00	127.80	Replace	Replace <i>CRA</i>	No
96637690	FRONT	6504558	INSULATION HOOD	1	186.00	10.00	167.40	Replace	Replace <i>DE</i>	No
96636405	FRONT	6504560	SEAL FRT HOOD	1	11.00	10.00	9.90	Replace	Replace <i>ne</i>	No
96636404	FRONT	6504559	SEAL HOOD LH	1	11.00	10.00	9.90	Replace	Replace <i>ne</i>	No
96636332	FRONT	6504561	HINGE HOOD FRT LH	1	17.00	10.00	15.30	Replace	Replace <i>XSC</i>	No
96636334	FRONT	6504562	HINGE HOOD FRT RH	1	17.00	10.00	15.30	Replace	Replace <i>XSC</i>	No
96636409	FRONT		LATCH FRT HOOD (LOCK)	1	141.00	10.00	126.90	Replace	Replace <i>PA</i>	No
96636419	FRONT		CABLE FRT HOOD RELEASE	1	21.00	10.00	18.90	Replace	Replace <i>XSC</i>	No
96631515	FRONT	6504568	PANEL FRT (SUPPORT PANEL)	1	574.00	10.00	516.60	Replace	Replace <i>PA</i>	No
96634185	FRONT	6504570	COVER RAD GRILL UPR	1	18.00	10.00	16.20	Replace	Replace <i>CRA</i>	No
94530397	FRONT		CLIP,RAD OPG UPR CVR	6	1.00 <i>6</i>	10.00	5.40	Replace	Replace <i>ne</i>	No
			W/HARNESS HEADLAMP	1	271.86	10.00	244.67	Replace	Replace <i>XSC</i>	No
96644858	FRONT	6504614	LAMP HEAD RH	1	841.00	10.00	756.90	Replace	Replace <i>CRA</i>	No
	AIRCON		AIR CON CONDENSER	1	694.00	10.00	624.60	Replace	Replace <i>PA</i>	No
94568291	COMMO N		HOSE A REF, DISCHARGE	1	29.04	10.00	26.14	Replace	Replace <i>PA</i>	No
96941807	COMMO N		PIPE A LIQUID, CONDENSER	1	101.23	10.00	91.11	Replace	Replace <i>PA</i>	No
	COMMO N		INTER COOLER	1	772.00	10.00	694.80	Replace	Replace <i>PA</i>	No
6992838	FRONT	6504645	RADIATOR ASSY	1	1,330.00	10.00	1,197.00	Replace	Replace <i>CRA</i>	No
			COOLANT	1	12.32	0.00	12.32	Replace	Replace <i>ne</i>	No
6801356	FRONT	6504488	HOSE RADIATOR OUTLET (BOTTOM)	1	25.00	10.00	22.50	Replace	Replace <i>XSC</i>	No
6801357	FRONT	6504489	HOSE RADIATOR OUTLET RR	1	13.00	10.00	11.70	Replace	Replace <i>SCU</i>	No

8657-45

Number				(\$)	(%)	(\$)	Recommen d	Surveyor Approved	Photos Attached	
96801355		TEE-RAD OTLT HOSE	1	5.00	10.00	4.50	Replace	Replace ?	No Yes	
96952021	FRONT	6504651	BRACKET RADIATOR LOWER	1	124.00	10.00	111.60	Replace	Replace ?	No Yes
96841894	FRONT		BRACKET RADIATOR UPPER	2	10.00 20	10.00	18.00	Replace	Replace Yes	No
96930811	FRONT	6504646	FAN AUXILIARY	1	369.00	10.00	332.10	Replace	Replace Yes	No
96859678	FRONT	6504648	FAN ENGINE	1	653.00	10.00	587.70	Replace	Replace ?	No Yes
			FAN RESISTOR	1	53.89	10.00	48.50	Replace	Replace ?	No Yes
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace Yes	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace Yes	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace Yes	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace Yes	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace Yes	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace Yes	No
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace Yes	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace Yes	No
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace Yes	No
96647117	COMMO N		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Replace Yes	No
			EXHAUST PIPE MOUNTING, REAR	2	4.40 8.80	10.00	7.92	Replace	Replace Yes	Repair
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace Yes	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace Yes	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace Yes	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace ?	No Yes
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace Yes	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace Yes	No
	COMMO N		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace Yes	No
	COMMO N		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace Yes	No
6851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace Yes	No
6851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace Yes	No
6190751	REAR		LAMP LICENSE	2	56.00 112	10.00	100.80	Replace	Replace Yes	No
3634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace Yes	No
3634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace Yes	No
3634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace Yes	No
993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace Yes	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace Yes	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace Yes	No

9619.43

Number			Qty	Unit Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace <i>PI</i> No
94503739			CLIP, TRIM	4	1.00 <i>4</i>	10.00	3.60	Replace	Replace <i>neu</i> No
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace <i>DE</i> No
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace <i>cut</i> No
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace <i>at</i> No
96932979			COVER BAORD SPARE TYRE	1	661.00	10.00	594.90	Replace	Replace <i>X</i> No
	COMMO N		SPARE TYRE STUD	1	56.59	10.00	50.93	Replace	Replace <i>X</i> No
	COMMO N		BREAKDOWN SIGN	1	35.00	0.00	35.00	Replace	Replace <i>DE</i> No
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace <i>Repair</i> No
			INSULATOR SHEET	1	41.48	10.00	37.33	Replace	Replace <i>X</i> No
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Replace <i>Repair</i> No
	BODY		CHASSIS MEMBER RR RH	1	525.38	10.00	472.84	Replace	Replace <i>Repair</i> No
96399775	COMMO N		W/HARNESS RR DEFOG	1	7.72	10.00	6.95	Replace	Replace <i>X</i> No
96646491	COMMO N		W/HARNESS T / LID	1	83.52	10.00	75.17	Replace	Replace <i>X</i> No
96646502	COMMO N		W/HARNESS TRK ROOM	1	51.74	10.00	46.57	Replace	Replace <i>X</i> No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace <i>scr</i> No
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace <i>Repair</i> No
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace <i>Repair</i> No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>acc</i> No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>neu</i> No
96633557	REAR	6504575	LINER LH REAR FENDER (PROTECTOR)	1	201.00	10.00	180.90	Replace	Replace <i>X</i> No
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace <i>scr</i> No
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace <i>Repair</i> No
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace <i>Repair</i> No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>neu</i> No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>neu</i> No
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace <i>X</i> No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace <i>X</i> No
	COMMO N		SEALANT W/SCREEN	2	37.00 <i>74</i>	0.00	74.00	Replace	Replace <i>X</i> No
TOTAL MATERIALS				9128.41			24,709.11	24,709.12	
TOTAL MATERIALS(Discounted)						19,767.30	19,767.30		

Added Spare Parts / Material Usage After Surveyor Signed off

Number	Quantity	Unit Price (\$)	Discount (%)	Total Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS							



3-3-18 / 13:22
5-3-18 / 08:22

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

14-2-18 / 08:22

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB939L
Ref. No : TAX/02/18/2084
Reg. Date : 25/01/2013
Vehicle Type : TAXI
Make : CHEVROLET EPICA 2.0 VCDI
Model : EPICA-2.0
Name of Driver : TAN CHOON HENG
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 12/02/2018 03:00:00 PM
Accident Reported Date / Time : 12/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : *Rasul*
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094593
Special Instruction to ARC, if any :
GBE2909G - NTUC IDAC
Resurvey after paint, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001
0068. email: rasul@lkkauto.com
Prepared Date : 12/02/2018 04:23:18 PM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date

14-2-18

2nd witness

Date

Supplementary

& Refer to the Supplementary part 1151

QC 3/3/18 9.27 Reject Fan Auxiliary No working 1056 Pass

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 2-2-18

Vehicle Return Time: 17:40

SMRT staff sign: *[Signature]*

TAX/02/18/2084

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB137674

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	2,197.00	1,600.00
Total Spray Painting Charges :	3,528.00	1,800.00
Total Material Charges :	9,207.78	14,105.32
Other Charges :	2,330.00	-2,705.32
TOTAL :	17,262.78	14,800.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	14.00	14.00
Prepared / Adjusted By :		RASUL
Arc / Surveyor Sign Off Date :	13/02/2018 08:26:28 AM	13/02/2018 04:24:26 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 12/02/2018 06:59:43 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0100

Invoice No :

Quotation Date : 4/3

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 2/12/2018 7:01:38 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	845.00	600.00
TO REPAIR REAR PORTION	1,352.00	1,000.00
Total Labour	2,197.00	1,600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO REPSRAY FRONT HOOD	378.00	200.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY REAR BOOT LID	378.00	200.00
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00
TO RESPRAY REAR MEMBER,LH	180.00	100.00
TO RESPRAY REAR MEMBER,RH	180.00	100.00
TO RESPRAY TAIL LAMP PANEL LH	180.00	50.00
TO RESPRAY TAIL LAMP PANEL RH	180.00	50.00
TO RESPRAY REAR FENDER RH	378.00	200.00
TO RESPRAY REAR FENDER LH	378.00	200.00
Total Spray Painting & Panel Beating	3,528.00	1,800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

8055

$$\begin{array}{r}
 + 14105.32 \\
 + 1600.00 \\
 + 2810.00 \\
 \hline
 18,515.32 \\
 - 202 \\
 \hline
 14,812.26 \\
 \hline
 \text{US \$14,800/-}
 \end{array}$$

	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	120.00	80.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	140.00
TO TOP UP A/C GAS	120.00	80.00
TO REMOVE / REFIT SEAT	120.00	0.00
TO REMOVE & REFIT EXHAUST	120.00	60.00
TO REMOVE & REFIT FUEL TANK	120.00	0.00
TO ALIGN CHASSIS	350.00	200.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	140.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REPLACE SUNDRY PARTS	100.00	20.00
TO WASH AND VACUUM	60.00	40.00
Lump Sum Adjustment by Surveyor	0.00	-3,715.32
Total Other Costs	2,330.00	-2,705.32

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93744489	FRONT	6504592	BUMPER FRT ASSY	1	1,238.00	10.00	1,114.20	Replace	Replace	No <input checked="" type="checkbox"/>
96634053	FRONT	6504681	ABSORBER ENGY FRT BUMPER	1	219.00	10.00	197.10	Replace	Replace	No <input checked="" type="checkbox"/>
96634054	FRONT	6504593	BEAM FRT BUMPER IMPACT	1	465.00	10.00	418.50	Replace	Replace	No <input checked="" type="checkbox"/>
	COMMO N		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <input checked="" type="checkbox"/>
	COMMO N		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No <input checked="" type="checkbox"/>
96633975	FRONT	6504679	GRILLE BUMPER AIR INL FRT (CTR)	1	41.00	10.00	36.90	Replace	Replace	No <input checked="" type="checkbox"/>
96633843	FRONT		GRILLE RADIATOR	1	252.00	10.00	226.80	Replace	Replace	No <input checked="" type="checkbox"/>
96634055	FRONT	6504573	STIFFENER LWR BUMPER	1	120.00	10.00	108.00	Replace	Replace	No <input checked="" type="checkbox"/>
96633983			BRACKET FRT BUMPER SIDE LH	1	9.00	10.00	8.10	Replace	Replace	No <input checked="" type="checkbox"/>
96633984	FRONT		BRACKET FRT BUMPER SIDE RH	1	9.00	10.00	8.10	Replace	Replace	No <input checked="" type="checkbox"/>
96636551	FRONT	6504557	PANEL FRT HOOD	1	1,044.00	10.00	939.60	Replace	Replace	No <input checked="" type="checkbox"/>
96635251	FRONT	6504683	GARNISH HOOD (MOULDING)	1	142.00	10.00	127.80	Replace	Replace	No <input checked="" type="checkbox"/>
96637690	FRONT	6504558	INSULATION HOOD	1	186.00	10.00	167.40	Replace	Replace	No <input checked="" type="checkbox"/>
96636405	FRONT	6504560	SEAL FRT HOOD	1	11.00	10.00	9.90	Replace	Replace	No <input checked="" type="checkbox"/>
96636404	FRONT	6504559	SEAL HOOD LH	1	11.00	10.00	9.90	Replace	Replace	No <input checked="" type="checkbox"/>
96636332	FRONT	6504561	HINGE HOOD FRT LH	0	17.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96636334	FRONT	6504562	HINGE HOOD FRT RH	0	17.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96636409	FRONT		LATCH FRT HOOD (LOCK)	1	141.00	10.00	126.90	Replace	Replace	No <input checked="" type="checkbox"/>
96636419	FRONT		CABLE FRT HOOD RELEASE	0	21.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96631515	FRONT	6504568	PANEL FRT (SUPPORT PANEL)	1	574.00	10.00	516.60	Replace	Replace	No <input checked="" type="checkbox"/>
96634185	FRONT	6504570	COVER RAD GRILL UPR	1	18.00	10.00	16.20	Replace	Replace	No <input checked="" type="checkbox"/>
94530397	FRONT		CLIP,RAD OPG UPR CVR	6	1.00	10.00	5.40	Replace	Replace	No <input checked="" type="checkbox"/>
			W/HARNESSE HEADLAMP	0	271.86	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96644858	FRONT	6504614	LAMP HEAD RH	1	841.00	10.00	756.90	Replace	Replace	No <input checked="" type="checkbox"/>
	AIRCON		AIR CON CONDENSER	1	694.00	10.00	624.60	Replace	Replace	No <input checked="" type="checkbox"/>
94568291	COMMO N		HOSE A REF, DISCHARGE	1	29.04	10.00	26.14	Replace	Check	No <input checked="" type="checkbox"/>
96941807	COMMO N		PIPE A LIQUID, CONDERSER	1	101.23	10.00	91.11	Replace	Check	No <input checked="" type="checkbox"/>
	COMMO N		INTER COOLER	1	772.00	10.00	694.80	Replace	Replace	No <input checked="" type="checkbox"/>
96992838	FRONT	6504645	RADIATOR ASSY	1	1,330.00	10.00	1,197.00	Replace	Replace	No <input checked="" type="checkbox"/>
			COOLANT	1	12.32	0.00	12.32	Replace	Replace	No <input checked="" type="checkbox"/>
96801356	FRONT	6504488	HOSE RADIATOR OUTLET (BOTTOM)	0	25.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96801357	FRONT	6504489	HOSE RADIATOR OUTLET RR	0	13.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>

Part Number	Position	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96801355			TEE-RAD OTLT HOSE	1	5.00	10.00	4.50	Replace	Check	No <input checked="" type="checkbox"/>
96952021	FRONT	6504651	BRACKET RADIATOR LOWER	1	124.00	10.00	111.60	Replace	Check	No <input checked="" type="checkbox"/>
96841894	FRONT		BRACKET RADIATOR UPPER	2	10.00	10.00	18.00	Replace	Replace	No <input checked="" type="checkbox"/>
96930811	FRONT	6504646	FAN AUXILIARY	1	369.00	10.00	332.10	Replace	Replace	No <input checked="" type="checkbox"/>
96859678	FRONT	6504648	FAN ENGINE	1	653.00	10.00	587.70	Replace	Replace	No <input checked="" type="checkbox"/>
			FAN RESISTOR	1	53.89	10.00	48.50	Replace	Check	No <input checked="" type="checkbox"/>
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No <input checked="" type="checkbox"/>
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No <input checked="" type="checkbox"/>
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No <input checked="" type="checkbox"/>
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace	No <input checked="" type="checkbox"/>
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace	No <input checked="" type="checkbox"/>
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <input checked="" type="checkbox"/>
96873820	REAR		COVER TOWING EYE RR	0	21.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace	No <input checked="" type="checkbox"/>
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace	No <input checked="" type="checkbox"/>
96847117	COMMON		W/HARNESS RR BPR	0	227.34	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
			EXHAUST PIPE MOUNTING, REAR	2	4.40	100.00	0.00	Replace	Repair	No <input checked="" type="checkbox"/>
96418400			MUFFLER A-EXH,RR	1	2,909.00	100.00	0.00	Replace	Repair	No <input checked="" type="checkbox"/>
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No <input checked="" type="checkbox"/>
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace	No <input checked="" type="checkbox"/>
96976171	REAR	6504635	REAR BOOT REFLECTOR	0	165.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace	No <input checked="" type="checkbox"/>
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace	No <input checked="" type="checkbox"/>
	COMMON		NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <input checked="" type="checkbox"/>
	COMMON		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No <input checked="" type="checkbox"/>
96851765	REAR	6504568	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace	No <input checked="" type="checkbox"/>
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace	No <input checked="" type="checkbox"/>
96190751	REAR		LAMP LICENSE	0	56.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No <input checked="" type="checkbox"/>
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No <input checked="" type="checkbox"/>
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No <input checked="" type="checkbox"/>
96993921	REAR	6504578	TRIM TAIL LID	0	71.00	10.00	0.00	Replace	Not given	No <input checked="" type="checkbox"/>
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No <input checked="" type="checkbox"/>
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <input checked="" type="checkbox"/>

Part Number	Location	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace	No /
94503739			CLIP, TRIM	4	1.00	10.00	3.60	Replace	Replace	No /
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace	No /
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace	No /
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace	No /
96932979			COVER BAORD SPARE TYRE	0	661.00	10.00	0.00	Replace	Not given	No X
	COMMO N		SPARE TYRE STUD	0	56.59	10.00	0.00	Replace	Not given	No X
	COMMO N		BREAKDOWN SIGN	1	35.00	0.00	35.00	Replace	Replace	No /
96515711			PANEL SPARE TYRE	1	2,299.00	100.00	0.00	Replace	Repair	No R
			INSULATOR SHEET	0	41.48	10.00	0.00	Replace	Not given	No X
	BODY		CHASSIS MEMBER RR LH	1	525.38	100.00	0.00	Replace	Repair	No R
	BODY		CHASSIS MEMBER RR RH	1	525.38	100.00	0.00	Replace	Repair	No R
96399775	COMMO N		W/HARNESS RR DEFOG	0	7.72	10.00	0.00	Replace	Not given	No X
96646491	COMMO N		W/HARNESS T / LID	0	83.52	10.00	0.00	Replace	Not given	No X
96646502	COMMO N		W/HARNESS TRK ROOM	0	51.74	10.00	0.00	Replace	Not given	No X
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace	No /
			PANEL TAIL LAMP, LH	1	143.40	100.00	0.00	Replace	Repair	No R
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	100.00	0.00	Replace	Repair	No R
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /
96633557	REAR	6504575	LINER LH REAR FENDER (PROTECTOR)	0	201.00	10.00	0.00	Replace	Not given	No X
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace	No /
			PANEL TAIL LAMP, RH	1	143.40	100.00	0.00	Replace	Repair	No R
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	100.00	0.00	Replace	Repair	No R
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /
			LINER RH REAR FENDER (PROTECTOR)	0	65.00	10.00	0.00	Replace	Not given	No X
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	0	45.00	10.00	0.00	Replace	Not given	No X
	COMMO N		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X
TOTAL MATERIALS								14,387.16	14,105.32	
TOTAL MATERIALS(Discounted)								9,207.78	14,105.32	

Added Spare Parts / Material Usage After Surveyor Signed off

Veron Chen (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Friday, 13 April 2018 8:54 AM
To: Veron Chen (LKKAUTO); Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB939L

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Friday, 13 April 2018 8:38 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Rasul (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB939L

Dear Poh Suan,

To repair rear portion revised to \$800.

Please confirmed Lump Sum \$14,650/- @ 14 days.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 5 March 2018 3:21 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB939L

Hi Rasul,

Attached herewith the repair estimate of SHB 939L having Case No: TAX/02/18/2084.

There is no change to the approved amount of \$14,800 @ 14 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Monday, 5 March 2018 3:18 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

**National Assessment Centre Services**


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18003116/R1vd3e2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 20-04-2018	
		Code: INC4	
1. Policy Particulars : THIRD PARTY CLAIM			
Insured Veh.	GBE 9209G	Veh. Inspected	SHB 939L
Policy No.	5080127283-01	Coverage (\$)	0.00
Claim No.	MT/0982151-003	Excess (\$)	0.00
Assign From		Assign Date	13/02/2018
2. Vehicle Particulars & Condition			
Make & Model	CHEVROLET EPICA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KL1LA69RJBB137674	Colour	MAROON
Odometer	598391	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	FALKEN	5 mm
L/H Front Tyre	205/65 R15	FALKEN	5 mm
R/H Rear Tyre	205/65 R15	FALKEN	5 mm
L/H Rear Tyre	205/65 R15	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/02/2018	Inspection Date	13/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 939L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT ASSY (DISC 10%)	TORN	1,238.00	1,114.20
1	ABSORBER ENGY FRT BUMPER (DISC 10%)	CRACKED	219.00	197.10
1	BEAM FRT BUMPER IMPACT (DISC 10%)	BENT	465.00	418.50
1	GRILLE BUMPER AIR INL FRT (CTR) (DISC 10%)	DEFORMED	41.00	36.90
1	GRILLE RADIATOR (DISC 10%)	CRACKED	252.00	226.80
1	STIFFENER LWR BUMPER (DISC 10%)	BENT	120.00	108.00
1	BRACKET FRT BUMPER SIDE LH (DISC 10%)	NECESSARY	9.00	8.10
1	BRACKET FRT BUMPER SIDE RH (DISC 10%)	NECESSARY	9.00	8.10
1	PANEL FRT HOOD (DISC 10%)	BUCKLED	1,044.00	939.60
1	GARNISH HOOD (MOULDING) (DISC 10%)	CRACKED	142.00	127.80
1	INSULATION HOOD (DISC 10%)	DEFORMED	186.00	167.40
1	SEAL FRT HOOD (DISC 10%)	NECESSARY	11.00	9.90
1	SEAL HOOD LH (DISC 10%)	NECESSARY	11.00	9.90
1	LATCH FRT HOOD (LOCK) (DISC 10%)	BENT	141.00	126.90
1	PANEL FRT (SUPPORT PANEL) (DISC 10%)	BUCKLED	574.00	516.60
1	COVER RAD GRILLE UPR (DISC 10%)	CRACKED	18.00	16.20
6	CLIP, RAD OPG UPR CVR @\$1.00 (DISC 10%)	NECESSARY	6.00	5.40
1	LAMP HEAD RH (DISC 10%)	CRACKED	841.00	756.90
1	AIR CON CONDENSER (DISC 10%)	BENT	694.00	624.60
1	INTER COOLER (DISC 10%)	BENT	772.00	694.80
1	RADIATOR ASSY (DISC 10%)	CRACKED	1,330.00	1,197.00
2	BRACKET RADIATOR @\$10.00 (DISC 10%)	BENT	20.00	18.00
1	FAN AUXILIARY (DISC 10%)	CRACKED	369.00	332.10
1	FAN ENGINE (DISC 10%)	CRACKED	653.00	587.70
1	BUMPER RR (DISC 10%)	DEFORMED	1,238.00	1,114.20
1	ABSORBER ENGY RR BUMPER (DISC 10%)	DEFORMED	70.00	63.00
1	BEAM RR BUMPER IMPACT (DISC 10%)	BENT	1,221.00	1,098.90
1	BRACKET RR BUMPER SIDE LH (DISC 10%)	NECESSARY	49.00	44.10
1	BRACKET RR BUMPER SIDE RH (DISC 10%)	NECESSARY	49.00	44.10
1	REFLECTOR REFLEX RR LH (DISC 10%)	BROKEN	264.00	237.60

Report Ref No. NS/INC18003116/R1vd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REFLECTOR REFLEX RR RH (DISC 10%)	BROKEN	264.00	237.60
1	REAR BOOT LID (DISC 10%)	BENT	974.00	876.60
1	REAR BOOT LOCK (DISC 10%)	BENT	77.00	69.30
1	REAR BOOT STRIKER (DISC 10%)	NECESSARY	15.00	13.50
1	REAR BOOT WEATHERSTRIP (DISC 10%)	CUT	49.00	44.10
1	LAMP BACK UP LH (DISC 10%)	CRACKED	151.00	135.90
1	LAMP BACK UP RH (DISC 10%)	CRACKED	122.00	109.80
1	EMBLEM REAR (DISC 10%)	NECESSARY	44.00	39.60
1	LETTERING:"CHEVROLET" (DISC 10%)	NECESSARY	29.00	26.10
1	LETTERING:"EPICALT" (DISC 10%)	NECESSARY	28.00	25.20
1	PANEL END REAR (DISC 10%)	BENT	255.00	229.50
4	CLIP, TRIM @\$1.00 (DISC 10%)	NECESSARY	4.00	3.60
1	TRIM REAR END PANEL (DISC 10%)	DEFORMED	114.00	102.60
1	TRIM REAR BOOT, LH (DISC 10%)	CUT	125.00	112.50
1	TRIM REAR BOOT, RH (DISC 10%)	CUT	125.00	112.50
1	LAMP RR COMBINATION LH (DISC 10%)	SCRATCHED	415.00	373.50
1	LAMP RR COMBINATION RH (DISC 10%)	SCRATCHED	415.00	373.50
1	NUMBER PLATE (SN)	SCRATCHED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	CRACKED	12.00	12.00
1	COOLANT (SN)	NECESSARY	12.32	12.32
1	SENSOR REVERSE (SN)	NECESSARY	180.00	180.00
1	NUMBER PLATE (SN)	SCRATCHED	15.00	15.00
1	NUMBER PLATE FRAME (SN)	SCRATCHED	12.00	12.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BREAKDOWN SIGN (SN)	DEFORMED	35.00	35.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	HINGE HOOD FRT LH	SERVICEABLE	17.00	-
1	HINGE HOOD FRT RH	SERVICEABLE	17.00	-
1	CABLE FRT HOOD RELEASE	SERVICEABLE	21.00	-

Report Ref No. NS/INC18003116/R1vd3e2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	W/HARNESS HEADLAMP	SERVICEABLE	271.86	-
1	HOSE E REF, DISCHARGE	SERVICEABLE	29.04	-
1	PIPE A LIQUID, CONDENSER	SERVICEABLE	101.23	-
1	HOSE RADIATOR OUTLET (BOTTOM)	SERVICEABLE	25.00	-
1	HOSE RADIATOR OUTLET RR	SERVICEABLE	13.00	-
1	TEE-RAD OTLT HOSE	SERVICEABLE	5.00	-
1	BRACKET RADIATOR LOWER	SERVICEABLE	124.00	-
1	FAN RESISTOR	SERVICEABLE	53.89	-
1	COVER TOWING EYE RR	SERVICEABLE	21.00	-
1	W/HARNESS RR BPR	SERVICEABLE	227.34	-
1	REAR BOOT REFLECTOR	SERVICEABLE	165.00	-
2	LAMP LICENSE @\$56.00	SERVICEABLE	112.00	-
1	TRIM TAIL LID	SERVICEABLE	71.00	-
1	COVER BOARD SPARE TYRE	SERVICEABLE	661.00	-
1	SPARE TYRE STUD	SERVICEABLE	56.59	-
1	INSULATOR SHEET	SERVICEABLE	41.48	-
1	W/HARNESS RR DEOG	SERVICEABLE	7.72	-
1	W/HARNESS T/LID	SERVICEABLE	83.52	-
1	W/HARNESS TRL ROOM	SERVICEABLE	51.74	-
1	LINER LH REAR FENDER (PROTECTOR)	SERVICEABLE	201.00	-
1	LINER RH REAR FENDER (PROTECTOR)	SERVICEABLE	65.00	-
1	MOLDING WINDSCREEN REAR	NOT NECESSARY	45.00	-
2	SEALANT W/SCREEN @\$37.00	NOT NECESSARY	74.00	-
2	EXHAUST PIPE MOUNTING, REAR @\$4.40	TO REPAIR	8.80	-
1	MUFFLER A-EXH, RR	TO REPAIR	2,909.00	-
1	PANEL SPARE TYRE	TO REPAIR	2,299.00	-
1	CHASSIS MEMBER RR LH	TO REPAIR	525.38	-
1	CHASSIS MEMBER RR RH	TO REPAIR	525.38	-
1	PANEL TAIL LAMP, LH	TO REPAIR	143.40	-
1	FENDER LH REAR	TO REPAIR	1,191.00	-
1	PANEL TAIL LAMP, RH	TO REPAIR	143.40	-

Report Ref No. NS/INC18003116/R1vd3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:4 of 4

Qty	Description of Parts	Condition	Estimated By Workshop (\$)	Qty Adjusted (\$)
1	FENDER RH REAR	TO REPAIR	1,467.00	-
			27,405.29	14,105.32
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		4,167.00	2,210.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		3,728.00	1,940.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.		60.00	40.00
			8,055.00	4,210.00
	GRAND TOTAL		35,460.29	18,315.32

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			14,650.00
---	--	--	------------------

Report Ref No. NS/INC18003116/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.