

ASS. REC. BY:

Surveyor

Sebastian

ASSIGNMENT (Office)

From (Person)

Yee Pei Li

of

EGI

Date/Time: 19/2/18 @ 9:05am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMB1394

Insured:

SLQ 65204

at Workshop m/s

SMRT

Tel:

9321 0958

Policy No:

60 woodlands Ind. Prk E 4

Claim No:

DSMPCL800262 / RH / pl

Sum Insured:

Excess:

D.O.A.

02/02/18

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS ^{wp}

Date/Time:

9:37am @ 19/2/18

Person Contacted:

sunny fan

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SMB1394-CC3/AXA13022100/R/sy 33	D.O.A: 02/11/2013
	SLQ 65204 - X	
23/2/18	Email preli revised to Pei Li	
4/6/18	@ 3:09pm Catherine will finalise asap.	
11/7/18	LS \$ 9750 confirmed by email (Recd 4646.89, 3:29)	

ASSIGNMENT

Form: _____ Date: _____

Estimated Cost: _____

CC / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop No: _____

at: _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Secn: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time / Action / Instruction

Veh No: SM8139U Ir Regn: 11/3/2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz Citro 6530 cc 6374Colour: Multi Colour A/C: Insured / Std / Nil / NASp. Reading: 479081 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WEB 62868323120694Gen. Cond: Good / Poor / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModi: AD / S/Rim / STD A/Rim orTyre Size: F: 275/70R22.5R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 6 mm R/Bal: 6/6 mmL/Bal: 6 mm L/Bal: 6/6 mmD.O.A: 7/2/18 D.O.I: 17/2/18Survey held at: SMRT

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 12 DEC 2010

Date/Time, File Pass 1?

☐

: Prel. Report

Date/Time, File Return 1?

☐

: Final Report

1) 1/17 - typist

Report Format:

Lump Sum / L.Bil: TP LS \$9750.2Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

TOTAL

350

Survey Department Check List (Case Handler)

Reference No.: CS EGI 18003120 Svc3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 23/7/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18003120/Svd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 19-02-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 6520U	Veh. Inspected	SMB 139U
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1800262/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	19/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	02/02/2018	Inspection Date	19/02/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAuto)

From: Sathya Sai (LKK Auto)
Sent: Wednesday, 11 July 2018 2:31 PM
To: catherineleesc@smrt.com.sg
Cc: Veron Chen (LKKAuto); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Gerald Tan
Subject: Chwee Hock (Auto Svcs/ARC)
Attachments: FINALIZE-SMB 139U (BUS/02/18/1008)
SMB 139 FINALISE.pdf

Good Day,

Please refer to attachment for finalisation.

Thank you

Best Regards,

Sathya Sai | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9807 2012 | Email: SathyaSai@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 19 February 2018 9:05 AM
To: 'admin-d@lkkauto.com'
Subject: OI : SLQ6520U / TP : SMB139U/LKK / DOA : 02/02/2018 (DSMPC1800262)
Attachments: SLQ6520U - SAS.pdf; SMB139U - SAS.pdf; SMB139U - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SUNNY TAN @ 9321 0958

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Obtain estimate and please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 14.02.2018
Our Reference: DSMPC1800262/RH/pl
Your Reference: SMB 139U

Sent via Fax

or

Email

TanAhLeong@smrt.com.sg

To: SMRT AUTOMOTIVE SERVICES PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SMB 139U
Insured's Vehicle: SLQ 6520U
Date Of Accident: 02.02.2018


We acknowledge receipt of your request for PRS on: 14.02.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us to date.
☒	Others: <u>OFFICER-IN-CHARGE - ROHAINI</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 23 February 2018 8:14 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: SLQ6520U / TP : SMB139U/LKK / DOA : 02/02/2018 (DSMPC1800262)
Attachments: PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SMB 139U
Date of survey: 19/2/2018
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 19 February 2018 9:39 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLQ6520U / TP : SMB139U/LKK / DOA : 02/02/2018 (DSMPC1800262)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 19 February 2018 9:05 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SLQ6520U / TP : SMB139U/LKK / DOA : 02/02/2018 (DSMPC1800262)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD.**

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SUNNY TAN @ 9321 0958

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Obtain estimate and please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and third party SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1800262/RH/pl

Our Ref: CS/EGII8003120/Svd3

Date: 23/2/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SMB 139U


We thank you for your instruction on 19/2/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/2/2018 at the premises of M/s SMRT AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$12,262.42
Revised Estimate Amount	: S\$10,792.98
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

YEANG WAI KEEN

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2292D
Vehicle Details	
Vehicle No.:	SMB139U
Vehicle to be Exported:	No
Intended De-registration Date:	20 Feb 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CITARO O530
Primary Colour:	Multi-Colour
Manufacturing Year:	2010
Engine No.:	90292600847644
Chassis No.:	WEB62808323120694
Maximum Power Output:	-
Open Market Value:	\$282,480.00
Original Registration Date:	11 Mar 2011
First Registration Date:	11 Mar 2011
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-

PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00


The information contained herein is correct as at 20 Feb 2018

OK

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB139U
Ref. No : BUS/02/18/1008
Reg. Date : 09/02/2018
Vehicle Type : BUS -12M
Make : MBOC500 (MERCEDES)
Model : MB CITARO O530
Name of Driver : Chen Haiqing
Type of Accident : HEAD TO REAR
Date / Time of Accident : 02/02/2018 06:52:00 AM
Accident Reported Date / Time : 07/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : SHC Capital Ltd
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No :
Special Instruction to ARC, if any :
SMB139U - REAR RIGHT PORTION
SLQ6520U (TP) - INSURED WITH ERGO INSURANCE (SHC)
Prepared Date : 09/02/2018 04:35:48 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

Sebastian

- hump Sun Repair.
- place After Paint.

90036121

Sebastianyong@lkkauto.com

8/1/2018

Chassis No :

Work Shop :

Summary of Repair Estimates

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Quotation from ARC

2,120.00

878.00

8,337.98

0.00

11,335.98

11,350.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

4.00

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

0.00

Adjusted by Surveyor, if applicable

0.00

0.00

8,337.98

0.00

0.00

0.00

0.00

0.00

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	2,120.00	0.00 1855
Total Labour	2,120.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	878.00	0.00 600
Total Spray Painting & Panel Beating	878.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
62875032	RIGHT	6010141	FLAP RADIATOR FOR CITARO	1	5,445.00	10.00	4,900.50	Replace	Replace	No <i>Defect</i>
	REAR	6009909	REAR BUMPER RH	1	837.84	10.00	754.06	Replace	Replace	No <i>✓ CRK</i>
	REAR	6009911	BRACKET REAR BUMPER RH	1	45.51	10.00	40.96	Replace	Replace	No <i>✓ MS</i>
	REAR	6009887	CHERIS PIN W HEAD	4	3.00 <i>12</i>	10.00	10.80	Replace	Replace	No <i>✓ N/C</i>
	REAR	6009892	BRACKET BOTTOM RH	1	135.90	10.00	122.31	Replace	Replace	No <i>✓ MS</i>
	REAR	6010010	EXTERIOR LAMP	1	63.15	10.00	56.83	Replace	Replace	No <i>✓ MS</i>
	REAR	6010011	BRACKET	1	99.90	10.00	89.91	Replace	Replace	No <i>✓ N/C</i>
	REAR	6009886	BRACKET 738mm	1	306.24	10.00	275.62	Replace	Replace	No <i>✓ BT</i>
	REAR	6009880	REAR TAIL LAMP RH	1	1,261.71	10.00	1,135.54	Replace	Replace	No <i>✓ CRK</i>
	REAR	6009881	REAR TAIL LAMP BRACKET RH	1	538.14	10.00	484.33	Replace	Replace	No <i>✓ BT</i>
	REAR	6009888	COUPLING	1	19.39	10.00	8.45	Replace	Replace	No <i>✓ N/C</i>
	REAR	6009889	BRACKET TOP RH	1	196.05	10.00	176.44	Replace	Replace	No <i>✓ N/C</i>
00054469	VE	6010012	SIDE MARKER LAMP	1	194.50	10.00	85.05	Replace	Replace	No <i>✓ MS</i>
11	REAR	6009894	BRACKET RH	1	1219.09	10.00	197.18	Replace	Replace	No <i>✓ BT</i>
TOTAL MATERIALS								8,337.98	8,337.98	
TOTAL MATERIALS(Discounted)								8,337.98	8,337.98	


Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB139U
 Ref. No : BUS/02/18/1008
 Reg. Date : 11/03/2011
 Vehicle Type : BUS -12M
 Make : MBOC500 (MERCEDES)
 Model : MB CITARO O530
 Name of Driver : Chen Haiqing
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 02/02/2018 06:52:00 AM
 Accident Reported Date / Time : 07/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : SHC Capital Ltd
 Vehicle is Towed Back? : No
 Towed Back Date/Time : 01/01/2000
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094676
 Special Instruction to ARC,if any :
 SMB139U - REAR RIGHT PORTION
 SLQ6520U (TP) - INSURED WITH ERGO INSURANCE (SHC)
 Prepared Date : 09/02/2018 04:35:48 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : WEB62808323120694

Mileage

0

Work Shop :

Repair Completed Date / Time :

01/01/2000

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 2,120.00

1,855.00

Total Spray Painting Charges : 878.00

600.00

Total Material Charges : 7,288.32

14 396.89

7,288.32

Other Charges : 0.00

0.00

TOTAL : 10,286.32**9,743.32****Lump Sum Total : 10,300.00****9,750.00**

No. of Repair Days : 4.00

3.00 ✓

Prepared / Adjusted By :

SEBASTIAN-LKK

Arc / Surveyor Sign Off Date : 14/02/2018 11:18:23 AM

19/02/2018 06:22:54 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 14/02/2018 11:17:07 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	2,120.00	1,855.00 ✓
Total Labour	2,120.00	1,855.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	878.00	600.00 ✓
Total Spray Painting & Panel Beating	878.00	600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
6287503206	RIGHT	6010141	FLAP RADIATOR FOR CITARO	1	5,445.00	10.00	4,900.50	Replace	Replace	No ✓	Deform
	REAR	6009909	REAR BUMPER RH	1	837.84	10.00	754.06	Replace	Replace	No ✓	CRK
	REAR	6009911	BRACKET REAR BUMPER RH	1	45.51	10.00	40.96	Replace	Replace	No ✓	MS
	REAR	6009887	CHERIS PIN W HEAD	4	3.00	10.00	10.80	Replace	Replace	No ✓	NEC
	REAR	6009892	BRACKET BOTTOM RH	1	135.90	100.00	0.00	Replace	Repair	No R	
	REAR	6010010	EXTERIOR LAMP	1	63.15	10.00	56.83	Replace	Replace	No ✓	MS
	REAR	6010011	BRACKET	1	99.90	100.00	0.00	Replace	Repair	No R	
	REAR	6009886	BRACKET 738mm	1	306.24	100.00	0.00	Replace	Repair	No R	
	REAR	6009880	REAR TAIL LAMP RH	1	1,261.71	10.00	1,135.54	Replace	Replace	No ✓	CRK
	REAR	6009881	REAR TAIL LAMP BRACKET RH	1	538.14	100.00	0.00	Replace	Repair	No R	
	REAR	6009888	COUPLING	1	9.39	10.00	8.45	Replace	Replace	No ✓	NEC
	REAR	6009889	BRACKET TOP RH	1	196.05	100.00	0.00	Replace	Repair	No R	
0005446911	VE	6010012	SIDE MARKER LAMP	1	94.50	10.00	85.05	Replace	Replace	No ✓	MS
	REAR	6009894	BRACKET RH	1	219.09	10.00	197.18	Replace	Replace	No ✓	BT
	REAR	6009884	BRACKET 760mm	1	343.14	10.00	308.83	Replace	Replace	No ✓	BT
	REAR	6009907	REAR BUMPER CENTER	1	1,791.33	10.00	1,612.20	Replace	Replace	No ✓	BT
TOTAL MATERIALS							9,110.39	9,110.40			
TOTAL MATERIALS(Discounted)							7,288.32	7,288.32			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	REAR	BRACKET 760mm	1	343.14	10.00	308.83	Replace	Replace	No
	REAR	REAR BUMPER CENTER	1	1,791.33	10.00	1,612.20	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						1,921.03			

$$\begin{array}{r}
 9110.4 \\
 - 20\% \\
 \hline
 7288.32 \\
 + 1855 \\
 + 600 \\
 \hline
 9743.32
 \end{array}$$

L/s: \$9750 @ 3 days confirmed.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18003120/Vvd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 13-07-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLQ 6520U	Veh. Inspected	SMB 139U	
Policy No.		Coverage (\$)	0.00	
Claim No.	DSMPC1800262/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	19/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CITARO O530	c.c	6374	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WEB62808323120694	Colour	MULTI	
Odometer	479081	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	CONTINENTAL	6 mm	
L/H Front Tyre	275/70 R22.5	CONTINENTAL	6 mm	
R/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	6/6 mm	
L/H Rear Tyre	275/70 R22.5 (D)	CONTINENTAL	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2018	Inspection Date	19/02/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 139U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FLAP RADIATOR FOR CITARO	DEFORMED	5,445.00	5,445.00
1	REAR BUMPER RH	CRACKED	837.84	837.84
1	BRACKET REAR BUMPER RH	MISSING	45.51	45.51
4	CHERIS PIN W HEAD @\$3.00	NECESSARY	12.00	12.00
1	EXTERIOR LAMP	MISSING	63.15	63.15
1	REAR TAIL LAMP RH	CRACKED	1,261.71	1,261.71
1	COUPLING	NECESSARY	9.39	9.39
1	SIDE MARKER LAMP	MISSING	94.50	94.50
1	BRACKET RH	BENT	219.09	219.09
1	BRACKET 760MM	BENT	343.14	343.14
1	REAR BUMPER CENTER	BENT	1,791.33	1,791.33
1	BRACKET BOTTOM RH	TO REPAIR SEE LABOUR	135.90	-
1	BRACKET	TO REPAIR SEE LABOUR	99.90	-
1	BRACKET 738MM	TO REPAIR SEE LABOUR	306.24	-
1	REAR TAIL LAM BRACKET RH	TO REPAIR SEE LABOUR	538.14	-
1	BRACKET TOP RH	TO REPAIR SEE LABOUR	196.05	-
	LESS 10% DISCOUNT		-	-1,012.26
			11,398.89	9,110.40
	LABOUR			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF BRACKET BOTTOM RH,BRACKET,BRACKET 738MM,REAR TAIL LAM BRACKET RH AND BRACKET TOP RH.		2,120.00	1,855.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		878.00	600.00
			2,998.00	2,455.00
	GRAND TOTAL		14,396.89	11,565.40

Report Ref No. CS/EGI18003120/Vvd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,750.00
---	--	--	----------

Report Ref No. CS/EGI18003120/Vvd3n2

SATHYA SAI KATHIRRASEN
Asst. Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.