

22/03/2002

ASS. REC. BY:

REF: CS/MSG18003123/1110302

Special Instruction:

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

joslin Lim

of

MSG

Date/Time:

15/2/18 @ 9.44am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 520X

Insured:

at Workshop m/s

SME Motor

Tel:

6747 6106

of

J. kaki Bk Ave 6 # 02-15 Auto bay

Policy No:

A80446414 QMX

Claim No:

549425

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

09/02/2018

CA

☒ REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:15am @ 15/2/18

Person Contacted:

Frankie

Vehicle IN / ☒ OUT

Date/Time

Action/Instruction

(✓)

Estimate

work closed for CNY, open on 20/2/18

SKQ 520X - X

20/2-

Revert via merimen

26/2 @

2:03pm authorise repair by Keny Ong

26/2 @

3:40pm email to Sebastian excess \$500

(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/MSG 18003123/4703

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SKQ520Xat Workshop m/s Sum

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 68k.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 18.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKQ520X Yr Regn: 10114Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Honda vere / c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 119228 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11008777Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60216

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 9/2/18 D.O.I. 20/2/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 48892Dep 95006.5CNY 16-162/4/18 16802.40 cont'd with AH 4/18. (Red: 3108.40:15%)

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report1) 4/1 Typist

Date/Time, File Return to?

2) _____

Report Format : ODLump Sum / I.B.I. (\$) 16,802.40

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

<u>300</u>
<u>10</u>
<u>310</u>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003123/Utd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 19-02-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKQ 520X
Policy No.	A80446414QMX	Coverage (\$)	0.00
Claim No.	549425	Excess (\$)	500.00
Assign From	MERIMEN (JOSLIN LIM)	Assign Date	19/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/02/2018	Inspection Date	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Feb 2018 Sendback Est	12 Feb 2018 10:33 \$18,849.30	15 Feb 2018 09:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NG CHYE CHOON, ID: S1580250B, Tel: +6585333199, Email: NOEMAIL		
Vehicle Reg. No.:	SKQ520X	Date of Loss:	09/02/2018 08:00 - :59
Claim Type:	OD / 549425	Policy/Cover Note No.:	A80446414QMX (Comprehensive) Coverage: 30/10/2017 - 29/10/2018
		Excess:	\$500.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/02/2018]		
Driver/Custodian:	NG CHYE CHOON (54 / Male), NRIC: S1580250B, Tel: +6585333199		
Adj Asg. Remarks:	URGENT. Please survey and revert.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 26 February 2018 3:40 PM
To: sebastian@smemotor.com.sg
Cc: SUR
Subject: VEHICLE SKQ 520X (DOA: 09/02/2018)

Dear Sebastian,

As spoken with you.

As instructed by our client MSIG , please proceed to repair the insured vehicle **SKQ 520X (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	12 Feb 2018 10:09	Clm Veh Model Changed	(204808) HONDA VEZEL 1.5 (A).	[R] Chia Pei Ying
2	12 Feb 2018 10:09	Clm Created	Reg No: SKQ520X. Policy No: A80446414QMX. Acct Date: 2018/02/09. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: SME Motor Pte Ltd (Kaki Bukit). Created from SAS:MSME18020608	[R] Chia Pei Ying
3	12 Feb 2018 10:33	Clm Submitted	18849.30.	[R] Chia Pei Ying
4	15 Feb 2018 08:24	Clm Registration Modified	Excess: -> 500.00.	[I] Joslin Lim
5	15 Feb 2018 08:24	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor): Please survey and authorise if consistent.	[I] Joslin Lim
6	15 Feb 2018 08:24	Adj Next Rpt Changed	Next Rpt: Im. Advice. Due Date: 2018/02/16	[I] Joslin Lim
7	15 Feb 2018 08:24	Adj Mandate Set	Approved: 25000.00. Reinsp: Adj decides.	[I] Joslin Lim
8	15 Feb 2018 08:37	Assignment 1st Accessed		[A] Ho Pei Fang
9	15 Feb 2018 09:43	Adj Assignment Cancelled	I.H.S unable to survey	[I] Joslin Lim
10	15 Feb 2018 09:43	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Joslin Lim
11	15 Feb 2018 09:44	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ): URGENT. Please survey and revert.	[I] Joslin Lim
12	15 Feb 2018 09:44	Adj Next Rpt Changed	Next Rpt: Im. Advice. Due Date: 2018/02/16	[I] Joslin Lim
13	15 Feb 2018 09:44	Adj Mandate Set	Approved: 25000.00. Reinsp: Adj decides.	[I] Joslin Lim
14	15 Feb 2018 10:11	Assignment 1st Accessed		[A] Nivitha Govindasamy
15	19 Feb 2018 14:07	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
16	20 Feb 2018 16:22	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
17	20 Feb 2018 16:29	Adj Im. Advice Submitted	Next Rpt: Final Rpt. Due Date: 2018/03/17	[A] DENISE TAY KWEE CHENG
18	20 Feb 2018 16:29	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2018/03/17	[A] DENISE TAY KWEE CHENG
19	20 Feb 2018 16:37	Adj Mandate Request	Cur. Req: 17406.30: DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
20	26 Feb 2018 12:03	Adj Next Rpt Changed	Next Rpt: Final Rpt. Due Date: 2018/03/17. Mandate Remarks: check items to be verified	[I] Keny Ong Thiam Beng
21	26 Feb 2018 12:03	Adj Mandate Set	Approved: 14349.40: check items to be verified	[I] Keny Ong Thiam Beng

ACTIVITY

[15/02/2018 08:45] Ho Pei Fang:
Frankie informed w/shop has close for CNY, to survey on 20/02/18, car in.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1721248	12/02/2018 10:09	Motor	SME Motor Pte Ltd	SME Motor Pte Ltd (Kaki Bukit)	SKQ520X		xx.xx
1727202	20/02/2018 16:22	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKQ520X		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 20 Feb 2018

Preliminary Advice

Vehicle No	: SKQ520X	Accident Date	: 09/02/2018
Make	: HONDA VEZEL	Policy No.	: A80446414QMX
Assignment Date	: 15/02/2018	Excess	: S\$500.00
Date of Inspection	: 20/02/2018	Est. Duration of Repair	: 10.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,849.30
Revised Amount	:S\$	14,349.40
Check Items (Estimated)	:S\$	3,056.90
Total	:S\$	17,406.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	48,892.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,108.00

Remarks

- (x) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0250B

Vehicle Details

Vehicle No.: SKQ520X
Vehicle to be Exported: No
Intended De-registration Date: 20 Feb 2018
Vehicle Make: HONDA
Vehicle Model: VEZEL 1.5G A
Primary Colour: Blue
Manufacturing Year: 2014
Engine No.: L15B3508792
Chassis No.: RU11008777
Maximum Power Output: 96.0 kW (128 bhp)
Open Market Value: \$18,104.00
Original Registration Date: 30 Oct 2014
First Registration Date: 30 Oct 2014
Transfer Count: 0
Actual ARF Paid: \$8,104.00 *↓ 0.5 ~*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Oct 2024
PARF Rebate Amount: \$6,078.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2024
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$63,990.00
COE Rebate Amount: \$42,814.00
Total Rebate Amount: \$48,892.00

The information contained herein is correct as at 20 Feb 2018

OK

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

sgCarMart.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

YOUR ONLY PLACE FOR
CERTIFIED PRE-OWNED BMW.
PERFORMANCE PREMIUM SELECTION

View available cars



Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Jan 2010 A5 Coupe \$49.8k, 87k Km, 1 Year Warranty.



No Repair, Zero Worries, 1 Year
Unlimited Mileage With
Workshop By Insurance Co.
360 VR Cars StarAd

▪ Free VICOM evaluation
▪ Free grooming and 6 months maintenance
▪ In-house workshop ensures quality service
▪ Member of SVTA and hire purchase association
▪ 100% deposit refund for unapproved loan



YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted

20 results/page

1 vehicles

Honda Vezel

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Vezel		Any	Any	2014	Any	Any	Any	Available
	Honda Vezel	1.5A X	\$72,800	\$10,160 /yr	20-Oct-2014	1,496 cc	-	SUV	Available

Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Excellent After Sales Service Assured. Come Visit Our Air-conditioned Showroom To Appreciate It In Mint Condition Tod...

Dickson Automobile

Posted: 15-Dec-2017 Tags: 2014 Honda Vezel, Honda Vezel, Honda, Vezel, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
--	------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Vezel, Honda Vezel Singapore, used Honda Vezel Singapore, used Honda Vezel, used vehicles Singapore or even buy used Honda Vezel Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

• Home

• New Car

• Used Car

• Sell Car

• Motoring Directory

• Products Guide

• Article

• Forum

• Tool & Tip

• About Us

• Careers

• Contact Us

• Sitemap

© 2004-2018 sgCarMart. All rights reserved.

• Terms of Service

• Privacy Policy

• Personal Data Protection Statement

Compare

http://www.sgcarmart.com/used_cars/listing.php?MOD=Honda+Vezel&AVL=2&RPG=20&AVL=2&V... 20-Feb-18

Address	BLK 207 PASIR RIS ST 21 #11-364
Postcode	510207
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

FRONT VEHICLE SUDDENLY STOP. I CANNOT STOP IN TIME AND HIT VEHICLE B. VEHICLE B FORWARD AND HIT VEHICLE C.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDT705Y
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.

same

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	18/MSIG/OD-078 (02)
Policy No:	A80446414QMX	Date of Loss:	09/02/2018
Vehicle Reg. No.:	SKQ520X	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG CHYE CHOON	Contact No:	+6585333199
Driver:	NG CHYE CHOON		

Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	30/10/2014
Vehicle Colour:	BLUE	Chassis No:	RU11008777
Engine No:	L15B3508792		
Odometer:	0 KM		

Paint Type:

Total Loss? NO

Est. Duration of Repair 14 (day)

Not Authorized
make
take photo before repair.
20/2/18
Excess \$500?

Description of Accident/Loss FRONT VEHICLE SUDDENLY STOP. I CANNOT STOP IN TIME AND HIT VEHICLE B. VEHICLE B FORWARD AND HIT VEHICLE C.

Remarks: VEHICLE IN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

Parts	• To resurvey before after spray painting	15,304.30
Miscellaneous Items	• To display damaged part(s) during resurvey	65.00
Labour	• Parts prices are subject to confirmation	3,480.00
Paintwork Labour	• Third party survey is on a "Without Prejudice" basis	0.00
Towing	• No illegal modification(s) is allowed	0.00
	• Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company	
	Calculated Gross Total (\$\$)	18,849.30
	Acknowledged by Repairer	
	- Excess (\$\$)	500.00
	Signature:	
	Date:	
	(\$\$)	18,349.30
	+ GST 7.00% (\$\$)	1,284.45
	Nett Amount (\$\$)	19,633.75

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This claim is handled by: **CHIA PEI YING**

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 12 Feb 2018)

Parts: M1-SUV **HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: **SME Motor Pte Ltd/SKQ520X/12/02/2018 10:33**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>See</i>	0.00	0.00	*430.00 F
2	2		*FRT BONNET HINGE <i>See</i>	0.00	0.00	*80.00 F
3	2		*FRT BONNET RUBBER (SHORT) <i>See</i>	0.00	0.00	*44.00 F
4	2		*FRT BONNET RUBBER (LONG) <i>See</i>	0.00	0.00	*50.00 F
5	1		*FRT BONNET INSULATOR <i>See</i>	0.00	0.00	*105.00 F
6	8		*INSULATOR CLIP <i>See</i>	0.00	0.00	*16.00 F
7	1		*FRT BONNET LOCK <i>See</i>	0.00	0.00	*90.00 F
8	1		*FRT BONNET LOCK CABLE <i>See</i>	0.00	0.00	*40.00 F
9	1		*FRT BONNET LOCK COVER <i>See</i>	0.00	0.00	*20.00 F
10	1		*FRT GRILLE <i>See</i>	0.00	0.00	*185.00 F
11	1		*FRT GRILLE OUTER GARNISH <i>See</i>	0.00	0.00	*150.00 F
12	2		*GRILLE CHROME <i>See</i>	0.00	0.00	*60.00 F
13	1		*GRILLE CENTER LOGO <i>See</i>	0.00	0.00	*18.00 F
14	4		*GRILLE CLIP <i>See</i>	0.00	0.00	*8.00 F
15	1		*FRT BUMPER <i>See</i>	0.00	0.00	*205.00 F
16	2		*FRT BUMPER RETAINER <i>See</i>	0.00	0.00	*30.00 F
17	10		*FRT BUMPER CLIP <i>See</i>	0.00	0.00	*20.00 F
18	1		*FRT BUMPER TOWING COVER <i>See</i>	0.00	0.00	*12.00 F
19	1		*FRT BUMPER LOWER GRILLE <i>See</i>	0.00	0.00	*55.00 F
20	1		*FRT BUMPER FOG LAMP GARNISH RH <i>See</i>	0.00	0.00	*22.00 F
21	2		*FRT BUMPER FOG LAMP ASSY <i>See</i>	0.00	0.00	*300.00 F
22	1		*FRT BUMPER LOWER SPOILER	0.00	0.00	*140.00 F
23	1	<i>See</i>	*FRT BUMPER LOWER SPOILER CHROME <i>See</i> SAMPLE	0.00	0.00	-
24	1		*FRT BUMPER REINFORCEMENT <i>See</i>	0.00	0.00	*280.00 F
25	2		*HEADLAMP <i>See</i>	0.00	0.00	*1,700.00 F
26	1		*HEADLAMP SUPPORT PANEL <i>See</i>	0.00	0.00	*385.00 F
27	1		*HEADLAMP SUPPORT PANEL TOP GARNISH <i>See</i>	0.00	0.00	*40.00 F
28	8		*TOP GARNISH CLIP <i>See</i>	0.00	0.00	*16.00 F
29	1		*AIRCON CONDENSER <i>See</i>	0.00	0.00	*350.00 F
30	1		*RADIATOR <i>See</i>	0.00	0.00	*760.00 F
31	1		*AIRCON MOTOR <i>See</i>	0.00	0.00	*180.00 F
32	1		*AIRCON MOTOR COWLING <i>See</i>	0.00	0.00	*85.00 F
33	1		*AIRCON FAN BLADE <i>See</i>	0.00	0.00	*55.00 F
34	1		*AIRCON COOLING PIPE <i>See</i>	0.00	0.00	*110.00 F
35	1		*AIRCON DISCHARGE PIPE <i>See</i>	0.00	0.00	*130.00 F
36	1		*RADIATOR MOTOR <i>See</i>	0.00	0.00	*260.00 F
37	1		*RADIATOR MOTOR COWLING <i>See</i>	0.00	0.00	*80.00 F
38	1		*RADIATOR FAN BLADE <i>See</i>	0.00	0.00	*50.00 F
39	1		*RADIATOR TOP HOSE <i>See</i>	0.00	0.00	*28.00 F
40	1		*RADIATOR LOWER HOSE <i>See</i>	0.00	0.00	*25.00 F

SME Motor Pte Ltd/SKQ520X/12/02/2018 10:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
41	1		*INTAKE MANIFOLD <i>one</i>	0.00	0.00	*350.00 F	<i>✓</i>
42	1		*INTAKE MANIFOLD AIR PIPE <i>To.1</i>	0.00	0.00	*20.00 F	<i>✓</i>
43	1		*INTAKE MANIFOLD AIR PIPE CLIP <i>11</i>	0.00	0.00	*6.00 F	<i>X</i>
44	1		*AIR DUCT <i>7w/</i>	0.00	0.00	*75.00 F	<i>✓</i>
45	1		*AIR HOSE <i>7w/</i>	0.00	0.00	*40.00 F	<i>✓</i>
46	1		*ALTERNATOR <i>11</i>	0.00	0.00	*980.00 F	<i>X</i>
47	1		*WIPER CORNER GARNISH LH <i>11</i>	0.00	0.00	*25.00 F	<i>X</i>
48	1		*ENGINE MOUNTING RH <i>11</i>	0.00	0.00	*105.00 F	<i>X</i>
49	1		*ENGINE MOUNTING LH <i>11</i>	0.00	0.00	*150.00 F	<i>X</i>
50	1		*RADIATOR SPARE TANK <i>22</i>	0.00	0.00	*30.00 F	<i>✓</i>
51	1		*FRT RH FENDER <i>11</i>	0.00	0.00	*205.00 F	<i>X</i>
52	2		*FRT RH FENDER PROTECTOR <i>To.1</i>	0.00	0.00	*90.00 F	<i>✓</i>
53	12		*FRT RH FENDER PROTECTOR CLIP <i>rec</i>	0.00	0.00	*24.00 F	<i>✓</i>
54	2		*FRT FENDER INNER COWLING <i>11</i>	0.00	0.00	*140.00 F	<i>X</i>
55	20		*INNER COWLING CLIP <i>11</i>	0.00	0.00	*40.00 F	<i>X</i>
56	1		*FRT ENGINE UNDER COVER <i>11</i>	0.00	0.00	*95.00 F	<i>X</i>
57	12		*FRT ENGINE UNDER COVER CLIP <i>rec</i>	0.00	0.00	*24.00 F	<i>✓</i>
58	1		*HORN <i>one</i>	0.00	0.00	*45.00 F	<i>✓</i>
59	1		*STEERING AIRBAG <i>same</i>	0.00	0.00	*860.00 F	<i>✓</i>
60	1		*FRT PASSENGER AIRBAG <i>same</i>	0.00	0.00	*1,380.00 F	<i>✓</i>
61	1		*AIRBAG CONTROL UNIT <i>same</i>	0.00	0.00	*650.00 F	<i>✓</i>
62	1		*CLOCK SENSOR <i>same</i>	0.00	0.00	*185.00 F	<i>✓</i>
63	2		*FRT SAFETY BELT <i>same</i>	0.00	0.00	*990.00 F	<i>✓</i>
64	1		*DASHBOARD <i>To.1</i>	0.00	0.00	*720.00 F	<i>✓</i>
65	1		*4 LIT ATF <i>11</i>	0.00	0.00	*70.00 F	<i>X</i>

F=Franchise part.

Sub Total (S\$)	13,913.00
+ Margin on L,N Items 10.00% (S\$)	1,391.30
Total Parts (S\$)	15,304.30

SME Motor Pte Ltd/SKQ520X/12/02/2018 10:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1-12884
10%
14172.40

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	NUMBER PLATE <i>ms</i>	40.00 <i>35</i>
2	1	RADIATOR COOLANT <i>ru</i>	25.00 ✓
Sub Total (S\$)			65.00 <i>60</i>

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	REMOVE & REFIX ENGINE	New <i>11</i>	350.00 <i>X</i>
4	REMOVE & REFIX 2 PCS SAFETY BELT AND AIRBAG SYSTEM	New	250.00 <i>300</i>
5	REPROGRAMME AIRBAG SYSTEM	New	200.00
6	REMOVE & REFIX DASHBOARD	New	250.00 ✓
7	LABOUR CHARGE	New	1,200.00 <i>900</i>
8	SPRAY PAINTING	New	1,100.00 <i>1000</i>
Gross Labour Cost (S\$)			3,480.00 <i>2870</i>

SME Motor Pte Ltd/SKQ520X/12/02/2018 10:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
41	1		*INTAKE MANIFOLD <i>one</i>	0.00	0.00	*350.00 F	✓
42	1		*INTAKE MANIFOLD AIR PIPE <i>To 1</i>	0.00	0.00	*20.00 F	✓
43	1		*INTAKE MANIFOLD AIR PIPE CLIP <i>11</i>	0.00	0.00	*6.00 F	✓
44	1		*AIR DUCT <i>7w/</i>	0.00	0.00	*75.00 F	✓
45	1		*AIR HOSE <i>7w/</i>	0.00	0.00	*40.00 F	✓
46	1		*ALTERNATOR	0.00	0.00	*980.00 F	✓
47	1		*WIPER CORNER GARNISH LH	0.00	0.00	*25.00 F	X
48	1		*ENGINE MOUNTING RH <i>11</i>	0.00	0.00	*105.00 F	✓
49	1		*ENGINE MOUNTING LH	0.00	0.00	*150.00 F	✓
50	1		*RADIATOR SPARE TANK <i>one</i>	0.00	0.00	*30.00 F	✓
51	1		*FRT RH FENDER <i>one</i>	0.00	0.00	*205.00 F	X
52	2		*FRT RH FENDER PROTECTOR <i>To 1</i>	0.00	0.00	*90.00 F	✓
53	12		*FRT RH FENDER PROTECTOR CLIP <i>one</i>	0.00	0.00	*24.00 F	✓
54	2		*FRT FENDER INNER COWLING <i>11</i>	0.00	0.00	*140.00 F	X
55	20		*INNER COWLING CLIP <i>11</i>	0.00	0.00	*40.00 F	X
56	1		*FRT ENGINE UNDER COVER	0.00	0.00	*95.00 F	✓
57	12		*FRT ENGINE UNDER COVER CLIP <i>one</i>	0.00	0.00	*24.00 F	✓
58	1		*HORN <i>one</i>	0.00	0.00	*45.00 F	✓
59	1		*STEERING AIRBAG <i>same</i>	0.00	0.00	*860.00 F	✓
60	1		*FRT PASSENGER AIRBAG <i>same</i>	0.00	0.00	*1,380.00 F	✓
61	1		*AIRBAG CONTROL UNIT <i>same</i>	0.00	0.00	*650.00 F	✓
62	1		*CLOCK SENSOR <i>same</i>	0.00	0.00	*185.00 F	✓
63	2		*FRT SAFETY BELT <i>same</i>	0.00	0.00	*990.00 F	✓
64	1		*DASHBOARD <i>To 1</i>	0.00	0.00	*720.00 F	✓
65	1		*4 LIT ATF <i>11</i>	0.00	0.00	*70.00 F	X

F=Franchise part.

Sub Total (S\$) 13,913.00
+ Margin on L,N Items 10.00% (S\$) 1,391.30
Total Parts (S\$) 15,304.30

SME Motor Pte Ltd/SKQ520X/12/02/2018 10:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2ps ftr grill bracket \$20 x 2 *one* ✓
2ps ftr lug beam \$30 x 2 *one* ✓
Starter \$780 *should / one* ✓
Battery positive positive terminal \$20 *one* ✓
Radiator sp Washer tank. \$65. *one* ✓

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Mar 2018)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SKQ520X/29/03/2018 09:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*FRT GRILLE BRACKET <i>side garage</i>	0.00	0.00	<i>Def</i> *40.00 F ✓
2	2		*FRT BUMPER BEAM	0.00	0.00	<i>Ref</i> *60.00 F ✓
3	1		*STARTER	0.00 <i>cro</i>	0.00 <i>sub</i>	*780.00 F ✓
4	1		*BATTERY POSITIVE TERMINAL	0.00	0.00	<i>Pin</i> *20.00 F ✓
5	1		*WASHER TANK	0.00	0.00	<i>ze</i> *65.00 F ✓

F=Franchise part.

Sub Total (S\$)	965.00
+ Margin on L,N Items 10.00% (S\$)	96.50
Total Parts (S\$)	1,061.50

SME Motor Pte Ltd/SKQ520X/29/03/2018 09:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS



台興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

NO: HLI9057386
PAGE 2

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
23	H38100-T7A-J01	LOW HORN RH	H1K55	1	45.00	45.00
24	H77810-T5A-N80ZA	MODULE KIT RH(N81ZA)	HDS	1	860.00	860.00
25	H77820-T7A-J80	MODULE KIT LH	HDS	1	1,380.00	1,380.00
26	H77100-T7A-000ZA	FR.DASHBOARD	HU3-TOP8	1	720.00	720.00
27	H74142-T7A-000	BONNET SIDE RUB.RH LONG	H1E1	1	25.00	25.00
28	H74192-T7A-000	BONNET SIDE RUB.LH LONG	H1G2	1	25.00	25.00
29	H74128-T7A-003	BONNET RUBBER FR.LH CTR	H1C4	1	22.00	22.00
Our D/O No: HDO9004228						
1	H17252-50T-000	INTAKE AIR DUCT	HDS	1	75.00	75.00
2	H74121-T7A-003	BONNET RUBBER FR.RH	HDS	1	22.00	22.00
3	H71129-T7M-H00	FR.GRILLE TOP COVER	HDS	1	40.00	40.00
4	H74141-T7Y-T00	BONNET INSULATOR	HDS	1	105.00	105.00
Our D/O No: HDO9004231						
1	H81450-T8C-M01ZA	FR.SEAT BELT RH	HDS	1	495.00	495.00
2	H81850-T8C-M01ZA	FR.SEAT BELT LH	HDS	1	495.00	495.00
Our D/O No: HDO9004235						
1	H17131-5R1-000	PCV TUBE	H1G2	1	20.00	20.00
2	H17100-5R1-004	INTAKE MANIFOLD	H2K28	1	350.00	350.00
3	H80341-T7A-J01	DISCHARGE HOSE	H2AA	1	130.00	130.00
4	H19502-50T-901	RAD.HOSE,LOWER	H1C4	1	25.00	25.00
5	H71151-T7J-H00	FR.GRILLE SIDE GARNISH RH	H76DL	1	20.00	20.00
6	H71152-T7A-000	FR.GRILLE GARNISH LH	H1Z3	1	20.00	20.00
7	H71140-T7A-000	FR.BPR.BEAM RH	HDS	1	30.00	30.00
8	H71190-T7A-000	FR.BPR.BEAM LH(T7J)	H76DL	1	30.00	30.00
9	H31200-5R0-J01	STARTER MOTOR ASSY(J02)	H1H1	1	780.00	780.00
Our D/O No: HDO9004237						
1	H38616-R1A-A01	A/CON FAN MOTOR	H1Z4	1	180.00	180.00
2	H38615-R1A-A02	A/CON FAN COWLING	HDS	1	85.00	85.00



台興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

1 KAKI BUKIT AVE C
#02-15/16/17/18 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
SKQ520X VEZEL
GARY

NO: HLI9057386
PAGE: 1
DATE: 24/03/2018
A/C CODE: L10SM446
TERMS: CR

Part No	Description	Location	Qty	Unit Price SIN	Amount SIN
Our D/O No: HDO9004227					
1 H60100-T8N-T00ZZ	BONNET	HU3017-3	1	430.00	430.00
2 H60120-T7A-000ZZ	BONNET HINGE RH	HDS	1	40.00	40.00
3 H60170-T7A-000ZZ	BONNET HINGE LH	HDS	1	40.00	40.00
4 H74120-T7A-003	BONNET LOCK	H1A4	1	90.00	90.00
5 H71150-T7J-H00	FR.GRILLE GARNISH.RR.CTR.	H76DL	1	20.00	20.00
6 H71121-T7A-000	FR.GRILLE	HU3-35	1	185.00	185.00
7 H71122-T7A-000	FR.GRILLE LENS	HU3-35	1	150.00	150.00
8 H71123-T7A-000	FR.GRIL LENS MLDG.RH	H1FT1	1	30.00	30.00
9 H71128-T7A-000	FR.GRIL LENS MLDG LH	H1FT1	1	30.00	30.00
10 H75700-S9A-G00	GRILLE EMBLEM(TA0)	H1M6	1	18.00	18.00
11 H71161-T7J-H00ZZ	FR.BUMPER	HU3-TOP1	1	205.00	205.00
12 H71104-T7A-000ZR	FR.TOW COVER	H1E1	1	12.00	12.00
13 H71103-T7J-H00	FR.BPR.LO.GRILLE	HU2R21	1	55.00	55.00
14 H71105-T7J-H00	FR.FOG LAMP GARNISH RH	H2K1	1	22.00	22.00
15 H33900-SLE-J51	FR.FOG LAMP RH	H2E3	1	150.00	150.00
16 H33950-SLE-J51	FR.FOG LAMP LH	H2E3	1	150.00	150.00
17 H71130-T7A-000ZZ	FR.REINFORCEMENT	HU3017-2	1	280.00	280.00
18 H60400-T7A-300ZZ	FR.BULKHEAD(310ZZ)	HU3017-4	1	385.00	385.00
19 H80110-T7A-J01 K	A/C CONDENSER	HU3-TOP6	1	350.00	350.00
20 H19010-50T-901 K	RADIATOR ASSY	HU3-TOP8	1	760.00	760.00
21 H17251-50T-000	AIR INTAKE TUBE HOSE <i>1/2"</i>	H3A8	1	40.00	40.00
22 H74107-T7M-H01	FR.W/H.ARCH PROT.RH	HU2R21S	1	45.00	45.00

Print / LSK / 24/3/2018 2:57:00 PM

Cont'd



星行汽车零部件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403
TOYOTA / LEXUS / MITSUBISHI / FORD / WINDSCREEN / CHEVROLET /
DAIHATSU / KIA / SUZUKI / HONDA
TEL: 6291 2827 FAX: 6296 4390
A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: SME MOTOR PTE LTD

NO: HLI9057386

PAGE:

3

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
3	H38611-R1A-A02	A/CON FAN BLADE	H3A6	1	55.00	55.00
4	H19015-50T-901	RAD FAN SHROUD	H3A6	1	80.00	80.00
5	H19020-R1A-A01	RAD FAN BLADE	H3A6	1	50.00	50.00
6	H19030-R1A-A02	RAD FAN MOTOR	H1C1	1	260.00	260.00
7	H32418-T5A-003	BATTERY TERMINAL COVER	H1C4	1	20.00	20.00
8	H19101-R1A-A00	RAD.SPARE TANK	H2A1	1	30.00	30.00
9	H76841-T5A-003	WASHER TANK	HDS	1	65.00	65.00
10	H71193-T7A-000	FR.BPR.SIDE RETAINER RH	HDS	1	15.00	15.00
11	H71198-T7A-000	FR.BPR.SIDE RETAINER LH	H2K6	1	15.00	15.00
Our D/O No: HDO9004242						
1	H33100-T7S-E51	HEADLAMP RH	HDS	1	850.00	850.00
2	H33150-T7A-J01	FRT.HEADLAMP LH	HU3-60	1	850.00	850.00
Our D/O No: HDO9004243						
1	H71102-T7W-A00	FR.BPR.CTR.SKIRT	HU3-57S	1	140.00	140.00
2	H91501-S1K-003	INSULATOR CLIP(STK-003)	HDS	8	2.00	16.00
3	H91505-TM8-003	CLIP GRILLE	HDS	4	2.00	8.00
4	H91505-TM8-003	CLIP BUMPER	HDS	10	2.00	20.00
5	H91505-TM8-003	CLIP TOP GARNISH	HDS	8	2.00	16.00
6	H74157-T7M-H01	FR.W/H ARCH PROT.LH	HDS	1	45.00	45.00
7	H91513-T7A-J01	FENDER CLIP	HDS	12	2.00	24.00
8	H91505-TM8-003	CLIP UNDER COVER	HDS	12	2.00	24.00
9	H77960-T7A-J42	SRS CONTROL UNIT	HDS	1	650.00	650.00
10	H77900-T4N-S21	REEL CABLE	HDS	1	185.00	185.00
TOTAL QUANTITY:			115	TOTAL	SIN 12,884.00	
				ADD GST @ 7%	901.88	
				GRAND TOTAL	SIN 13,785.88	

Print: LSK 24/3/2018 2:57:02 PM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



2018/03/24

E. & O. E.

GOODS RECEIVED BY

2018/03/24

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2018 Sendback Est	12 Feb 2018 10:33 S\$18,849.30	15 Feb 2018 09:44 Edit Adj Rpt	S\$16,802.40 Edit Estimates	S\$16,802.40 View Rpt		Pending for Survey Report Cancel Case
Supp #1	29 Mar 2018 09:55	29 Mar 2018 09:56 S\$1,061.50	29 Mar 2018 09:56			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NG CHYE CHOON, ID: S1580250B, Tel: +6585333199, Email: NOEMAIL		
Vehicle Reg. No.:	SKQ520X	Date of Loss:	09/02/2018 08:00 - :59 [39 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 549425	Policy/Cover Note No.:	A80446414QMX (Comprehensive) Coverage: 30/10/2017 - 29/10/2018
		Excess:	S\$500.00
Repairer:	SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines)		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/03/2018]		
Driver/Custodian:	NG CHYE CHOON (54 / Male), NRIC: S1580250B, Tel: +6585333199		
Adj Asg. Remarks:	URGENT. Please survey and revert.		

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

- MSIG_SG (04/04/2018): Alert - Adj Mandate Approved (S\$16802.40) - SKQ520X - Claim Handler: Joslin Lim
- MSIG_SG (26/02/2018): Alert - Adj Mandate Approved (S\$14349.40) - SKQ520X - Claim Handler: Joslin Lim

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKQ520X (549425)
OD
Feb 9 2018 8:00AM
[NG CHYE CHOON]
SME Motor Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☐	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print					
1	10/02/18 13:41	Accident Statement		Load HTM						
2	12/02/18 10:33	Repairer Estimates		Load HTM						
3	29/03/18 09:56	Repairer Estimates Suppl. #1		Load HTM						
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	20/02/18 16:29	Adjuster Immediate Advice		Load HTM						
2	03/04/18 09:00	Adjuster Immediate Advice		Load HTM						
Photos/Images							3 per page		☐	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	20/02/18 17:58	Odometer Reading		Load JPG	☒					
2	20/02/18 17:58	General View		Load JPG	☒					
3	20/02/18 17:58	Chassis Number		Load JPG	☒					
4	20/02/18 17:58	General View		Load JPG	☒					
5	20/02/18 17:58	General View		Load JPG	☒					
6	20/02/18 17:58	General View		Load JPG	☒					
7	20/02/18 17:58	General View		Load JPG	☒					
8	20/02/18 17:58	General View		Load JPG	☒					
9	20/02/18 17:58	General View		Load JPG	☒					
10	20/02/18 17:58	General View		Load JPG	☒					
11	20/02/18 17:58	General View		Load JPG	☒					
12	20/02/18 17:58	General View		Load JPG	☒					
13	20/02/18 17:58	General View		Load JPG	☒					
14	20/02/18 17:58	General View		Load JPG	☒					
15	20/02/18 17:58	General View		Load JPG	☒					
16	20/02/18 17:58	General View		Load JPG	☒					
17	20/02/18 17:58	General View		Load JPG	☒					
18	20/02/18 17:58	General View		Load JPG	☒					
19	20/02/18 17:58	General View		Load JPG	☒					
20	20/02/18 17:58	General View		Load JPG	☒					
21	20/02/18 17:58	General View		Load JPG	☒					
22	20/02/18 17:58	General View		Load JPG	☒					
23	20/02/18 17:58	General View		Load JPG	☒					
24	20/02/18 17:58	General View		Load JPG	☒					
25	20/02/18 17:58	General View		Load JPG	☒					
26	20/02/18 17:58	General View		Load JPG	☒					
27	20/02/18 17:58	General View		Load JPG	☒					
28	20/02/18 17:58	General View		Load JPG	☒					
29	20/02/18 17:58	General View		Load JPG	☒					
30	20/02/18 17:58	General View		Load JPG	☒					
31	20/02/18 17:58	General View		Load JPG	☒					

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
32	20/02/18 17:58	General View		☒
33	20/02/18 17:58	General View		☒
34	20/02/18 17:58	General View		☒
35	20/02/18 17:58	General View		☒
36	20/02/18 17:58	General View		☒
37	20/02/18 17:58	General View		☒
38	20/02/18 17:58	General View		☒
39	20/02/18 17:58	General View		☒
40	20/02/18 17:58	General View		☒
41	20/02/18 17:58	General View		☒
42	20/02/18 17:58	General View		☒
43	20/02/18 17:58	General View		☒
44	20/02/18 17:58	General View		☒
45	20/02/18 17:58	General View		☒
46	20/02/18 17:58	General View		☒
47	20/02/18 17:58	General View		☒
48	20/02/18 17:58	General View		☒
49	20/02/18 17:58	General View		☒
50	20/02/18 17:58	General View		☒
51	20/02/18 17:58	General View		☒
52	20/02/18 17:58	General View		☒
53	20/02/18 17:58	General View		☒
54	20/02/18 17:58	General View		☒
55	20/02/18 17:58	General View		☒
56	20/02/18 17:58	General View		☒
57	20/02/18 17:58	General View		☒
58	20/02/18 17:58	General View		☒
59	20/02/18 17:58	General View		☒
60	20/02/18 17:58	General View		☒
61	20/02/18 17:58	General View		☒
62	20/02/18 17:58	General View		☒
63	20/02/18 17:58	General View		☒
64	20/02/18 17:58	General View		☒
65	20/02/18 17:58	General View		☒
66	20/02/18 17:58	General View		☒
67	20/02/18 17:58	General View		☒
68	20/02/18 17:58	General View		☒
69	20/02/18 17:58	General View		☒
70	20/02/18 17:58	General View		☒
71	20/02/18 17:58	General View		☒
72	20/02/18 17:58	General View		☒
73	20/02/18 17:58	General View		☒
74	20/02/18 17:58	General View		☒
75	20/02/18 17:58	General View		☒
76	20/02/18 17:59	General View		☒
77	20/02/18 17:59	General View		☒
78	20/02/18 17:59	General View		☒
79	20/02/18 17:59	General View		☒
80	20/02/18 17:59	General View		☒
81	20/02/18 17:59	General View		☒

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
82	20/02/18 17:59	General View	 Load JPG	☒
83	20/02/18 17:59	General View	 Load JPG	☒
84	20/02/18 17:59	General View	 Load JPG	☒
85	20/02/18 17:59	General View	 Load JPG	☒
86	20/02/18 17:59	General View	 Load JPG	☒
87	20/02/18 17:59	General View	 Load JPG	☒
88	20/02/18 17:59	General View	 Load JPG	☒
89	20/02/18 17:59	General View	 Load JPG	☒
90	20/02/18 17:59	General View	 Load JPG	☒
91	20/02/18 17:59	General View	 Load JPG	☒
92	20/02/18 17:59	General View	 Load JPG	☒
93	20/02/18 17:59	General View	 Load JPG	☒
94	20/02/18 17:59	General View	 Load JPG	☒
95	20/02/18 17:59	General View	 Load JPG	☒
96	20/02/18 17:59	General View	 Load JPG	☒
97	20/02/18 17:59	General View	 Load JPG	☒
98	20/02/18 17:59	General View	 Load JPG	☒
99	20/02/18 17:59	General View	 Load JPG	☒
100	20/02/18 17:59	General View	 Load JPG	☒
101	20/02/18 17:59	General View	 Load JPG	☒
102	20/02/18 17:59	General View	 Load JPG	☒
103	20/02/18 17:59	General View	 Load JPG	☒
104	20/02/18 17:59	General View	 Load JPG	☒
105	20/02/18 17:59	General View	 Load JPG	☒
106	20/02/18 17:59	General View	 Load JPG	☒
107	20/02/18 17:59	General View	 Load JPG	☒
108	20/02/18 17:59	General View	 Load JPG	☒
109	20/02/18 17:59	General View	 Load JPG	☒
110	20/02/18 17:59	General View	 Load JPG	☒
111	20/02/18 17:59	General View	 Load JPG	☒
112	20/02/18 17:59	General View	 Load JPG	☒
113	20/02/18 17:59	General View	 Load JPG	☒
114	20/02/18 17:59	General View	 Load JPG	☒
115	20/02/18 17:59	General View	 Load JPG	☒
116	20/02/18 17:59	General View	 Load JPG	☒
117	20/02/18 17:59	General View	 Load JPG	☒
118	20/02/18 17:59	General View	 Load JPG	☒
119	20/02/18 17:59	General View	 Load JPG	☒
120	20/02/18 17:59	General View	 Load JPG	☒
121	20/02/18 17:59	General View	 Load JPG	☒
122	03/04/18 08:48	Reinspection Photo	 Load JPG	☒
123	03/04/18 08:48	Reinspection Photo	 Load JPG	☒
124	03/04/18 08:48	Reinspection Photo	 Load JPG	☒
125	03/04/18 08:48	Reinspection Photo	 Load JPG	☒
126	03/04/18 08:48	Reinspection Photo	 Load JPG	☒
127	03/04/18 08:48	Reinspection Photo	 Load JPG	☒
128	03/04/18 08:48	Reinspection Photo	Load JPG	☒
129	03/04/18 08:48	Reinspection Photo	Load JPG	☒
130	03/04/18 08:48	Reinspection Photo	Load JPG	☒
131	03/04/18 08:48	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail Print
132	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
133	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
134	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
135	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
136	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
137	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
138	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
139	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
140	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
141	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
142	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
143	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
144	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
145	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
146	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
147	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
148	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
149	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
150	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
151	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
152	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
153	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
154	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
155	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
156	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
157	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
158	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
159	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
160	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
161	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
162	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
163	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
164	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
165	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
166	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
167	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
168	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
169	03/04/18 08:48	Reinspection Photo	1 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail Print
1	12/02/18 10:33	E-filed GIA report	1 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	20/02/18 16:37	ESTIMATE	1 Load PDF	
2	03/04/18 08:47	SUPPLEMENTARY	1 Load PDF	
3	09/04/18 12:09	Parts Invoice	1 Load PDF	

Linked Accident Report Documents

View

Assessment Reports				1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	10/02/18 13:41	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	10/02/18 13:28	Driving License		Load JPG	☒
2	10/02/18 13:28	INSURANCE		Load JPG	☒
3	10/02/18 13:41	Accident Photo		Load JPG	☒
4	10/02/18 13:41	Accident Photo		Load JPG	☒
5	10/02/18 13:41	Accident Photo		Load JPG	☒
6	10/02/18 13:41	Accident Photo		Load JPG	☒
7	10/02/18 13:41	Accident Photo		Load JPG	☒
8	10/02/18 13:41	Accident Photo		Load JPG	☒
9	10/02/18 13:41	Accident Photo		Load JPG	☒
10	10/02/18 13:41	Accident Photo		Load JPG	☒
11	10/02/18 13:41	Accident Photo		Load JPG	☒
12	10/02/18 13:41	Accident Photo		Load JPG	☒
13	10/02/18 13:41	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	10/02/18 13:27	Sketch Plan		Load TIF	
2	10/02/18 13:27	Sketch Plan #2		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003123/UTD3E2

Date: 09/04/2018

REFERENCE

Insured/Claimant:	NG CHYE CHOON	Policy No:	A80446414QMX	
Date of Loss:	09/02/2018	Nature of Claim:	OD	Claim No: 549425

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ520X		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B3508792
Reg. Date:	30/10/2014 (Man. Year: 2014)	Chassis No:	RU11008777
Colour:	Blue	Odometer:	119228 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,365.80	14,172.40	2,193.40	13.40
Miscellaneous Items	65.00	60.00	5.00	7.69
Labour	3,480.00	2,570.00	910.00	26.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,910.80	16,802.40	3,108.40	15.61
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	19,410.80	16,302.40	3,108.40	16.01
+ GST 7.00/7.00% (S\$)	1,358.76	1,141.17	217.59	16.01
Nett Amount (S\$)	20,769.56	17,443.57	3,325.99	16.01

INSPECTION

Date of Assignment:	15/02/2018 Present Location:	SME Motor Pte Ltd (Kaki Bukit)
Date Inspected:	20/02/2018 Inspected At:	1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
		Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Apr 2018)
Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKQ520X)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Buckled	430.00 F	*430.00 F
2	2		*FRT BONNET HINGE (WCP)	Bent	80.00 F	*80.00 F
3	2		*FRT BONNET RUBBER (SHORT) (WCP)	Necessary	44.00 F	*44.00 F
4	2		*FRT BONNET RUBBER (LONG) (WCP)	Necessary	50.00 F	*50.00 F
5	1		*FRT BONNET INSULATOR (WCP)	Deformed	105.00 F	*105.00 F
6	8		*INSULATOR CLIP (WCP)	Necessary	16.00 F	*16.00 F
7	1		*FRT BONNET LOCK (WCP)	Twisted	90.00 F	*90.00 F
8	1		*FRT BONNET LOCK CABLE (WCP)	Not Necessary	40.00 F	*- F
9	1		*FRT BONNET LOCK COVER (WCP)	Cracked	20.00 F	*20.00 F
10	1		*FRT GRILLE (WCP)	Cracked	185.00 F	*185.00 F
11	1		*FRT GRILLE OUTER GARNISH (WCP)	Cracked	150.00 F	*150.00 F
12	2		*GRILLE CHROME (WCP)	Scratched	60.00 F	*60.00 F
13	1		*GRILLE CENTER LOGO (WCP)	Necessary	18.00 F	*18.00 F
14	4		*GRILLE CLIP (WCP)	Necessary	8.00 F	*8.00 F
15	1		*FRT BUMPER (WCP)	Distorted	205.00 F	*205.00 F
16	2		*FRT BUMPER RETAINER (WCP)	Bent	30.00 F	*30.00 F
17	10		*FRT BUMPER CLIP (WCP)	Necessary	20.00 F	*20.00 F
18	1		*FRT BUMPER TOWING COVER (WCP)	Torn	12.00 F	*12.00 F
19	1		*FRT BUMPER LOWER GRILLE (WCP)	Twisted	55.00 F	*55.00 F
20	1		*FRT BUMPER FOG LAMP GARNISH RH (WCP)	Twisted	22.00 F	*22.00 F
21	2		*FRT BUMPER FOG LAMP ASSY (WCP)	Cracked	300.00 F	*300.00 F
22	1		*FRT BUMPER LOWER SPOILER (WCP)	Cracked	140.00 F	*140.00 F
23	1		*FRT BUMPER LOWER SPOILER CHROME (WCP)		-	-
24	1			Distorted	280.00 F	*280.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRT BUMPER REINFORCEMENT (WCP)			
25	2		*HEADLAMP (WCP)	Cracked	1,700.00 F	*1,700.00 F
26	1		*HEADLAMP SUPPORT PANEL (WCP)	Bent	385.00 F	*385.00 F
27	1		*HEADLAMP SUPPORT PANEL TOP GARNISH (WCP)	Distorted	40.00 F	*40.00 F
28	8		*TOP GARNISH CLIP (WCP)	Necessary	16.00 F	*16.00 F
29	1		*AIRCON CONDENSER (WCP)	Distorted	350.00 F	*350.00 F
30	1		*RADIATOR (WCP)	Distorted	760.00 F	*760.00 F
31	1		*AIRCON MOTOR (WCP)	Dented / Jammed	180.00 F	*180.00 F
32	1		*AIRCON MOTOR COWLING (WCP)	Cracked	85.00 F	*85.00 F
33	1		*AIRCON FAN BLADE (WCP)	Cracked	55.00 F	*55.00 F
34	1		*AIRCON COOLING PIPE (WCP)	Not Necessary	110.00 F	*- F
35	1		*AIRCON DISCHARGE PIPE (WCP)	Bent	130.00 F	*130.00 F
36	1		*RADIATOR MOTOR (WCP)	Dented / Jammed	260.00 F	*260.00 F
37	1		*RADIATOR MOTOR COWLING (WCP)	Cracked	80.00 F	*80.00 F
38	1		*RADIATOR FAN BLADE (WCP)	Cracked	50.00 F	*50.00 F
39	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	28.00 F	*- F
40	1		*RADIATOR LOWER HOSE (WCP)	Torn	25.00 F	*25.00 F
41	1		*INTAKE MANIFOLD (WCP)	Cracked	350.00 F	*350.00 F
42	1		*INTAKE MANIFOLD AIR PIPE (WCP)	Torn	20.00 F	*20.00 F
43	1		*INTAKE MANIFOLD AIR PIPE CLIP (WCP)	Not Necessary	6.00 F	*- F
44	1		*AIR DUCT (WCP)	Twisted	75.00 F	*75.00 F
45	1		*AIR HOSE (WCP)	Twisted	40.00 F	*40.00 F
46	1		*ALTERNATOR (WCP)	Not Necessary	980.00 F	*- F
47	1		*WIPER CORNER GARNISH LH (WCP)	Not Necessary	25.00 F	*- F
48	1		*ENGINE MOUNTING RH (WCP)	Not Necessary	105.00 F	*- F
49	1		*ENGINE MOUNTING LH (WCP)	Not Necessary	150.00 F	*- F
50	1		*RADIATOR SPARE TANK (WCP)	Deformed	30.00 F	*30.00 F
51	1		*FRT RH FENDER (WCP)	Repair	205.00 F	*- F
52	2		*FRT RH FENDER PROTECTOR (WCP)	Torn	90.00 F	*90.00 F
53	12		*FRT RH FENDER PROTECTOR CLIP (WCP)	Necessary	24.00 F	*24.00 F
54	2		*FRT FENDER INNER COWLING (WCP)	Not Necessary	140.00 F	*- F
55	20		*INNER COWLING CLIP (WCP)	Not Necessary	40.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRT ENGINE UNDER COVER (WCP)	Not Necessary	95.00 F	*- F
57	12		*FRT ENGINE UNDER COVER CLIP (WCP)	Necessary	24.00 F	*24.00 F
58	1		*HORN (WCP)	Cracked	45.00 F	*45.00 F
59	1		*STEERING AIRBAG (WCP)	Activated	860.00 F	*860.00 F
60	1		*FRT PASSENGER AIRBAG (WCP)	Activated	1,380.00 F	*1,380.00 F
61	1		*AIRBAG CONTROL UNIT (WCP)	Activated	650.00 F	*650.00 F
62	1		*CLOCK SENSOR (WCP)	Activated	185.00 F	*185.00 F
63	2		*FRT SAFETY BELT (WCP)	Activated	990.00 F	*990.00 F
64	1		*DASHBOARD (WCP)	Torn	720.00 F	*720.00 F
65	1		*4 LIT ATF (WCP)	Not Necessary	70.00 F	*- F
Supplementary #1						
66	2		*FRT GRILLE BRACKET (WCP)	Distorted	40.00 F	*40.00 F
67	2		*FRT BUMPER BEAM (WCP)	Bent	60.00 F	*60.00 F
68	1		*STARTER (WCP)	Cracked / Shorted	780.00 F	*780.00 F
69	1		*BATTERY POSITIVE TERMINAL (WCP)	Torn	20.00 F	*20.00 F
70	1		*WASHER TANK (WCP)	Deformed	65.00 F	*65.00 F

F=Franchise part.

Sub Total (S\$)	14,878.00	12,884.00
+ Margin on L,N Items 10.00/10.00% (S\$)	1,487.80	1,288.40
Total Parts (S\$)	16,365.80	14,172.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NUMBER PLATE (MISSING)	40.00	35.00
2	1	RADIATOR COOLANT (NECESSARY)	25.00	25.00
Sub Total (S\$)			65.00	60.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	REMOVE & REFIX ENGINE	New	350.00	0.00
4	REMOVE & REFIX 2 PCS SAFETY BELT AND AIRBAG SYSTEM	New	250.00	300.00
5	REPROGRAMME AIRBAG SYSTEM	New	200.00	0.00
6	REMOVE & REFIX DASHBOARD	New	250.00	250.00
7	LABOUR CHARGE	New	1,200.00	900.00
8	SPRAY PAINTING	New	1,100.00	1,000.00
Gross Labour Cost (S\$)			3,480.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >