

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9480Y -

AAD1802-143

Not Authorised
11 Sep @ 1450

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD9480Y - JHOW
VF1ABL15AUC273328
CHEVROLET
EPICA 2.0
13.02.2018
AIG

PART		LIST	
1	1	Rear Bumper	\$ Bu 1,202.00 ✓
2	1	Rear Bumper Beam	\$ Bu 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$ Sn 260.00
4	1	Rear Bumper Side Retainer RH	\$ Sn 68.76
5	1	Rear Bumper Side Retainer LH	\$ Sn 68.76
6	1	Rear Bumper Reflectors RH	\$ Sn 119.74
7	1	Rear Bumper Reflectors LH	\$ Sn 119.74
8	1	Rear Bumper Tow Hook Cover	\$ Sn 93.00
9	1	Rear End Panel Outer	\$ R 623.76
10	1	Rear End Panel Inner Trim	\$ Sn 263.84
11	1	Bootlid	\$ R 973.00
12	1	Bootlid inner trim board	\$ Sn 400.00
13	1	Bootlid Weatherstrip	\$ Sn 344.28
14	1	Bootlid Lock - Top	\$ R 466.56
15	1	Bootlid 'CHEVROLET' Badge	\$ Sn 120.62
16	1	Bootlid Logo	\$ Sn 138.84
17	1	Bootlid 'EPICA LT' Badge	\$ Sn 119.84
18	1	Bootlid Reflector Centre	\$ Sn 217.97
19	1	Bootlid Reflector RH	\$ Sn 128.40
20	1	Bootlid Reflector LH	\$ Sn 128.40
21	1	Rear Tail Lamp RH	\$ Sn 479.30
22	1	Rear Tail Lamp Panel RH	\$ R 359.00
23	1	Rear Tail Lamp LH	\$ Sn 479.30
24	1	Rear Tail Lamp Panel LH	\$ R 359.00
25	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$ R 1,110.00
26	1	Rear Fender RH	\$ R 1,145.00
27	1	Rear Fender Inner Trim RH	\$ Sn 418.44
28	1	Rear Fender LH	\$ R 1,145.00
29	1	Rear Fender Inner Trim LH	\$ Sn 418.44

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD9480Y -

AAD1802-143

TOTAL	\$	12,010.93
10%	\$	1,201.09
	\$	10,809.84

Specical Nett

1	1Set	Licence Plate With Holder	\$	Sm	60.00	X
2	1Set	Bootlid inner trim board Clip	\$	nn	40.00	X
3	1Set	Rear Bumper Parking Sensor	\$	Sm	300.00	X
4	1Set	Rear Bumper Fastener Clip	\$	nn	44.00	
5	1Set	Rear Fender Inner Trim Clip LH	\$	nn	30.00	} X
6	1Set	Rear Fender Inner Trim Clip RH	\$	nn	30.00	
7	1Set	Rear Bumper End Dust Cover Clip	\$	nn	30.00	
8	1	Rear Boot Sticker 'Trans-cab'	\$	nn	30.00	
9	1	Rear Boot Sticker '6555-3333'	\$	Sm	10.00	
10	1	Rear Exhaust Mounting	\$	nn	80.00	
11	2	Rear Windscreen Sealant	\$	nn	100.00	
12	1	Rear Windscreen Inner Sponge Seal	\$	Sm	180.00	
13	1	Spare Tyre	\$	Sm	126.74	
14	1	Spare Wheel Rim	\$			

TOTAL	\$	1,090.74
TOTAL PARTS	\$	11,900.58

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 2,700.00 2007

To Check Electrical Lighting Concerned.

\$ 170.00 101

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

Putty And Spray Painting Of The Affected
 Portion.

\$ 2,800.00 2007

To reinstall rear bumper parking sensor.

\$ 170.00 601

To transfer of end panel fittings and conduct
 water seepage test.

\$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD
NO.2 ANG MO KIO ST63 SINGAPORE 569111
TEL NO. 6287 6666 FAX NO. 6257 1330
CO/GST REG NO. 201019626G
SHD9480Y -

AAD1802-143

To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00 X
To transfer of boot fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 X
Towing fees	\$	<i>nn</i> 120.00 X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X

	\$	7,410.00
TOTAL	\$	19,310.58

Repair Days

~~10~~ Days