

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

19-Feb-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 REGN NO: SHD 1552 B

1 pc Front o/s door
1 pc Rear o/s door
2 pcs Rear o/s door hinge @\$39.00

\$ 1,723.60 *R*
\$ 2,017.48 *bu*
\$ 78.00 *?*
\$ 3,819.08
\$ 763.82
\$ 3,055.26

Less 20%

S/NETT

1 set o/s door sticker
1 pc Rear o/s fender sticker

\$ 100.00 *ne*
\$ 60.00 *ne*

Sundry

To dismantle and refit the inner component of the front n/s door into new shell door

\$ ~~50.00~~ 20

To dismantle and refit the inner component of the front n/s door into new shell door

\$ ~~150.00~~ 80

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the o/s rocker panel, rear o/s fender

\$ ~~150.00~~ 80

To putty and spray painting on front o/s door, rear o/s door, o/s rocker panel, rear o/s fender

\$ ~~800.00~~ 500

To apply rustproofing on the repaired and replaced panels.

\$ ~~800.00~~ 700 ~~700.00~~

\$ ~~200.00~~ 100

\$ 5,365.26

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASul
Hp 90010068

6 days

4/5

20/02/18 @ 1410

Resy after repair