

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE	Document No.	: SQT18000709	Page	1
	64 CECIL STREET	Date	: 15. Feb 2018		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZ1007		
	SINGAPORE 049711	Svc Advisor	: LIEW THYE WEI		
Registration No	: SLV5434R	Engine No	: L13B11030016		
Chassis No	: JHMGK3850JX204391	Date Time	: 15. Feb 2018 11:48:58 AM		
Model	: JAZZ 1.3LXR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: OON SHUMIN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 13/2/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: OON SHUMIN						
	OWNER INSURER: TOKIO MARINE						
	ACC DATE: 13/2/18						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INS.						
	TP VEH: SH8781J						
66100-TAR-T00ZZ	PANEL COMPRR. <i>2 - buc</i>	1	314.00	25	235.50	16.49	251.99
68100-TAR-U10ZZ	TAILGATE COMP <i>- buc</i>	1	716.30	25	537.22	37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE <i>?</i>	1	92.30	25	69.22	4.85	74.07
74801-T5S-K01	LOCK ASSY, TAILGATE <i>?</i>	1	77.10	25	57.82	4.05	61.87
73127-TY0-000	RUBBER C WINDSHIELD DAMPER	1	11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBER WINDSHIELD DAMPER	2	6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPER STD 5X5	1	8.30	25	6.22	0.44	6.66
91501-T5A-J01	FASTENER C WINDSHIELD	4	0.80	25	2.40	0.17	2.57
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
84640-T5A-003ZA	LINING ASSY RR. PANEL <i>2 - cc.</i>	1	60.80	25	45.60	3.19	48.79
84651-TAR-Z03ZA	LINING ASSY L. TRUNK <i>?</i>	1	165.60	25	124.20	8.69	132.89
84601-TAR-Z03ZA	LINING ASSY R. TRUNK <i>?</i>	1	165.60	25	124.20	8.69	132.89
84521-T5A-901ZA	LID ASSY SPARE TIRE <i>?</i>	1	186.00	25	139.50	9.77	149.27
75722-T5L-T01	EMBLEM RR. <i>- cc.</i>	1	10.50	25	7.87	0.55	8.42
04715-T5A-J50ZZ	FACE, RR. BUMPER <i>- cc.</i>	1	492.70	25	369.52	25.87	395.39
71505-T5A-J60	GARNISH, RR. BUMPER <i>- cc.</i>	1	37.50	25	28.12	1.97	30.09
71502-T5A-J60	COVER, R. RR. BUMPER <i>?</i>	1	20.30	25	15.22	1.07	16.29
71507-T5A-J60	COVER, L. RR. BUMPER <i>?</i>	1	20.30	25	15.22	1.07	16.29
71503-T5A-J50	COVER, RR. EXPI FIN <i>?</i>	1	9.10	25	6.82	0.48	7.30



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLV5434R
Chassis No : JHMGK3850JX204391
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : OON SHUMIN
Ins Policy No. :
Date of Accident : 13/2/2018

Document No. : SQT18000709
Date : 15. Feb 2018
Customer No. : WZ1007
Svc Advisor : LIEW THYE WEI
Engine No : L13B11030016
Date | Time : 15. Feb 2018 11:48:58 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91505-TM8-003	CLIPBUMPER	7	2.00	25	10.50	0.74	11.24
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.60	25	12.45	0.87	13.32
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
Sum Item					2230.50	156.17	2,386.67
BOSUN	SUNDRIES	1	30.00	10	30.00	2.10	32.10
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	7.00	107.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	320.00	25	320.00	22.40	342.40
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	280.00		280.00	19.60	299.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2200.00	1680	2200.00	154.00	2354.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00	2250	2500.00	175.00	2675.00
Sum Labor					6430.00	450.10	6,880.10

Survey By

Date & Time

Excess

Status

Signature

Total Amount 8,660.50 606.27 9,266.77

Total (Inclusive of GST) 9,266.77

before paint photos.

Printed on 15/2/2018 12:15:39 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: