

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

19 FEB 2018

Estimate No. : b1 45963
Date Estimated : 19/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
Sridhar Venkateswaran
519 Bedok Reservoir Road
#03-70

Singapore 479276

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS3716T	NS38301	10/04/2015	316iA/4	0

DESCRIPTIONVALUETo remove and install right front fender, right front door,
right rear door and right rear fender and attachment include
knocking cause by the accident

4,250.00

Painting right front fender, right front door, right rear
fender

3,540.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

177.00

Sundries.

80.00

Total Labour 1: 8,047.00

Labour 1	:	8,047.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	563.29
Grand Total	:	8,610.29

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **