

## PDI TUAS

PDI TUAS

CHIAM YIK YEE, ALVIN ROY  
(ZHAN YIYI, ALVIN ROY)  
211 BUKIT BATOK STREET 21  
#08-256  
Singapore, 650211  
Singapore

*Tanjin 1749574*  
*wp,*  
*2/2/18 @ 10:5*  
*3 days*  
*\* Running before print*  
*See @ 11:45 am*

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

## Service Quote

Customer No. CV025983  
Quote No. SER/QUO/1800279  
QuoteDate 15/02/18  
Salesperson Edmund Nai  
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make               | Model Description              | Mileage              | Service Advisor |
|--------------------|--------------------------------|----------------------|-----------------|
| Volkswagen Passeng | GOLF A7 1.4 TSI (DSG)RECAT EQP | 37,905               | Kong Charmaine  |
| License No.        | VIN                            | Initial Registration | Sales Advisor   |
| SKN5444R           | WVWZZZAUZEW392758              | 25/06/14             | Edmund Nai      |
| Engine Code        | Labor Type                     | Engine No.           | Model Code      |
|                    | 1T                             | CXS 200673           | 5G13GZ          |

| No.                 | Description                                            | Qty. | UoM     | Unit Price | Amount       |
|---------------------|--------------------------------------------------------|------|---------|------------|--------------|
| P B&P ALEX LABOUR   | LABOUR                                                 | 3    | UNIT    |            | 840 2,520.00 |
| P B&P ALEX PAINT    | SPRAY PAINT                                            | 3    | UNIT    |            | 800 2,400.00 |
| P B&P DIAG          | PROGRAMMING & CALIBRATION<br>COMPULSORY TO DO AFTER AC | 1    | Time Un |            | ✓ 480.00     |
| P B&P MECH          | ELECT WIRING & MECH COMPO                              | 1    | Time Un |            | ✓ 280.00     |
|                     | Nett                                                   |      |         |            |              |
|                     | Sum Labor                                              |      |         |            | 5,680.00     |
| P 5G0807305B        | BUMPER REINFORCEMENT                                   | 1    | Pieces  |            | ? 629.03     |
|                     | Successor 5G0807305D                                   |      |         |            |              |
| P 5G0919491         | SENSOR BRACKET                                         | 1    | Pieces  |            | rec 12.74    |
| P 5G0919491         | SENSOR BRACKET                                         | 1    | Pieces  |            | rec 12.74    |
| P 5G0919491A        | SENSOR BRACKET                                         | 1    | Pieces  |            | rec 12.74    |
| P 5G0919492A        | SENSOR BRACKET                                         | 1    | Pieces  |            | rec 12.74    |
| P 5G0945106         | REFELCTOR RHS                                          | 1    | Pieces  |            | ? 67.86      |
| P 5G0998492 GRU     | SENSOR Bracket                                         | 1    | Pieces  |            | rec 27.89    |
| P 5G0998492 GRU     | SENSOR Bracket                                         | 1    | Pieces  |            | rec 27.89    |
| P 5G6807394         | BUMPER BRACKET RH                                      | 1    | Pieces  |            | ? 31.59      |
| P 5G6807394A        | BUMPER GUIDE RH                                        | 1    | Pieces  |            | ? 31.59      |
| P 5G6807417APGRU    | REAR BUMPER COVER                                      | 1    | Pieces  |            | der 996.45   |
|                     | Predecessor 5G6807417ARGRU                             |      |         |            |              |
| P 5G6807441 GRU     | TOWING COVER                                           | 1    | Pieces  |            | cut 21.86    |
| P 5G6807568D 9B9    | REAR DIFFUSER                                          | 1    | Pieces  |            | ? 279.81     |
|                     | Use Predecessor 5G6807568D                             |      |         |            |              |
| P 5G6807863A        | STRIP                                                  | 1    | Pieces  |            | rec 58.12    |
|                     | Use Predecessor 5G6807863                              |      |         |            |              |
| Sum carried forward |                                                        |      |         |            | 7,903.05     |

Payments to: - BBN: - Acc.-No.:

**PDI TUAS**

PDI TUAS

CHIAM YIK YEE, ALVIN ROY  
(ZHAN YIYI, ALVIN ROY)  
211 BUKIT BATOK STREET 21  
#08-256  
Singapore, 650211  
Singapore

Phone No.  
Fax No.  
E-Mail

VAT Registration No. M20098505-2  
Tax No. 199101494Z

**Service Quote**

Customer No. CV025983  
Quote No. SER/QUO/1800279  
QuoteDate 15/02/18  
Salesperson Edmund Nai  
Page 2

**THIS IS NOT AN OFFICIAL TAX INVOICE**

| Make               | Model Description              | Mileage              | Service Advisor |
|--------------------|--------------------------------|----------------------|-----------------|
| Volkswagen Passeng | GOLF A7 1.4 TSI (DSG)RECAT EQP | 37,905               | Kong Charmaine  |
| License No.        | VIN                            | Initial Registration | Sales Advisor   |
| SKN5444R           | VVVZZZAUZEW392758              | 25/06/14             | Edmund Nai      |
| Engine Code        | Labor Type                     | Engine No.           | Model Code      |
|                    | 1T                             | CXS 200673           | 5G13GZ          |

|              |            |           |           |
|--------------|------------|-----------|-----------|
|              |            | Continued | 7,903.05  |
| P D 180KU2A1 | 2KADHESIVE | 1 Pieces  | Acc 89.84 |
| P D 822150A1 | BONDAGENT  | 1 Pieces  | Wai 64.27 |
|              | Sum Item   |           | 2,377.16  |

|  |           |          |
|--|-----------|----------|
|  | Sum Labor | 5,680.00 |
|  | Sum Item  | 2,377.16 |

|                     |          |          |
|---------------------|----------|----------|
| Total               | SGD      | 8,057.16 |
| 7% GST              | 8,057.16 | 564.00   |
| Total SGD Incl. GST |          | 8,621.16 |

**Explanations**

P = Proportionately Charged

Payment Terms No Credit

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to: - BBN: - Acc.-No.: