



FALCON-AIR

ESSENTIAL LIVING SE ASIA PTE LTD
196 PANDAN LOOP #05-15 PANTECH BUSINESS HUB
SINGAPORE 128384

Attention : Motor Claim Department

Contact : 62761380 92386464

Estimate : ES003115

Date : 14/02/2018

Vehicle Num. : GBB4169L

Make/Model : TOYOTA HIACE-FEB 2009

Chassis/Eng# : KDH2010011814

Accident Date : 12/02/2018

Claim No. :

Reference : TP NTUC VS EQ

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE		1,969.50 <i>OK</i>
2.	1	TAILGATE GLASS		1,227.10 <i>OK</i>
3.	1	TAILGATE LOGO		75.00 <i>OK</i>
4.	1	TAILGATE STICKER HI ACE		48.00 <i>OK</i>
5.	1	TAILGATE OUTER HANDLE		155.00 <i>?</i>
6.	1	RH TAILLAMP		398.50 <i>OK</i>
7.	1	RH TAILLAMP LOWER PANEL		320.00 <i>100 320.00 OK</i>
8.	1	RH REAR FENDER AIR DUCT		55.00 <i>?</i>
9.	1	REAR BUMPER		400.20 <i>OK</i>
10.	1	REAR BUMPER SIDE RETAINER		50.00 <i>OK</i>
11.	1	REAR END PANEL		330.60 <i>?</i>
12.	1	RH TAILLAMP PANEL		545.00 <i>OK</i>
List TotalS\$:				5,583.90
25.00% Discount S\$:				1,395.98
				4,187.92
SPECIAL NETT ITEMS :				
1.	1	70 KM/HR STICKER		10.00 <i>OK</i>
Special Nett Total S\$:				10.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D

GST REG. NO.: 19-9501140-D

**FALCON-AIR**

ESSENTIAL LIVING SE ASIA PTE LTD
196 PANDAN LOOP #05-15 PANTECH BUSINESS HUB
SINGAPORE 128384

Attention : Motor Claim Department

Contact : 62761380 92386464

Estimate : ES003115

Date : 14/02/2018

Vehicle Num. : GBB4169L

Make/Model : TOYOTA HIACE-FEB 2009

Chassis/Eng# : KDH2010011814

Accident Date : 12/02/2018

Claim No. :

Reference : TP NTUC VS EQ

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO TRANSFER TAILGATE PARTS/MECHANISM
TO REMOVE/REPLACE REAR WINDSCREEN GLASS
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS
TO CUT/OUT REWELD REAR END PANEL,RH TAIL LAMP PANEL
REPAIR REAR FENDER RH INCLUDES KNOCKING &
REPLACEMENT OF PARTS

Labour Total S\$:

~~80.00~~ 40
~~120.00~~ 100
~~800.00~~ 650

~~750.00~~ 600

1,720.00

From
Hp 900 10068
6 days
1/3
10/07/18 @ 1255
Resy after repair



E. & O.E.

Total S\$:

5,917.92

for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg