

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E**19 FEB 2018**

Estimate No. : b1 45959
Date Estimated : 19/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -
Elinor Trudy Chia
4A Jalan Emas Urai

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 678730

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT169Z	L493746	30/01/2013	X5 xDRIVE35i	0

DESCRIPTIONVALUE

To replace front bumper, left front fender and attachment
include knocking cause by the accident

1700 ~~2,580.00~~

Painting front bumper, left front fender.

1996 ~~2,218.00~~

To replace left headlight including program
and conduct tests for proper function.

451 ~~531.00~~

To carry out body cavity preservation.
(Per panel).

100 ~~118.00~~

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 ~~177.00~~

Sundries.

150.00

Total Labour 1: **5,744.00**DESCRIPTIONQTY PRICVALUE

CASING LOWER PART SCHWARZ (PDC)

1 402.35

? 402.35

FRT BUMPER PRIMED

1 924.10

SCA 924.10

UNDERRIDE PROTECTION FRT (ALU MATT)

1 176.75

? 176.75

TRIM BAR LH (ALU MATT)

1 32.75

? 32.75

CLOSED GRID LH

1 67.20

? 67.20

FRT BUMPER CARRIER

1 708.15

? 708.15

SIDE PANEL PRIMED FRT LH (SRA)

1 1,397.40

BRA 1,397.40

BRACKET LEFT (SRA)

1 22.70

? 22.70

GASKET LH

1 33.15

? 33.15

LH BI XENON HEADLIGHT

1 2,825.70

CA 2,825.70

LH FOGLAMP

1 258.15

? 258.15

DECOUPLING RING PDC TORQUE CONVERTE

4 5.05

? 20.20

ULTRASONIC SENSOR (SCHWARZ)

2 236.85

? 473.70

BUMPER PDC SENSOR - ELBOW

2 236.85

? 473.70

Total Parts : **7,816.00**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45959
Date Estimated : 19/02/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJT169Z	L493746	30/01/2013	X5 xDRIVE35i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 06/03/15 @ 1100 Excess \$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date _____

RESURVEY PARTS PHOTOS Yes / No

Surveyor's E-mail _____

No. of Working Days Recommended 5 days

Resury b4 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	5,744.00
Parts	:	7,816.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	949.20
Grand Total	:	14,509.20

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **