



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Ong Yee Mei 76 Hougang Ave 7 #11-21 Singapore 538807 Contact No 98222389	Cust No/Name	KCV01262/Ms Ong Yee Mei
	Reg No/Reg Date	SJN7870S / 27/02/200
	Date In/Mileage	/ 0
	Chassis No	JMYLRHA1W9U000224
	Engine No	3B20BP8130
	Make/Model	MIT/I-CASUAL
	Colour/Trim	P03 / GY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV01262	CRDVCH	19/02/2018/ 09:24	QUA	265 / AndreChow	21422			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E	PNT98000							840 1260.00
	RESPRAY FRONT BUMPER AND BONNET							825 1100.00
E	PNT88000							60 100.00
	RENEW FRONT BUMPER, FRONT BONNET							200.00
A	54900099							
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
A	10028901							
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
	USING HI-SCAN PRO TEST							
M	SUNDRY							20 50.00
	SUNDRIES							
M	FACE KIT,FR BUMPER				1.00	803.00	00.00	803.00
M	BRACKET,FR BUMPER SIDE,RH				1.00	6.00	00.00	6.00
M	BRACKET,FR BUMPER SIDE,LH				1.00	6.00	00.00	6.00
M	5900A531 (BONNET)				1.00	385.00	00.00	385.00

SURVEYOR NAME: Rasul - Hp 9001068

SURVEYOR SIGNATURE: [Signature]

DATE: 07/03/18 @ 1610

REMARKS: 4 days

Refy by part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Confirm & accepted by

7% GST on 3910.00 273.70

Nett 3,910.00

Total Payable 4,183.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.