



W

## SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SG5064X  
 Ref. No : BUS/01/18/7051  
 Reg. Date : 18/07/2016  
 Vehicle Type : DOUBLE DECK  
 Make : VOLVO  
 Model : Volvo B9TL DD  
 Name of Driver : Han Dan  
 Type of Accident : HEAD TO SIDE  
 Date / Time of Accident : 27/01/2018 09:45:00 PM  
 Accident Reported Date / Time : 30/01/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : AIG  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle Issued? : No  
 Accident Repair Job Card No : 000024094699  
 Special Instruction to ARC, if any :  
 SG5046X - REAR LEFT SIDE SCRATCHES  
 SGP9200M (TP) INSURED WITH AIG  
 Prepared Date : 02/02/2018 06:23:16 PM



**LKX Auto Consultants hereby notify the Registrar of the following:**

- To ensure better repair quality
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey to be a 'Without Prejudice' basis
- No legal responsibility to attend
- Supplementary charges must be approved and is subject to final approval from Insurance Company

Authorised by Registrar  
 Signature:  
 Date:

Sebastian  
 22/2/18

- Part by part repair  
 - Photo Before & After Paint

Ref: 18005207/5053

Chassis No : YV3S4P92XGA176862  
Work Shop :

Mileage : 0  
Repair Completed Date / Time :

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	0.00
Total Spray Painting Charges	: 432.00	0.00
Total Material Charges	: 0.00	0.00
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 1,492.00</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sing Off Date	: 27/02/2018 09:51:10 AM	01/01/1900 12:00:00 AM

67

Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/02/2018 09:51:10 AM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :  
Quotation Date :  
Invoice Amount :

Invoice No :  
Invoice Date :  
Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,060.00	<del>0.00</del> 795
<b>Total Labour</b>	<b>1,060.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	432.00	<del>0.00</del> 300
<b>Total Spray Painting &amp; Panel Beating</b>	<b>432.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
TOTAL MATERIALS										
TOTAL MATERIALS(Discounted)								0.00	0.00	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									