

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0199/2018/CCS
Date : 14-Feb-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: SLR 829 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Audi Singapore Pte Ltd
Address : 8 Kallang Avenue
#08-01 To 09 Aperia Tower 1
Singapore 339509
Telephone : HP +65 6718 6002
Type of Claim : Third Party Claims
Policy No. : VFX/P1886473
Vehicle No : **SLV 5874 D**
Model Code : Audi RS5 2.9 TFSI QU
Model / Year : Jan-18
Engine No : DEC 003009
Chassis No : WUAZZZF53JA901804
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Feb-18
Place of Accident : Singapore Press Holdings MSCP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 5874 D.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper and transfer all trims to new bumper. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,400.00 750	
3	To respray front bumper and rhs front fender.	\$ 1,600.00 1100	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>3,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLV 5874 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	\$ 5,190.00	✓
2	FRONT BUMPER LOWER SPOILER <i>Deformed</i>	\$ 584.00	✓
3	FRONT BUMPER CLOSING ELEMENT <i>?</i>	\$ 262.00	?
4	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS		\$ 6,336.00	
TOTAL LABOUR CHARGES		\$ 3,672.00	
GRAND TOTAL		\$ 10,008.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian *ly*
Surveyed Date : 12/02/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant