

15/5/2010

INS. CASE OWNER:

Zuhadah

CC 4 / III18003224

1A2535Y

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

20/02/18

Registered in Merimen:

20/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

CHB 6271P

Claim No.:

Name of Insured:

CTPL

Policy No.:

Insured Tel No.:

HP:

Make / Model:

MERCEDES - BENZ

Excess Sec II :\$

D.O.A.:

14/02/18

Place of Accident:

RANGGON RD

Is driver the owner?

(YES ☒ NO)

Nature of Accident:

If NO. Driver Name / Age: PUNG SZM

OI GIA REPORT ☒ YES / NO ; TP GIA REPORT ☒ YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLU 5145E



INSRS:

WSP: Retable Car 2

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SLU 5145E - X

CHB 6271P - NALENC08003127/18/1 PUA: 08/03/18

STAGE

DATE / PIC

22/02/18 (Ashu)

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

26/2/18

SEEK MANDATE FOR LIABILITY.

27/2/18

MANDATE APPROVAL. LIABILITY.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 12 APR 2018

* TP DO NOT DO D/S. WILL SUBMIT W/P ONCE FINALISED.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

O/D REAR ENDED TP.

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle / WP

2) Report Format:

TP

3) Survey fee:

+ 250

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18003224/Aes3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 20-02-2018	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 6271P	Veh. Inspected	SLU 5145E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/02/2018	Inspection Date	28/02/2018
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875
Contact No.: +65 8166 9797 Fax No.: +65 6385 1751

Vehicle No.: SLU 5145E

Model: HONDA FREED

TP III Ashes

GB71040675

QTY DESCRIPTION

List Items:

- | | | |
|---|---------------------------------|--------|
| 1 | Tailgate assy | Dented |
| 2 | Tailgate hinge @ S\$64.30 | new |
| 1 | Tailgate lock | Repad |
| 1 | Tailgate emblem "FREED" | 3 |
| 1 | Tailgate emblem "HYBRID" | 1 |
| 1 | Tailgate emblem "LOGO" | 1 |
| 1 | Tailgate lamp LH | new |
| 1 | Tailgate weatherstrip | cut |
| 1 | Tailgate chrome moulding | new |
| 1 | Tailgate inner board | Repad |
| 1 | Rear bumper | Dented |
| 2 | Rear bumper retainer @ S\$46.90 | new |
| 2 | Rear bumper bracket @ S\$63.60 | new |
| 1 | Rear bumper lamp LH | cut |
| 1 | Rear end panel | Repad |
| 1 | Rear windscreen moulding top | 3 |
| 1 | Rear windscreen moulding lower | 1 |

AMOUNT (S\$)

1898.70	✓ 1750
128.60	✓
242.30	✓
88.90	✓
87.70	✓
45.60	✓
436.40	✓
193.80	✓
247.80	✓
282.70	✓
1223.20	✓
93.80	✓
127.20	✓
163.40	✓
620.60	✓
42.80	✓
48.50	✓

4262.7

3410.16

5972.00
Less 20 % (1194.40)
Subtotal 4777.60

Special Nett Items:

- | | | |
|---|------------------------------|-------|
| 1 | Rear windscreen sealant | new |
| 1 | Rear bumper clip (set) | new |
| 1 | Rear windscreen sealant foam | new |
| 1 | Reverse sensor | Repad |

310

80.00	60
50.00	30
40.00	20
250.00	200

Subtotal 420.00

Labour Charges:

- | |
|---|
| To transfer tailgate mechanism |
| To remove and refix rear windscreen glass |
| To remove and refix reverse sensor |
| To remove and refix car recorder camera (rear) |
| To apply undercoating on affected area |
| To check wiring system |
| To inspect rear lighting, mechanism, and water test for leakage |
| To jacking, replace and repair above parts |
| To respray painting on affected area |

1430

180.00	80
180.00	120
120.00	50
120.00	50
120.00	X
80.00	30
120.00	+
1200.00	500
1000.00	600

Subtotal 3120.00

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Vehicle No.: SLU 5145E

Model: HONDA FREED

ESTIMATE PARTS AND LABOUR GRAND TOTAL S\$

8317.60

h/s Adrian Lim,
28/02/18.
05 Days.

total 5150.16
h/s 4.1K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 12 April 2018 1:54 PM
To: 'Zuhaidah Samsuri'
Cc: Vic (LKKAUTO)
Subject: Your Ref: MCT18020530, Accident Involving SLU 5145E & SHB 6271P on 14/02/2018

Your Ref: MCT18020530
Our Ref: CC4/III18003224/Aea3

Hi Aida,

Accident Involving SLU 5145E & SHB 6271P on 14/02/2018

We refer to the above matter.

We were informed by TP workshop that they do not do direct settlement, case had pass to lawyer to handle the case.

In view of the above, We will proceed to close file and submit our without prejudice report to your office

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2018 Edit Reg		20 Feb 2018 00:00 Edit Adj Rpt	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	RELIABLE RIDES PTE LTD , Co. Reg. No.: 201611527N		
Vehicle Reg. No.:	SLU5145E	Date of Loss:	14/02/2018 13:00 - :59 [2 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18020530	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHB6271P	Policy No. (Claimant):	5096390005
		Excess:	
Repairer:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50, 415875 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/03/2018]		
Driver/Custodian (Insured):	PUNG SIM (), NRIC: S1495005B		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (27/02/2018): Alert - Adj Mandate Approved (S\$0.00) - SLU5145E - Claim Handler: Zuhaidah Bte S...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SLU5145E (MCT18020530)**
[SHB6271P]
TP
RELIABLE RIDES PTE LTD
Feb 14 2018 1:00PM
[COMFORT TRANSPORTATION PTE LTD]
Reliable Carz Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 16:30	General View	1 Load JPG	✓
2	29/03/18 16:30	Chassis Number	1 Load JPG	✓
3	29/03/18 16:30	General View	1 Load JPG	✓
4	29/03/18 16:30	General View	1 Load JPG	✓
5	29/03/18 16:30	General View	1 Load JPG	✓
6	29/03/18 16:30	General View	1 Load JPG	✓
7	29/03/18 16:30	General View	1 Load JPG	✓
8	29/03/18 16:30	General View	1 Load JPG	✓
9	29/03/18 16:30	General View	1 Load JPG	✓
10	29/03/18 16:30	General View	1 Load JPG	✓
11	29/03/18 16:30	General View	1 Load JPG	✓
12	29/03/18 16:30	General View	1 Load JPG	✓
13	29/03/18 16:30	General View	1 Load JPG	✓
14	29/03/18 16:30	General View	1 Load JPG	✓
15	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
16	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
17	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
18	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
19	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
20	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
21	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
22	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
23	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
24	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
25	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
26	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
27	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
28	29/03/18 16:30	Reinspection Photo	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/18 17:46	ACKNOWLEDGEMENT EMAIL TO III DD 20.02.2018	1 Load PDF	
2	20/02/18 17:46	LAWYER FORM + TP GIA REPORT	1 Load PDF	
3	12/04/18 14:24	EMAIL TO III DD 120418	1 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	21/02/18 08:58	Singapore Accident Statement	1 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18003224/AEA3S2

Date: 16/04/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLU5145E	Insured Vehicle No :	SHB6271P
Date of Loss:	14/02/2018	Nature of Claim:	TP
		Claim No:	MCT18020530

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5145E	Engine No:	LEB5569165
Make & Model:	HONDA FREED, 1.5 G (A)	Chassis No:	GB71040675
Reg. Date:	04/12/2017 (Man. Year: 2017)	Odometer:	13986 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,197.60	3,720.16	1,477.44	28.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,430.00	1,690.00	54.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,317.60	5,150.16	3,167.44	38.08
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	8,317.60	4,100.00	4,217.60	50.71

INSPECTION

Date of Assignment:	20/02/2018		
Date Inspected:	28/02/2018	Inspected At:	Reliable Carz Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #05-50 Singapore 415875
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Apr 2018)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU5145E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE ASSY	Dented	1,898.70 FL	*1,750.00 FL
2	2		*TAILGATE HINGE	Not Necessary	128.60 FL	*- FL
3	1		*TAILGATE LOCK	Damaged	242.30 FL	*242.30 FL
4	1		*TAILGATE EMBLEM FREED	Necessary	88.90 FL	*88.90 FL
5	1		*TAILGATE EMBLEM HYBRID	Necessary	87.70 FL	*87.70 FL
6	1		*TAILGATE EMBLEM LOGO	Necessary	45.60 FL	*45.60 FL
7	1		*TAILGATE LAMP LH	Not Necessary	436.40 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Cut	193.80 FL	*193.80 FL
9	1		*TAILGATE CHROME MOULDING	Not Necessary	247.80 FL	*- FL
10	1		*TAILGATE INNER BOARD	Deformed	282.70 FL	*282.70 FL
11	1		*REAR BUMPER	Deformed	1,223.20 FL	*1,223.20 FL
12	2		*REAR BUMPER RETAINER	Necessary	93.80 FL	*93.80 FL
13	2		*REAR BUMPER BRACKET	Not Necessary	127.20 FL	*- FL
14	1		*REAR BUMPER LAMP LH	Cut	163.40 FL	*163.40 FL
15	1		*REAR END PANEL	Repair	620.60 FL	*- FL
16	1		*REAR WINDSCREEN MOULDING TOP	Necessary	42.80 FL	*42.80 FL
17	1		*REAR WINDSCREEN MOULDING LOWER	Necessary	48.50 FL	*48.50 FL
18	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
19	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1		*REAR WINDSCREEN SEALANT FOAM	Necessary	40.00 FS	*20.00 FS
21	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	6,392.00	4,572.70
- List Item Discount on L Items 20.00/20.00% (S\$)	1,194.40	852.54
Total Parts (S\$)	5,197.60	3,720.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER TAILGATE MECHANISM.	New	180.00	80.00
2	TO REMOVE AND REFIX REAR WINDSCREEN GLASS.	New	180.00	120.00
3	TO REMOVE AND REFIX REVERSE SENSOR.	New	120.00	50.00
4	TO REMOVE AND REFIX CAR RECORDER CAMERA (REAR)	New	120.00	50.00
5	TO APPLY UNDERCOATING ON AFFECTED AREA.	New	120.00	0.00
6	TO CHECK WIRING SYSTEM.	New	80.00	30.00
7	TO INSPECT REAR LIGHTING, MECHANISM, AND WATER TEST FOR LEAKAGE.	New	120.00	0.00
8	TO JACKING, REPLACE AND REPAIR ABOVE PARTS.	New	1,200.00	500.00
9	TO RESPRAY PAINTING ON AFFECTED AREA.	New	1,000.00	600.00
Gross Labour Cost (\$\$)			3,120.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >