



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 20.02.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2226L TOYOTA VELLFIRE (2013)

To Supply

1)	1pc	rear end panel inner & outer		\$	840.00 x
2)	1pc	rear end panel top garnish		\$	400.00 x
3)	1pc	rear bumper		\$	1,050.00 <i>Ry</i>
4)	1pc	rear bumper right retainer		\$	130.00 x
5)	1pc	rear bumper left retainer		\$	130.00 x
6)	2pcs	rear bumper left & right tow hook cover	@ \$ 35.00	\$	70.00 <i>LH-nd V, RH</i>
7)	1set	rear bumper clip		\$	30.00 x
8)	2pcs	rear bumper parking sensor	@ \$290.00	\$	580.00 ?
9)	2pcs	rear bumper parking sensor cover	@ \$ 25.00	\$	50.00 <i>ant</i> ✓

Sub total parts	\$	3,280.00
Less: 25% discount	\$	(820.00)
	\$	2,460.00

To supply S.Nett parts

1)	1pc	rear bumper chrome step garnish (Genuine accessories from Japan)	\$	652.70 <i>dk</i>
-----	-----	--	----	------------------

L/charges

1)	To remove & replace reverse sensor, check wiring	\$	100.00 <i>30</i>
-----	--	----	------------------

- 2) To knock rear end panel, remove rear bumper, step garnish. Replace the above parts & align rear boot lid 250
\$ 500.00
- 3) To putty, respray painting rear boot lid inlet & outer, rear floor panel, end panel, rear bumper & etc 250
\$ 500.00

Sub total L/charges	\$	1,100.00
Estimated Grand total	\$	4,212.70

Taufik 97495749
- WP -

21/2/18 @ 1140

02 days

Resurvey after repair.

sure@khant.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: