

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	12	TAIL GATE COMP	Reviewing	545.28	DENTED	
	13	WEATHERSTRIPTAILGATE	Reviewing	0	NOT NECESSARY	
	14	EMBLEMRR	Reviewing	8.38	NECESSARY	
	15	EMBLEM,RR, LVTEC	Reviewing	9.16	NECESSARY	
	16	LOCK ASSYTAILGATE	Reviewing	48.79	JAMMED	
	17	LINING ASSYRR.PANEL	Reviewing	0	NOT NECESSARY	
	18	PANEL COMPR.	Reviewing	0	NOT NECESSARY	
	19	LAMP UNITR.	Reviewing	0	NOT NECESSARY	
	20	LAMP UNITL.	Reviewing	0	NOT NECESSARY	
	21	LIGHT ASSYR.LID	Reviewing	0	NOT NECESSARY	
	22	LIGHT ASSYLID	Reviewing	0	NOT NECESSARY	
	23	RUBBER CL.WINDSHIELD DAMPER	Reviewing	12.54	NECESSARY	
	24	DAMPERSTD 5X5	Reviewing	5.39	NECESSARY	
	25	RUBBER CL.WINDSHIELD DAMPER	Reviewing	12.54	NECESSARY	
	26	CAPPVOT	Reviewing	3.05	NECESSARY	
	27	FASTENER BWISHIELD	Reviewing	8.32	NECESSARY	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RSR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	11		REMOVE & INSTALL REAR COMPARTMENT LININGS.	0	0	0	Reviewing		
	12		CUT OFF & RENEW RR PANEL STRAIGHTEN.	1120	0	0	Reviewing		
	13		SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	900	0	0	Reviewing		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	496E TAMPINES AVE. 9 #08-516 S. 521496, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	S2593381H	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
VISHNU BATHAM Shekhar	2/15/18 12:31 PM	5150.65	5150.65	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice (with mandate).dd 070818.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 7, 2018
PARF_COE Rebate Enquiry.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 7, 2018
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 7, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	July 5, 2018
LKK SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	February 28, 2018
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 22, 2018
Preliminary Advice .pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	February 22, 2018
GIA SLF9211A INSD.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	February 15, 2018
ESTIMATE .pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	February 15, 2018
GIA SDP3068D TP.pdf	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	February 15, 2018
EMAIL .pdf	Letters and Correspondence	Workshop	VISHNU BATHAM Shekhar	February 15, 2018