

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

LKK

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SDP3068D

Chassis No : JHMRU1810GX200729

Model : HRV DX-SIN CVT YM 2016

Owner's Name : CHEE WAI YIP

Ins Policy No. : TP DIRECT SETTLEMENT

Date of Accident : 12/2/2018

Document No. : SQT18000705 Page 1

Date : 15. Feb 2018

Customer No. : WZA006

Svc Advisor : JASON HENG

Engine No : L15B4530731

Date | Time : 15. Feb 2018 9:03:15 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	THIRD PARTY CLAIMS (J/NO:)						
	OWNER: CHEE WAI YIP						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 12/2/18						
	SURVEYED BY:						
	DATE:						
	TP INSURER:						
	TP VEH:						
71501-T7B-000	FACE RR.BUMPER ✓ DT	1	762.60	35	✓ 495.69	34.70	530.39
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ✓ DMG	1	320.00		✓ 320.00	22.40	342.40
74940-TZ5-A01	BUZZER ASSYSMART ?	1	59.30	35	✓ 38.54	2.70	41.24
38387-TZ5-A01	ANTENNA ASSYL.F. ?	1	58.10	35	✓ 37.76	2.64	40.40
33505-T7A-J01	REFLECTOR ASSYR.RR. X	1	151.80	35	98.67	6.91	105.58
33555-T7A-J01	REFLECTOR ASSYL.RR. X	1	151.80	35	98.67	6.91	105.58
91505-TM8-003	CLIPBUMPER ✓ NEC	8	2.00	35	✓ 10.40	0.73	11.13
71593-T7A-000	SPACERR.RR.BUMPER SIDE ✓ NEC	1	11.50	35	✓ 7.47	0.52	7.99
71598-T7A-000	SPACERL.RR.BUMPER SIDE ✓ NEC	1	11.50	35	✓ 7.47	0.52	7.99
68100-T7A-J20ZZ	TAIL GATE COMP ✓ DT	1	838.90	35	✓ 545.28	38.17	583.45
74440-T7A-003	WEATHERSTRIPTAILGATE X	1	96.80	35	62.92	4.40	67.32
75722-T7W-A01	EMBLEMRR. ✓ NEC	1	12.90	35	✓ 8.38	0.59	8.97
75725-T8N-T00	EMBLEM,RR. I-VTEC ✓ NEC	1	14.10	35	✓ 9.16	0.64	9.80
74800-T7A-J02	LOCK ASSYTAILGATE ✓ Jm.	1	76.60	35	✓ 49.79	3.49	53.28
84640-T7A-J01ZA	LINING ASSYRR.PANEL ?	1	43.00	35	✓ 27.95	1.96	29.91
66100-T7A-300ZZ	PANEL COMPRR. ?	1	365.70	35	✓ 237.70	16.64	254.34
33502-T7A-J01	LAMP UNTR. X	1	428.70	35	278.65	19.51	298.16
33552-T7A-J01	LAMP UNITL. X	1	428.70	35	278.65	19.51	298.16
34150-T7A-J01	LIGHT ASSY,R.LID X	1	264.60	35	171.99	12.04	184.03
34155-T7A-J01	LIGHT ASSYL.LID X	1	264.60	35	171.99	12.04	184.03
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER ✓ NEC	1	19.30	35	✓ 12.54	0.88	13.42
73226-SZW-000	DAMPERSTD 5X5 ✓ NEC	1	8.30	35	✓ 5.39	0.38	5.77



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SDP3068D
Chassis No : JHMRU1810GX200729
Model : HRV DX-SIN CVT YM 2016
Owner's Name : CHEE WAI YIP
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 12/2/2018

Document No. : SQT18000705 Page 2
Date : 15. Feb 2018
Customer No. : WZA006
Svc Advisor : JASON HENG
Engine No : L15B4530731
Date | Time : 15. Feb 2018 9:03:15 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER ✓ NEC	1	19.30	35	12.54	0.88	13.42
76711-T6A-003	CAPPIVOT ✓ NEC	1	4.70	35	3.05	0.21	3.26
91501-S70-003	FASTENER BW/SHIELD ✓ NEC	4	3.20	35	8.32	0.58	8.90
91502-S70-003	FASTENER B ✓ NEC	2	4.90	35	6.37	0.45	6.82
91536-SS0-J01	FASTENER AW/SHIELD ✓ NEC	2	3.50	35	4.55	0.32	4.87
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ✓ NEC	2	60.00		120.00	8.40	128.40
Sum Item					3129.89	219.12	3,349.01
BOSUN	SUNDRIES	1	100.00 40		100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	300.00 280		300.00	21.00	321.00
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00 80		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00 80		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00 ?		100.00	7.00	107.00
BOMISC1	REMOVE & INSTALL TAILGATE SPOILER (N)	1	160.00 140		160.00	11.20	171.20
BOMISC1	RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	160.00 ✓		160.00	11.20	171.20
BOMISC1	RESET & CALIBRATE REAR VIEW CAMERA (N)	1	160.00 ✓		160.00	11.20	171.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00 ✓		160.00	11.20	171.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00 X		140.00	9.80	149.80
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00 566		800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00 ? 566		800.00	56.00	856.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	3500.00 1120 ← without end panel		3500.00	245.00	3745.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00 2240 ← with end panel		2500.00	175.00	2675.00
Sum Labor					9080.00	635.60	9,715.60

Survey By _____
Date & Time _____
Excess _____
Status _____

Total Amount 12,209.89 854.72 13,064.61
Total (Inclusive of GST) 13,064.61

Printed on 15/2/2018 9:23:02 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SDP3068D
Chassis No : JHMRU1810GX200729
Model : HRV DX-SIN CVT YM 2016
Owner's Name : CHEE WAI YIP
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 12/2/2018

Document No. : SQT18000705
Date : 15. Feb 2018
Customer No. : WZA006
Svc Advisor : JASON HENG
Engine No : L15B4530731
Date | Time : 15. Feb 2018 9:03:15 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Signature							

without
end panel
5 days

with
end panel
8 days.

Sebastian.
21/2/18.

- Part by part repair.
- Question Mark Item
Photo
- Photo Before Paint
90036121

sebastianyeang@lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 15/2/2018 9:23:02 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)