

KOON HENG MOTOR

(Reg. No: 24840700K)

BLK 1 KAKI BUKIT AVE 6 #02-14 (AUTO BAY @ KAKI BUKIT) SINGAPORE 417883

TEL: 67487348 FAX: 67432524

email: koonhengmotor@gmail.com

M/S **AXA Insurance Pte Ltd**
4 Shenton Way
24-01 Axa Tower
Singapore 068811
Tel : 6880 4888

Estimation No : 26022018 / 6840

Type : TP

Date : 26/2/2018

A/C No : CB684067

*Not Affected
Make
4/5 = 2700/-
2.6mph. Hk
ay -
32
28/2/18*

Re: ESTIMATION ON REPAIR COST TO VEHICLE NO: CB684067

Make/ Model : Nissan Urvan MicroBus 3.0
Chassis No : JN1TG4E25Z0791844

Accident Date : 23/02/2018

PARTS REQUIRED

Description	Qty	U/Price (\$\$)	Amount (\$\$)
1 Rear Boot <i>Bod 50</i>	1	2,101.40	2,101.40
2 Rear Boot Rubber <i>7M</i>	1	140.80	140.80
3 Rear Boot Inner Lock <i>11</i>	1	323.80	323.80
4 Rear Boot Side 3.0 DT I Sticker <i>re</i>	1	17.80	17.80
5 Rear Boot Side 3.0 Urvan Sticker <i>re</i>	1	17.80	17.80
6 Rear Bumper <i>2100</i>	1	632.70	632.70
7 Rear Bumper Side Retainer <i>11</i>	2	81.00	162.00
8 Rear Bumper Side Clips <i>re</i>	8	5.50	44.00
9 Rear Boot Side Shock Absorber <i>11</i>	1	278.50	278.50
10 Rear Boot Tail End Panel <i>re</i>	1	489.90	489.90
TOTAL			4,208.70
LESS DISCOUNT 30%			1,262.61
TOTAL SPARE PARTS			2,946.09

*2954.5
2068.15*

LABOUR CHARGES

11 TO KNOCK/REPAIR/WELDING OF DAMAGED PARTS, CHANGING OF ACCIDENT PAR	1,000.00	<i>520</i>
12 TO SPRAY PAINT FOR AFFECTED AREAS	1,000.00	<i>600</i>
13 TO WIRING	80.00	<i>30</i>
14 TO UNDERCOAT	200.00	<i>30</i>
15 TO SEAT CUSHION	17200.00	<i>2</i>
16 WINDSCREEN GLASS	150.00	<i>100</i>
17 WINDSCREEN GLASS GUM	<i>re</i> 60.00	<i>40 S.N</i>
18 WINDSCREEN GLASS SEAL	<i>re</i> 60.00	<i>30 S.N</i>
19 REAR BOOT SIDE 70KM STICKER	<i>re</i> 30.00	<i>10 S.N</i>
TOTAL	2,780.00	
GRAND TOTAL AMOUNT (PARTS & LABOUR)	5,726.09	<i>3428.15</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: