

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204

SINGAPORE 528840

TEL: 67853933 FAX: 67883933

R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : 53329821X

TERENCE SOON GRABCAR

BLK 282 TAMPINES ST 22

06-294

SINGAPORE

TEL : FAX :

PH : 98320962

ATTN :

ESTIMATE BILL

Number : EBK0000236

Date : 20/02/2018

Case No : ADK0000307

Vehicle No : SJG6641E

Chassis : MR053HY9305070988

Year of Mfr 2008

Policy No

Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	RR BUMPER ✓ DD	1.0	487.90	25	365.93
2	RR BUMPER BRACKET LH RH ✓ NEC	2.0	75.14	25	112.71
3	RR BUMPER CLIPS ✓ NEC	10.0	4.90	25	36.75
4	RR BUMPER SIDE RETAINER LH RH ✓ NEC	2.0	88.50	25	132.75
5	RR BUMPER REFLECTOR LH RH ✓ NEC	2.0	75.37	25	113.06
6	RR TAILLAMP LH RH ✓ CRA	2.0	295.90	25	443.85
7	RR BOOTLID ✓ DD	1.0	857.60	25	643.20
8	RR BOOTLID INNER RUBBER ✓ NEC	1.0	127.80	25	95.85
9	RR BOOTLID LOCK TOP ?	1.0	282.50	25	211.88
10	RR BOOTLID LOCK BTM ✓ BT	1.0	92.92	25	69.69
11	RR BOOTLID HINGE LH RH ?	2.0	75.16	25	112.74
12	RR BOOTLID EMBLEM ✓ NEC	1.0	66.37	25	49.78
13	RR BOOTLID LOGO E ✓ NEC	1.0	75.16	25	56.37
14	RR BOOTLID LOGO VIOS ✓ NEC	1.0	80.50	25	60.38
15	RR END PANEL ?	1.0	698.90	25	524.18
16	RR END PANEL TOP GARNISH ?	1.0	185.20	25	138.90
17	RR END PANEL TOP GARNISH CLIPS ?	8.0	4.90	25	29.40
18	RR SPARE TYRE PANEL TOP TRIMBOARD X SUC	1.0	157.31	25	117.98
List Price - Parts Sub Total					3,315.40
19	RR REVERSE SENSOR ?	1.0	250.00	0	250.00
20	RR NO PLATE W HOLDER X SUC	1.0	70.00	0	70.00
Special Nett Price - Parts Sub Total					320.00
Parts Total					3,635.40
21	RR SPARE TYRE PANEL REPAIR ?	1.0			
22	RR FENDER LH RH REPAIR X IN	1.0			
23	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	1,000.00	0	1,000.00
24	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	1,000.00
25	WIRING	1.0	80.00	0	80.00
Labour 1 Sub Total					2,080.00
SINGAPORE DOLLARS : SIX THOUSAND ONE HUNDRED FIFTEEN AND CENTS FORTY-EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		5,715.40
			GST 7.00%		400.08
			TOTAL		6,115.48

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : 53329821X

TERENCE SOON GRABCAR
BLK 282 TAMPINES ST 22
06-294
SINGAPORE
TEL : FAX :
PH : 98320962
ATTN :

ESTIMATE BILL

Number : EBK0000236
Date : 20/02/2018
Case No : ADK0000307
Vehicle No : SJG6641E
Chassis : MR053HY9305070988
Year of Mfr : 2008
Policy No :
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
	Without Prejudice hump Sum Repair Parts / Dismantle / Reassembly Resurvey after Paint Parts Price subject to confirmation 3-4 days Repair Wilson, LKK Tel : 67418434 wilson@lkkauto.com				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
Date of accident : 14/02/2018 09:15 AM. Place : JUNCTION MARINA BLVD AND SHEARES AVE					

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE