

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

OMAR BIN HAJI MOHAMED SAID
5 LUCKY VIEW
S 467437

TP Direct Asia
Xiao Tony

Date :13.03.2018
Vehicle no :SIN 5654 M
Make/Model :TOYOTA ALTIS
Accident date :14.02.2018

No	Description	Qty	Amount (\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>NR NR</i>	1	\$ 53.8 X
2	Rear boot lid <i>Buckled</i>	1	\$ 845.3 ✓
3	Rear boot lid hinges @ \$56.40 <i>Best</i>	2	\$ 112.8 ✓
4	Rear boot lid upper lock <i>Damaged</i>	1	\$ 81.7 ✓
5	Rear boot lid lower lock <i>NR NR</i>	1	\$ 25.8 X
6	Rear boot lid handle <i>NR NR</i>	1	\$ 176.5 X ✓
7	Rear boot lid 1.6 emblem	1	\$ 44.5 ✓
8	Rear boot lid COROLLA emblem <i>NR</i>	1	\$ 24.1 ✓
9	Rear boot lid ALTIS emblem	1	\$ 25.7 ✓
10	Rear boot lid reflector @ \$80.60 <i>NR NR</i>	2	\$ 161.2 ✓
11	Rear boot lid weather strip <i>NR</i>	1	\$ 143.1 ✓
12	Rear lamp @ \$299.60 <i>NR NR</i>	2	\$ 599.2 ✓
13	Rear lamp housing @ \$487.00 <i>Buckled</i>	2	\$ 974 761
14	Rear lamp lower panel @ \$92.30 <i>Dented</i>	2	\$ 184.6 ✓
15	Rear lamp lower panel revet @ \$8.80 <i>NR</i>	8	\$ 70.4 30
16	Rear end panel <i>Dented</i>	1	\$ 708.3 ✓
17	Rear end panel inner top garnish <i>NR NR</i>	1	\$ 26.5 ✓
18	Rear bumper <i>NR NR</i>	1	\$ 385.3 ✓
19	Rear bumper side holder @ \$17.20 <i>NR</i>	2	\$ 34.4 ✓
20	Rear bumper bracket @ \$51.10 <i>Dented</i>	2	\$ 102.2 ✓
21	Rear bumper clips (1set) <i>NR</i>	1	\$ 35 ✓
22	Rear exhaust pipe <i>Best</i>	1	\$ 337.5 ✓
23	Rear exhasut pipe mounting <i>NR NR</i>	1	\$ 55 X
24	Rear spare tyre top board <i>NR</i>	1	\$ 49.1 ✓
25	Rear spare tyre well <i>NR NR</i>	1	\$ 757 X
26	Rear spare tyre well insulation @ \$57.20 <i>NR NR</i>	3	\$ 171.6 X
27	Rear fender @ \$758.20 <i>NR NR</i>	2	\$ 1516.4 X
28	Rear fender inner shield @ \$35.10 <i>NR NR</i>	2	\$ 70.2 X
29	Rear fender inner trim @ \$161.20 <i>NR NR</i>	2	\$ 322.4 X
30	Rear LH fender lower air vent <i>NR NR</i>	1	\$ 55 X
31	Rear centre exhaust pipe <i>NR NR</i>	1	\$ 2200 X
32	Rear boot lid cable <i>NR NR</i>	1	\$ 57.6 X
33	Rear boot lid centre logo <i>NR NR</i>	1	\$ 65.7 40.50
			\$ 10471.9
Less 25% Disc			\$ 2617.98
Total			\$ 7853.92

4938.50

3703.87

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

OMAR BIN HAJI MOHAMED SAID
5 LUCKY VIEW
S 467437

Date :13.03.2018
Vehicle no :SIN 5654 M
Make/Model :TOYOTA ALTIS
Accident date :14.02.2018

No	Description	Qty	Amount (\$\$)
----	-------------	-----	---------------

Special Nett Items

1	Rear bumper reverse sensor <i>Damaged</i>	1	\$ 380 <i>200</i>
2	Rear number plate <i>2nd New</i>	1	\$ 50 <i>x</i>
3	Rear number plate holder <i>3rd New</i>	1	\$ 50 <i>x</i>
Total			\$ 480

Labour Cost

1	To supply rear windscreen sealant	\$ 50 <i>x</i>
2	To supply rear sealant	\$ 200 <i>60</i>
3	Remove & reinstall rear windscreen	\$ 150 <i>x</i>
4	Remove & reinstall exhaust pipe	\$ 150 <i>80</i>
5	Remove & reinstall reverse sensor	\$ 150 <i>50</i>
6	Remove & reinstall petrol tank	\$ 150 <i>x</i>
7	Remove & reinstall roof lining & cushion	\$ 150 <i>60</i>
8	Remove, replace & repair consistent to the accident	\$ 1800 <i>1300</i>
9	Respray painting	\$ 1600 <i>1400</i>
10	Tuff kote	\$ 150 <i>50</i>
Total		\$ 4550
Grand Total		\$ 12883.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 6903.87
4/s: 55K
08 Days

55K
08 Days