

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 8157D

DATE 19/2/2018 22:26

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ -43.60
	Boot Lid Hyundai Plate ✓			\$ -24.20
	Boot Lid 'H' Emblem ✓			\$ -26.10
	Boot Lid CRDI Plate ✓			\$ -22.70
	Boot Lid Lamp (RH) ✓			\$ -230.20
	Licence Lamp (RH) ✓			\$ -32.50
	Boot Lid Trimboard ✕			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✕			\$ 10.00
	Rear Bumper ✓			\$ -578.40
	Rear Bumper Reinforcement ✓			\$ -483.30
	Rear Bumper Clip ✓			\$ -22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ✕			\$ 185.80
	Rear Bumper Protector (LH/RH) ✕ report		\$ 38.00	\$ 76.00
	Tail Lamp (RH) ✓			\$ -344.00
	Rear Panel ✕ report			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	Rear Fender (RH) ✕ report			\$ 1,935.90
	Rear Fender Inner Lining (RH) ?			\$ 74.10
	Rear Windscreen Moulding ✕			\$ 60.00
	SUB TOTAL			\$ 6,562.00
	LESS 20%			\$ 1,312.40
	DISCOUNTED TOTAL			\$ 5,249.60
	Boot Lid Comfort Logo & Tel No. Sticker			\$ -30.00
	Rear No. Plate			\$ -25.00
	Rear Bumper Reverse Sensor ✕			\$ 135.70
	Rear Bumper Rubber Mat ✓			\$ -50.00
	Rear Windscreen Sealant ✕			\$ 46.00
	Labour Charge			\$ 286.70
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 2,220.00
	ESTIMATE TOTAL			\$ 7,756.30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a surveyor appointed by the insurance company.

LKKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *[Signature]*

Date: *20/2/18*

1210 Ls.

3 days

45

After Repair

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett

Nett